Safety Recall #2006080005

November, 2006

Dear Mercedes-Benz Owner

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. WE SENT YOU THIS NOTICE BECAUSE WE ARE CONCERNED ABOUT YOUR SAFETY.

DaimlerChrysler AG (DCAG), the manufacturer of Mercedes-Benz vehicles, has decided that a defect which relates to motor vehicle safety exists in certain Model Year 1998 - 2004 SLK-Class vehicles with regard to the tail lamp assemblies. Mercedes-Benz USA, LLC (MBUSA) therefore has initiated a recall of these vehicles. Our records indicate that your vehicle is included in the affected population of vehicles.

DCAG has determined that due to heat generated by the brake lamps, the base of the lamp sockets can be subject to thermal deformation over time. This deformation can cause movement in the socket-to-bulb connection, which may lead to a loosening of the electrical contacts in the sockets, and a failure of the bulb to illuminate. This condition can cause a failure of either side brake lamp bulbs to illuminate. The center brake lamp is not affected. A failure of the brake lamp bulbs to illuminate could lead to a rear end vehicle crash.

This is the first of <u>two letters</u> you will receive regarding this condition. This letter is being sent to let you know that if you experience a rear lamp failure your dealer will repair or provide you a replacement lamp assembly at no charge. At this time your dealer does not have the new design of lamp assembly in stock and the free initial repair will be made with the original design. Beginning in the Spring of 2007, dealers will receive replacement lamp assemblies of a new design. The redesigned tail lamp assemblies will use more heat resistant material and enhanced lamp holder mountings to better withstand the heat generated by the brake lamp. At that time, MBUSA will provide you a second notice to let you know that the new lamps are in stock, and that you should contact your authorized Mercedes-Benz dealer to make the repair. When you receive your second letter you should immediately schedule an appointment to have the replacement lamp assembly installed even if your existing tail lamps have not failed or have been replaced with the original design. Only when the new design is installed will your equipment function as originally intended.

Until the new design lamp assembly is available, your authorized Mercedes-Benz dealer will replace failed assemblies at no charge with compatible lamp assemblies that are now in dealer stock. This service will be provided free of charge. The working time required to repair this condition is approximately 1 hour. As a matter of normal service process, your authorized Mercedes-Benz dealer will also check for other repair measures which might be applicable to your vehicle and this may increase the required working time. Please contact your authorized Mercedes-Benz dealer for additional information and to schedule an appointment at this time only if you experience tail lamp failure. Please mention Recall Campaign #2006080005.

If you are no longer the vehicle owner, or have a change of address, please complete the reverse side of this letter and return the complete letter in the enclosed envelope. If this is a leased vehicle and the lessor and registered owner receive this notice, please forward this information by first class mail to the lessee. If you have paid to have this recall condition corrected prior to this notice you may be eligible to receive reimbursement. Please see the reverse side of this notice for details.

Please contact your authorized Mercedes-Benz dealer should you have any questions or encounter any difficulty regarding this recall. If your dealer is unable to remedy your situation please contact us at 1-(800) FOR-MERCedes (1-800-367-6372).

If an authorized Mercedes-Benz dealer or Mercedes-Benz USA, LLC, fails or is unable to perform this service without charge within 60 days, pursuant to law 49 U.S.C. Chapter 301, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, S.W., Washington, D.C. 20590 or call the toll-free Auto Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153); or go to http://www.safercar.gov.

We apologize for any inconvenience this situation may cause you.

Sincerely

IMPORTANT

IF FOR ANY REASON YOU DO NOT NOW OWN THIS VEHICLE OR HAVE A CHANGE OF ADDRESS, PLEASE COMPLETE THE SECTION BELOW, PLACE IN THE ENCLOSED ENVELOPE, AND DROP IN ANY MAIL BOX. IF POSSIBLE, PROVIDE THE NAME AND ADDRESS OF THE PRESENT OWNER SO THAT WE MAY CONTACT THEM.

SCRAPPED		
STOLEN		
OTHER		
SOLD	I HAVE SOLD THE VEHICLE TO:	
MY NEW ADDRESS IS:		
NAME		
STREET		APT
<u>CITY</u>	STATE	ZIP
PHONE		

THANK YOU FOR YOUR COOPERATION

**** PLEASE DO NOT DETACH. RETURN COMPLETE LETTER **** DO NOT USE THE ENCLOSED ENVELOPE FOR OTHER CORRESPONDENCE

Reimbursement to Customers for Repairs Performed Prior to Recall

If you have already <u>paid</u> to have this recall condition corrected you may be eligible to receive reimbursement.

Requests for reimbursement may include parts, labor, fees and taxes. Reimbursement may be limited to the amount the repair would have cost if completed by an authorized Mercedes-Benz dealer. The following documentation must be presented to your dealer for reimbursement.

Original or clear copy of all receipts, invoices and/or repair orders that show:

- The name and address of the person who paid for the repair.
- The Vehicle Identification Number (VIN) of the vehicle that was repaired.
- · What problem occurred, what repair was done, when it was done and who repaired it.
- · The total cost of the repair expense that is being claimed.
- Proof of payment of repair (copy of front and back of cancelled check, or copy of credit card receipt).
- Reimbursement will be made by check from your dealer. If your claim is denied you will receive a letter from MBUSA within 60 days of receipt with the reason(s) for the denial.

Please speak with your dealer concerning this matter.