



RECEIVED
NYS-215

2005 AUG 23 A 11: 58

OFFICE OF
DEFECTS INVESTIGATION

MACK TRUCKS, INC.
2100 MACK BOULEVARD
P.O. BOX M
ALLENTOWN, PA 18105-5000

August 12, 2005

TO: DISTRIBUTOR PRINCIPALS
SERVICE MANAGERS

SUBJECT: Vehicle Safety Recall - SC0296
CHN Slack Adjuster, Drag Link Interference

On Mack CHN model vehicles manufactured from July 2004 through February 2005 equipped with the FXL axle, and Meritor 16.5 x 5 brakes there exists the potential that the drag link may contact the brake slack adjuster during full wheel cut and articulation of the chassis. As a result of the interference, the slack adjuster may be damaged to a point where brake performance is compromised.

Approximately 333 vehicles are involved in this safety recall (320 US and 13 Canada).

A copy of the service bulletin covering the repair instructions and procedures is enclosed.

It is important that preparation be made immediately to assure prompt inspection and/or correction of all vehicles involved. The National Traffic and Motor Vehicle Safety Act and Canadian Motor Vehicle Safety Act requires dealers to insure that all new and used vehicles are free of safety defects and comply with all relevant safety standards at the time of delivery to the consumer. All Safety Recalls, which affect new or used inventory, must be performed before the vehicle is sold or leased. Please refer to Service Operations Service Letter #SL-004-001 dated 11/19/92 regarding the aforementioned amendment.

Please note that Dealers are responsible for performing the recall on all vehicles subject to the recall at no charge to the owner regardless of mileage, age of vehicle, or ownership from this time forward. Additionally, the National Traffic and Motor Vehicle Safety Act requires that the owner's vehicle(s) be corrected within a reasonable time after parts are available to the Dealer. The law states that failure to repair a vehicle within (60) days after tender for repair shall be a prima facie evidence of unreasonable time. However, circumstances of a particular situation may reduce the sixty (60) day period. If the vehicle is not repaired within a reasonable time, the vehicle owner may be entitled, without charge, to a reasonable equivalent vehicle or refund of the purchase price, less reasonable allowances for depreciation.

Please use the enclosed Notice of Mandatory Safety Campaign card(s) to report sold or transferred trucks. Make sure these cards are returned to us and not directly to the customer or to another dealer. A notice of the recall will be mailed to all identified registrants of affected vehicles. To avoid warranty denial of your claim for reimbursement of expenses connected with this recall, first, make sure the truck presented for the recall work is on your list. If not, check for the recall authorization on the MACKnet chassis inquiry. Also, check that another Mack dealer has not previously completed the recall.

Mack Trucks, Inc., recommends a follow-up by telephone or a personal visit, of all owners of vehicles subject to the recall who fail to bring the vehicle(s) in for repair. Your District Service Manager will be contacting you to assure that this recall attains the visibility we feel is necessary to ensure 100% completion. Please be prepared to review your progress and/or any problems associated with the recall.

If you have any questions about this recall, which may not have been covered in this letter or enclosures, please contact the Regulatory Compliance Administrator by calling (336) 393-2233.

Very truly yours,

MACK TRUCKS, INC.

Enclosures: Customer Notice
Service Bulletin
Notification Cards



VEHICLE RECALL

SC296

(Not applicable to Mack Trucks Australia)

Date: 08/08/05

To: All MACK Dealers

Subject: Interference Condition Between Slack Adjuster and Drag Link — CHN Models with FXL12 or FXL14.6 Front Steer Axles and 16.5" x 5" Brakes

Information:


It has been determined that on certain CHN model chassis equipped with either an FXL12 or FXL14.6 front axle, an interference condition exists between the slack adjuster and the drag link on the front left-hand side of the vehicle. To eliminate this condition, revised brake assemblies that reorient the brake mounting position on the steering knuckle are available. The revised brake assemblies are supplied completely assembled with brake shoes, camshaft, etc. The existing brake chambers and slack adjusters, however, must be reused.

Approximately 333 CHN model chassis manufactured between July 16, 2004 and February 14, 2005 are involved in this campaign. A list of affected chassis has been sent to all affected dealers.

Procedures:

NOTE

Before proceeding, check the campaign status in the MACKnet system to see if the campaign has already been completed. Campaign status can also be checked by looking at the Campaign Completion Label located on the lower edge of the passenger-side door. If the campaign has been completed, the campaign number (SC296) and the completion date should be written on the label.




703153a

Figure 1 — Campaign Label Location

The following procedures are used to remove and replace the front axle brake assemblies.

1. Secure the chassis for service, apply the parking brakes and place blocks at the rear wheels to prevent the vehicle from moving.
2. Remove the wheel, tire and front hub assembly as follows:
 - a. Back off the slack adjuster to provide clearance between the brake shoes and brake drum to facilitate removal of the drum. Refer to the *Air and Brake System Service Manual*, 16-104, for information on backing off the slack adjuster.
 - b. Position a wheel dolly under the front wheel.
 - c. Remove the ABS sensor from the steering knuckle assembly by first pulling the sensor wire retainer from its mounting hole in the knuckle, and then pull the sensor from the sensor mounting hole and clip. After removing the sensor, remove the sensor retaining spring clip.



403591a

Figure 2 — ABS Sensor

- d. Using hubcap removal/installation tool J 45996, remove the hubcap.
- e. Raise the vehicle so that the front wheels are off the ground, and then position heavy-duty jackstands under the front axle beam on both side of the chassis.

! DANGER

Do not work on or around a vehicle that is supported only by a hydraulic jack, as the jack can fail suddenly and unexpectedly, resulting in serious personal injury or death. Use jackstands of adequate capacity to support the weight of the vehicle.

- f. Remove the snap ring from the axle spindle using a suitable snap ring pliers.




Figure 3 — Removing Snap Ring (Shown with Wheel Removed)

- g. Remove the locking plate from the spindle.




Figure 4 — Removing Locking Plate (Shown with Wheel Removed)

- h. Using a 70 mm socket (OTC tool No. 1953M), extension and handle, remove the hub nut.
- i. Using hand pressure, remove the "D"-shaped washer.




Figure 5 — Removing "D" Washer (Shown with Wheel Removed)

- j. Using the wheel dolly, remove the wheel, tire and hub assembly from the axle spindle.
3. Remove the brake assembly as follows:

NOTE

Before removing the brake assembly, make sure that the ABS sensor has been removed from the steering knuckle.

- a. Remove and discard the air line to the front axle brake chamber.
- b. Secure the brake assembly to a hoist or other suitable lifting device.
- c. Using a 20 mm Torx® socket, remove the eight capscrews that secure the brake assembly to the steering knuckle.




Figure 6 — Removing Brake Assembly Capscrews

- d. While supporting the brake assembly with the lifting device, carefully remove the assembly complete with the spider assembly.





Figure 7 — Removing Brake Assembly

4. Remove the existing dust shield (if so equipped) from the spider.
5. Disconnect the slack adjuster from the brake chamber pushrod.
6. Remove the brake chamber from the brake spider mounting bracket.
7. Transfer the slack adjuster from the existing brake spider to the new brake assembly (part Nos. 8235-QP61655785 for the left-hand side, and 8235-QP61655786 for the right-hand side).
8. Install the brake chamber on the new brake assembly and tighten the mounting bolts to 107 lb-ft (145 N•m).
9. Reconnect the slack adjuster to the brake chamber pushrod. Use a new cotter pin (part No. 29AX5) in the clevis pin.
10. If equipped, install the dust shields to the brake spider.
11. Reinstall the brake assembly as follows:
 - a. Secure the brake assembly to a hoist or other type of suitable lifting device.




403350a

Figure 8 — Lifting Brake Assembly

- b. Position the brake assembly on the steering knuckle and align the mounting holes in the spider with the mounting holes in the knuckle.


- c. Install the eight capscrews that secure the brake assembly to the steering knuckle. Using an alternating criss-cross pattern, tighten the eight capscrews to 151–181 lb-ft (205–245 N•m).



403349a

Figure 9 — Tightening Brake Assembly Capscrews

- d. Connect a new air line (part No. 42QE2125) to the brake chamber and the fitting on the side of the frame rail.
12. Install the wheel, tire and hub assembly as follows:
- a. Apply a light coating of special spindle grease (part No. 6000-1161247) to the axle spindle.




403589a

Figure 10 — Applying Grease to Spindle

NOTE

The spindle must be lightly coated with special spindle grease (part No. 6000-1161247) prior to installation of the hub assembly. DO NOT use regular MG-C chassis grease.


- b. Install a new O-ring (part No. 530AM5) in the groove at the back of the wheel hub. Use a small amount of the special spindle grease to hold the O-ring in place if necessary.



403588a

Figure 11 — Installing O-Ring in Hub Assembly

- c. Using a wheel dolly, slide the wheel, tire and hub assembly onto the axle spindle as far as it will go (until the inner bearing of the hub contacts the knuckle flange).



403381a

Figure 12 — Wheel Hub Installation

1. Knuckle Flange

2. Inner Bearing

- d. Install the "D" washer and a new hub nut (part No. 153AM5). Hand-tighten the nut.

CAUTION

Always use a new hub nut when installing the hub assembly.




Figure 13 — Installing "D" Washer and Hub Nut

- e. Using a 70 mm socket (OTC tool No. 1953M), tighten the hub nut to 89–133 lb-ft (120–189 N•m).
- f. Rotate the wheel 20 revolutions in either direction.
- g. After rotating the wheel 20 revolutions, tighten the nut to 664–811 lb-ft (900–1100 N•m). It is important to support the torque wrench with a jackstand to stabilize the wrench while applying this relatively high torque value. If using a dial-type torque wrench, have an assistant observe the reading on the dial while torque is being applied.

NOTE

With unitized hub assemblies, bearing end play adjustment is not necessary. Tightening the hub nut to the proper torque value ensures proper end play.





Figure 14 — Final Nut Tightening (Shown with Wheel Removed)

- h. Install the lock plate by indexing the plate around the hub until the plate aligns with the flats of the nut. The lock plate must not be forced over the nut. Install the snap ring. The lock plate and snap ring are properly installed when the snap ring rotates freely in the snap ring groove.

⚠ CAUTION


Do not hammer on the lock plate. Rotate the snap ring to ensure engagement.



403344a

Figure 15 — Installing Snap Ring (Shown with Wheel Removed)


- i. Install a new O-ring (part No. 6000-3197784) in the hubcap and coat with MG-C grease.



403383a

Figure 16 — Applying MG-C Grease to Hubcap O-Ring


- j. Install the hubcap and hand-tighten.
- k. Apply Never-Seize® or equivalent, to a new ABS sensor retaining spring clip (part No. 745-801534), and then install the retaining spring clip into the ABS sensor hole located on the forward edge of the steering knuckle.



403586a

Figure 17 — Installing ABS Sensor Retaining Clip


- l. Install the ABS sensor until it engages the spring clip.



403585a

Figure 18 — Installing ABS Sensor

- m. Insert the ABS sensor wire retainer into the hole located above and forward of the ABS sensor hole.




403591a

Figure 19 — ABS Sensor Wire Retainer

- n. Use a tie wrap (part No. 48RU2313) to secure the ABS sensor harness to the cam tube, and use the existing clamp to secure the harness to the brake chamber mounting bracket.
 - o. Route the sensor harness along the brake chamber air line. Beginning approximately 2" (50.8 mm) from the swaged metal hose end connected to the brake chamber, secure the harness to the air line every 4"-6" with a tie wrap (part No. 48RU2313). Excess sensor harness wire should be looped and secured to the air line with a tie wrap.
- 13. Repeat the above procedures for the opposite side of the vehicle.
 - 14. Lubricate the brake cam tubes and slack adjusters on both sides of the chassis with MG-C grease.
 - 15. Adjust the front axle brakes. For complete brake adjustment procedures, refer to the *Air and Brake System Service Manual*, 16-104.
 - 16. Remove the jackstands and lower the vehicle to the ground.
 - 17. Using the hubcap removal/installation tool, tighten the hubcaps to 159-210 lb-ft (215-285 N•m) on both sides of the chassis.

NOTE

To signify that the campaign has been completed, use a permanent-type marker (such as a Sharpie®) to write the campaign number (SC296) and completion date in the spaces provided on the Campaign Completion label located on the lower edge (below the door latch) of the passenger-side door. If a label is not already affixed to the door, apply a label (part No. TS897) and supply the information as required. Campaign Completion labels are available in packs of 50 and can be ordered by faxing a completed BR313 to Pacesetters Business Services at 610-264-9465.



703153a

Figure 20 — Campaign Label Location

Required Parts:

Order vehicle recall parts on a separate stock order and process through the parts distribution center normally serving your area. Order the brake assemblies using the normal ship direct process. Do not order the brake assemblies "VOR," and do not include parts on this requisition that are not required for this recall campaign.

International orders are to be prefixed — V.O.R.

Qty	Part No.	Description
1	8235-QP61655785	Front brake assembly, left-hand side
1	8235-QP61655786	Front brake assembly, right-hand side
2	42QE2125	Front brake hose assembly
*	6000-1161247	Special spindle grease
2	530AM5	O-ring, front hub
2	6000-3197784	O-ring, hubcap
2	153AM5	Hub nut
2	745-801534	Retainer spring clip, ABS sensor
2	29AX5	Cotter pin, 1/8" x 1-1/2"
**	48RU2313	Tie-wraps

* Supplied in 1.1 lb. (500 g) containers

** Quantity as required

Removed Parts:

The removed brake assemblies and brake hoses can be scrapped locally.

Reimbursement:

Campaign expenses are to be recovered through normal warranty claim procedures. Enter the following information on the warranty claim:

UNDER**ENTER**

Failed Part No..... SC296

Labor Code/Allowance 512 1B FX 95 — 0.2 hr.

Time allowed to take charge of vehicle and determine campaign status.

512 1C FX 95 — 3.6 hrs.

Time allowed to remove and replace front axle brake assemblies on both the left- and right-hand sides of chassis. Does not include "take-charge" time.

NOTE

As required by Federal Motor Vehicle Safety Standards 49 CFR 573.11, no vehicle subject to an open safety campaign shall be delivered to the customer until such time as the defect or noncompliance is remedied.