



U.S. Department
of Transportation

**National Highway
Traffic Safety
Administration**

400 Seventh Street, SW
Washington, DC 20590

September 13, 2006

DAVID M. MIHALICK
FOUR WINDS
419 WEST PIKE STREET, P.O. BOX 629
JACKSON CENTER, OH 45334-0629

NVS-215
06V-351

Subject: ENGINE FUEL RAIL CLIP FRACTURE/CHEVROLET/WORKHORSE

Dear MR. MIHALICK:

This letter is to acknowledge your recent defect information report. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

FOUR WINDS/CHATEAU/2004-2006
FOUR WINDS/DUTCHMEN/2004-2006
FOUR WINDS/FOUR WINDS/2004-2006
FOUR WINDS/FUN MOVER/2004-2006
FOUR WINDS/HURRICANE/2004-2006
FOUR WINDS/INFINITY/2004-2006
FOUR WINDS/MAGELLAN/2004-2006
FOUR WINDS/WINDSPORT/2004-2006

NHTSA Campaign Number: 06V-351

Mfg's Report Date: September 8, 2006

Components: ENGINE AND ENGINE COOLING

Potential Number of Units Affected: 692

Summary:

ON CERTAIN MOTOR HOMES BUILT ON WORKHORSE AND EQUIPPED WITH GM 8.1L V8 ENGINES, IMPROPER HARDENING DURING THE HEAT TREATMENT PROCESS CAN CAUSE THE FUEL RAIL PULSE DAMPER RETAINER CLIP TO FRACTURE, RESULTING IN INADEQUATE RETENTION OF THE DAMPER. IF THE DAMPER BECOMES LOOSE, FUEL COULD BE PUMPED BY THE FUEL PUMP INTO THE UNDER HOOD AREA.

Consequence:

IN THE PRESENCE OF AN IGNITION SOURCE, A FIRE COULD RESULT.

Remedy:

CHEVROLET AND WORKHORSE ARE HANDLING THE OWNER NOTIFICATION AND REMEDY FOR THIS CAMPAIGN (PLEASE SEE 06V225 AND 06V289). DEALERS WILL REPLACE THE FUEL RAIL PULSE DAMPER RETAINER CLIPS ON THESE ENGINES FREE OF CHARGE. OWNERS MAY CONTACT CHEVROLET AT 1-800-630-2438, WORKHORSE AT 877-294-6773 OR THOR INDUSTRIES AT 937-596-6849.

Notes:

CUSTOMERS CAN ALSO CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY 1-800-424-9153), OR GO TO [HTTP://WWW.SAFERCAR.GOV](http://www.safercar.gov).


Please provide the following additional information and be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in your report, Chevrolet/Workhorse will be handling the owner notification, remedy, and quarterly reporting for this campaign. However, please be advised that 49 CFR 573.5 provides that the vehicle manufacturer is responsible for any safety related defect or any noncompliance in the vehicle or any item of original equipment. If Chevrolet/Workhorse's campaign is not satisfactory, you may be required to conduct a follow-up notification.

Your contacts for this recall will be Pat Wallace or Delia Lopez, who may be reached by phone at 202-366-5232 or 202-366-9525 or by email at patricia.wallace@dot.gov or delia.lopez@dot.gov. We look forward to working with you for successful completion of this recall campaign.

Sincerely,



George H. Person
Chief, Recall Management Division
Office of Defects Investigation
Enforcement