



June 2006

Recall Campaign No. 06V-134, R1200 GS, R1200 RT, R1200 ST – Front ABS Sensor Cable Routing

Dear BMW Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

BMW AG has decided that a defect which relates to motor vehicle safety exists in certain 2005-06 BMW R1200 GS, 2006 BMW R1200 RT, and 2005 BMW R1200 ST motorcycles. Our records indicate that you are the owner of a potentially affected motorcycle.

We sincerely apologize for any inconvenience this may cause you.

DESCRIPTION OF DEFECT

The defect involves the routing of the front Anti-Lock Brake System (ABS) sensor cable. If certain service procedures are performed, for example, a front tire change which involves removal of the front left brake caliper, it is possible for the ABS sensor cable to be routed incorrectly when the caliper is reinstalled. If this happens, the sensor cable can come into contact with, and rub/chafe against, the front brake disk. Over time, if the chafing becomes severe, it is possible to lose the ABS function.

However, loss of ABS function will be displayed to the rider by the warning lamp in the instrument cluster. Normal braking is not affected and remains fully functional. The capability to bring the motorcycle to a stop would still exist.

You may continue to ride your motorcycle; however, you must have the problem corrected promptly. Failure to observe the following precautions, in conjunction with traffic and road conditions, and the rider's reactions, could increase the risk of a crash.

PRECAUTIONS

- 1. CONTACT YOUR AUTHORIZED BMW RETAILER IMMEDIATELY TO HAVE THE NECESSARY REPAIR PERFORMED AS SOON AS POSSIBLE.**
- 2. If you observe the ABS brake warning lamp in the instrument cluster while riding, your motorcycle may be experiencing this problem. Ride cautiously as your motorcycle no longer has ABS functionality. Contact your Authorized BMW retailer immediately to have the necessary repair performed as soon as possible. Should you need BMW Roadside Assistance, they can be reached at 1-877-680-2176.**
- 3. If you are not the only rider of this motorcycle, please advise all other riders of this important information.**

Company
BMW of North America, LLC

BMW Group Company

Mailing address
PO Box 1227
Westwood, NJ
07675-1227

Office address
300 Chestnut Ridge Road
Woodcliff Lake, NJ
07677-7731

Telephone
(201) 307-4066

DESCRIPTION OF REPAIR

The repair will consist of attaching additional retaining clips to the ABS sensor cable, which will provide a more secure connection to the wheel carrier on all affected motorcycles. If any ABS sensor cable shows evidence of chafing, it will be replaced.

The actual repair may take up to one hour; however, additional time may be required depending upon the BMW retailer's scheduling and processing. This work will be performed *free of charge* by your Authorized BMW retailer.

OTHER INFORMATION

If you are no longer the owner of this motorcycle, we would appreciate you furnishing us with the name and address of the new owner using the enclosed postage-paid card.

If you are a lessor of this motorcycle, Federal Regulations require you to forward this notice to your lessee.

If you have already had this repair performed at your own expense, please see the attachment regarding possible eligibility for reimbursement.

Again, we sincerely apologize for any inconvenience this may cause you.

Should you have any questions about this campaign, please contact your Authorized BMW retailer.

We appreciate your confidence in our product, and we wish to do everything we can to retain your confidence. Should you need additional assistance, you may contact BMW Customer Relations and Services at 1-800-831-1117, or via CustomerService@bmwmotorcycles.com.

If the BMW retailer is unable to remedy the defect without charge or within a reasonable period of time, you may notify the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street S.W., Washington, DC 20590, call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153), or go to <http://www.safercar.gov>.

BMW OF NORTH AMERICA, LLC

TREAD ACT CUSTOMER REIMBURSEMENT PLAN
(BMW of North America, LLC)

If you have paid for the repair described in the attached letter, and you would like to be considered for reimbursement, please contact your authorized BMW motorcycle retailer. Expenses from repair facilities outside of the BMW motorcycle retailer network will be considered; however, the procedure must meet BMW standards and use BMW Genuine Parts.

Your authorized BMW motorcycle retailer will request a copy of your owner notification letter, as well as, a copy of your previously paid invoice, and then inspect the vehicle (if it is still in your possession) prior to submitting a claim on your behalf to BMW of North America, LLC for reimbursement.

Please note the following:

- Only a repair that is the subject of this safety recall is reimbursable. Consequential expenses such as towing, rental, accommodations, damage repairs, etc will not be reimbursed.
- When BMW Genuine Parts are used, the Manufacturers Suggested Retail Price (MSRP) will be considered as the guideline for reasonable charges.
- Expenses for repairs performed more than 10 days after the date of the last owner notification letter sent by BMW are not eligible for reimbursement.
- Taxes and hazardous waste disposal, where previously paid, are eligible for reimbursement.
- BMW will not reimburse for prior repairs that did not utilize BMW Genuine Parts.

We anticipate that your authorized BMW motorcycle retailer will be able to answer any questions that you may have regarding your qualifications for reimbursement of a previous repair. If you qualify for such a reimbursement, they will also be able to advise you of the manner in which you could receive reimbursement.

We recommend that your authorized BMW motorcycle retailer be your primary contact on this issue; however, our Customer Relations and Services Department may be contacted at 1-800-831-1117 for any special assistance that you may require.

Alternatively, you may submit your request for reimbursement to the following address:

Customer Relations and Services Department
BMW of North America, LLC
P.O. Box 1227
Westwood, NJ 07675-1227