



AFFECTED VEHICLES
MODELS: 2007 Eclipse/Eclipse Spyder

Date: September, 2006

RE: IMPORTANT SAFETY RECALL NOTIFICATION: SR-06-004

Dear Mitsubishi Owner,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Reason For Notice: Mitsubishi Motors North America, Inc. has detected that a defect that relates to vehicle safety exists in certain 2007 Eclipse and Eclipse Spyder vehicles. The metal forming part of the front crossmember may have been improperly stamped resulting in the metal becoming thinner in cross-section than specified. This could over time result in breakage of the crossmember. Breakage of the crossmember may cause separation of the passenger side lower control arm which may result in a loss of steering control.

What you should do: Please contact your Authorized Mitsubishi Dealer to schedule an appointment to have the crossmember inspected. When you bring your vehicle in, show this letter. (If you misplace this letter, they will arrange the repair, free of charge.)

What your dealer will do: The dealership will schedule an appointment to have the crossmember inspected by authorized personnel. If the crossmember requires replacement, the dealer will replace it.

How long will it take? The time needed for the inspection is approximately 10 minutes. If the crossmember requires replacement, actual repair time is approximately 3 hours. The dealer may need to keep your vehicle for a longer period of time due to service scheduling issues, but every effort will be made to minimize your inconvenience.

If you have any trouble having your vehicle repaired promptly and at no charge, please inform us by calling the Mitsubishi Customer Relations Department at **888-MITSU-2006 (888-648-7820)**.

Hours: Monday – Friday 6 a.m. to 5 p.m. (Pacific Time).

If after contacting Mitsubishi Customer Relations, you still have a problem having this repair made promptly and without charge, write to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street SW, Washington, D.C. 20590, or call the Auto Safety Hotline toll-free (888) 327-4236 (TTY 800-424-1953), or go to <http://www.safercar.gov>.

If you have already encountered a problem regarding the above and have paid for the repair, you may send your original receipts and/or other adequate proof of payment to the following address for reimbursement:
 Mitsubishi Customer Relations Department, P.O. Box 6400, Cypress, CA 90630-0064

Notice to Lessors: If you are a lessor of five or more leased vehicles as of the date of this letter, you have an obligation under federal law, (49 CFR Part 577), to provide the lessee of the above referenced vehicle with a copy of this letter by first class mail within ten days of receipt. Further, you must maintain a record, which identifies the lessee to whom you sent a copy of this letter, the date you sent it, and the vehicle identification number (VIN) of the subject vehicle.

We appreciate your prompt attention to this matter. If you have any questions, please contact your Mitsubishi Dealer.

C0605KXX