

RECEIVED

SEP 29 2006

076



HYUNDAI · KIA MOTORS

September 29, 2006

Mr. Daniel Smith
Associate Administrator for Enforcement
National Highway Traffic Safety Administration
400 Seventh Street, S.W.
Washington, D.C. 20590

RE: Recall Number 06V-234 Defect Information Report (additional information)
(Hyundai Campaign 076)

Dear Mr. Smith

Hyundai Motor Company previously submitted a Defect Information Report to NHTSA regarding a recall campaign of approximately 43,301 model year 2006 Hyundai Sonata vehicles produced beginning on April 14, 2005 through August 31, 2005 (NHTSA Recall Number 06V-234) pursuant to Part 573 of Title 49 of the Code of Federal Regulations. Dealers have been notified of the recall on September 27, 2006 and owner notification will be conducted in two mailings, beginning on October 2, 2006 and will be completed on October 9, 2006.

Enclosed for NHTSA's files are final copies of the Technical Service Bulletin, owner notification letter and dealer notification letters.

Sincerely,

A handwritten signature in black ink that reads "Robert Babcock".

Robert Babcock
Manager, Certification and Compliance Issues

Attachments: 5

HYUNDAI · KIA MOTORS
Hyundai-Kia America Technical Center Inc.
6800 Geddes Road, Superior Township, MI 48198
TEL : 734-337-9499 FAX : 734-337-3168
www.hatci.com



HYUNDAI Technical Service Bulletin

Group	BODY
Number	06-01-007
Date	SEPTEMBER, 2006
Model	2006 SONATA

Subject
SUN VISOR LABEL REPLACEMENT (CAMPAIGN 076)

CIRCULATE TO:	<input type="checkbox"/> GENERAL MANAGER	<input checked="" type="checkbox"/> PARTS MANAGER	<input checked="" type="checkbox"/> TECHNICIAN
<input checked="" type="checkbox"/> SERVICE ADVISOR	<input checked="" type="checkbox"/> SERVICE MANAGER	<input checked="" type="checkbox"/> WARRANTY MGR	<input type="checkbox"/> SALES MANAGER

IMPORTANT: DEALERS MUST PERFORM THIS CAMPAIGN ON ALL AFFECTED VEHICLES PRIOR TO CUSTOMER RETAIL DELIVERY AND WHENEVER AN AFFECTED VEHICLE IS IN THE SHOP FOR ANY MAINTENANCE OR REPAIR.

IMPORTANT: WHEN A VEHICLE ARRIVES AT THE SERVICE DEPARTMENT, ACCESS HYUNDAI MOTOR AMERICA'S "WARRANTY VEHICLE INFORMATION" SCREEN VIA DCS INTERACTIVE OR DCS ON-LINE TO IDENTIFY OPEN CAMPAIGNS.

DESCRIPTION:

Some vehicles affected by this TSB may have sun visor labels that have become distorted or separated. This TSB provides the procedure for sun visor label inspection and replacement.

NOTE: If the warning label is attached securely, do not replace it.

VEHICLES AFFECTED:


Assembly Plant (First 3 places of VIN #)	Affected Vehicle Production Date Range
Asan (KMH)	APR. 14, 2005 to AUG. 10, 2005
HMMA (5NP)	MAY 20, 2005 to AUG. 31, 2005

PART INFORMATION:

Part Name	Figure	Notes
Advanced Air Bag Label		2 each (RH and LH)
Flip Visor Over Label		2 each (RH and LH)

Sun visor label kit P/N: 00305-85201

(Kit contains 2 each of “Advanced Air Bag” label and 2 each of “Flip Visor Over Label”).
Additional kits can be ordered from your facing PDC.





HYUNDAI Technical Service Bulletin

Group	BODY
Number	06-01-007



EXAMPLES OF DISTORTED LABELS:

SERVICE PROCEDURE:


1. Slowly peel the distorted label from the sun visor by steadily pulling a loose edge.

NOTE: Do not use a knife to remove the label

2. Clean the label attachment area with a clean cloth.
3. Peel the backing paper off the new label and attach the new label in the position where the original label was located, as shown in the photos.



4. Rub across the new label to attach it securely to the sun visor.



CAUSAL PART TABLE:

HMC (KMH)*			
SUN VISOR LH		SUN VISOR RH	
85201 3K250QD	Beige - No Sunroof	85202 3K250QD	Beige - No Sunroof
852013K250QS	Gray - No Sunroof	85202 3K250QS	Gray - No Sunroof
85201 3K750QD	Beige - Sunroof	85202 3K750QD	Beige - Sunroof
85201 3K750QS	Gray - Sunroof	85202 3K750QS	Gray - Sunroof

HMMA (5NP)*			
SUN VISOR LH		SUN VISOR RH	
85201 0A250QD	Beige - No Sunroof	85202 0A250QD	Beige - No Sunroof
85201 0A250QS	Gray - No Sunroof	85202 0A250QS	Gray - No Sunroof
85201 0A750QD	Beige - Sunroof	85202 0A750QD	Beige - Sunroof
85201 0A750QS	Gray - Sunroof	85202 0A750QS	Gray - Sunroof

* Assembly Plant (First 3 places of VIN #)

WARRANTY CLAIM INFORMATION:

Op Code	Operation	Causal Part #	Op Time	Nature	Cause
85261F00	Sun visor label replacement	See Causal Part Table	0.2 M/H	N86	C63

NOTE: Submit claim using Warranty Claim Entry Screen.

NOTE: If the sunvisor is damaged during the removal of the label, replace the sun visor under normal warranty procedure.

*N86 Falling off, sagged

**C63 Flaw in material

September 27, 2006

**TO: ALL HYUNDAI DEALER PRINCIPALS/GENERAL MANAGERS:
ALL HYUNDAI DEALERSHIP SERVICE MANAGERS:
ALL HYUNDAI DEALERSHIP PARTS MANAGERS:
ALL HYUNDAI DEALERSHIP SALES MANAGERS:**

Subject: Campaign 076 - 2006 Sonata - Sun Visor Label Inspection and/or Replacement

Hyundai Motor America is conducting a Customer Notification Sun Visor Label Inspection and/or Replacement Campaign on certain 2006 MY Sonata vehicles produced beginning April 14, 2005 through August 10, 2005 for vehicles produced in Korea and March 1, 2005 through August 31, 2005 for vehicles produced in Alabama.

Affected vehicles may have Sun Visor labels that have become distorted or separated. This campaign provides the procedure for replacement of those Sun Visors labels that have become distorted or separated. Warning labels that are attached securely **DO NOT** need to be replaced.

Affected vehicles **WILL NOT BE IDENTIFIED** as having an open Campaign 076. All in-stock vehicles, if any, must have Campaign 076 completed prior to retailing if the Sun Visor label has become distorted or separated. Warranty claims are to be submitted for those vehicles that require replacement of the Warning Label.

Enclosed with the Service Manager's letter are materials, which were developed for your use: Dealer Letter, Customer Letter, five (5) copies of the Technical Service Bulletin (TSB# 06-01-007) containing instructions on performing the service, as well as a supply of Sun Visor Labels for your in-stock vehicles, as well as additional Sun Visor Labels for customer's vehicles should they ask you to replace their labels. Additional Sun Visor labels may be ordered from your facing PDC. TSB #06-01-007 will be available on Hyundai's Website on September 27, 2006.

Customer notification letters, along with replacement labels, will be mailed to all affected customers in two weekly mailings, October 2, 2006 and October 9, 2006. A customer may request that your dealership inspect or replace the labels for him/her, please perform the service and submit a Warranty Claim. TSB # 06-01-007 provides instructions on how to submit a Warranty Claim.

It is IMPORTANT TO SUBMIT A CAMPAIGN CLAIM FOR EACH VEHICLE SERVICED so your dealership can be compensated for your work and Hyundai can maintain accurate records of campaign completions.

LEGAL LIABILITY NOTICE: You are required to keep confidential any and all information and documents provided to you by Hyundai Motor America in the conduct of carrying out work for this service campaign. Hyundai Motor America dealers may use owner information provided for the campaign only for the purpose of conducting and performing this service campaign, and for no other purpose.

Hyundai appreciates your cooperation and support. Questions may be directed to your District Parts and Service Manager or Warranty HELPREP line at 1-877-446-2922.

HYUNDAI MOTOR AMERICA

//ALL HMABSTXX 9/27/06 9/28/06 9/28/06
TO: All Hyundai Dealership General Managers, Sales Managers,
 Service Managers, Parts Managers, and Warranty Administrators
FROM: Hyundai Motor America

Subject: Campaign 076 - 2006 Sonata - Sun Visor Label Inspection and/or Replacement

Hyundai Motor America is conducting a Customer Notification Sun Visor Label Inspection and/or Replacement Campaign on certain 2006 MY Sonata vehicles produced beginning April 14, 2005 through August 10, 2005 for vehicles produced in Korea and March 1, 2005 through August 31, 2005 for vehicles produced in Alabama.

Affected vehicles may have Sun Visor labels that have become distorted or separated. This campaign provides the procedure for replacement of those Sun Visors labels that have become distorted or separated. Warning labels that are attached securely **DO NOT** need to be replaced.

Affected vehicles **WILL NOT BE IDENTIFIED** as having an open Campaign 076. All in-stock vehicles, if any, must have Campaign 076 completed prior to retailing if the Sun Visor label has become distorted or separated. Warranty claims are to be submitted for those vehicles that require replacement of the Warning Label.

Enclosed with the Service Manager's letter are materials, which were developed for your use: Dealer Letter, Customer Letter, five (5) copies of the Technical Service Bulletin (TSB# 06-01-007) containing instructions on performing the service, as well as a supply of Sun Visor Labels for your in-stock vehicles, as well as additional Sun Visor Labels for customer's vehicles should they ask you to replace their labels. Additional Sun Visor labels may be ordered from your facing PDC. TSB #06-01-007 will be available on Hyundai's Website on September 27, 2006.

Customer notification letters, along with replacement labels, will be mailed to all affected customers in two weekly mailings, October 2, 2006 and October 9, 2006. A customer may request that your dealership inspect or replace the labels for him/her, please perform the service and submit a Warranty Claim. TSB # 06-01-007 provides instructions on how to submit a Warranty Claim.

It is IMPORTANT TO SUBMIT A CAMPAIGN CLAIM FOR EACH VEHICLE SERVICED so your dealership can be compensated for your work and Hyundai can maintain accurate records of campaign completions.

LEGAL LIABILITY NOTICE: You are required to keep confidential any and all information and documents provided to you by Hyundai Motor America in the conduct of carrying out work for this service campaign. Hyundai Motor America dealers may use owner information provided for the campaign only for the purpose of conducting and performing this service campaign, and for no other purpose.

Hyundai appreciates your cooperation and support. Questions may be directed to your District Parts and Service Manager or Warranty HELPREP line at 1-877-446-2922.

HYUNDAI MOTOR AMERICA

Sun Visor Label Inspection and Replacement Instructions

First:


Verify that the two sun visor warning labels are attached to each sun visor and that their edges are secure.

Replace any sun visor warning label that is missing or whose edges are not secure.

Do NOT replace warning labels that are attached securely.

Examples of Distorted Labels:

"Advanced Air Bags" Label
Top Surface of Sun Visors





"Flip Visor Over" Label
Bottom Surface of Sun Visors




Replacement Procedure:

1. Slowly peel the distorted label from the sun visor by steadily pulling a loose edge. Do not use a knife to remove the label. A knife may injure you or damage the sun visor.
2. Clean the label attachment area with a clean cloth.
3. Peel the backing paper off the new label and attach the new label in the position where the original label was located, as shown in the photos below:



4. Rub across the new label to attach it securely to the sun visor.

Note: The labels are packed with a fine powder in a clear plastic bag to prevent them from sticking together.



MOTOR VEHICLE RECALL

Dear 2006 Sonata Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Hyundai has decided that a defect, which relates to motor vehicle safety, exists in certain model year 2006 Hyundai Sonata vehicles that were produced during the period beginning on April 14, 2005 through August 31, 2005.

Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

What is the problem?

- Labels containing air bag warning information, illustrated below, are attached to your vehicle's sun visors. Some of these labels may not have been properly installed, causing them to distort or separate from the sun visors. If the labels are distorted or missing, the driver or front seat passenger will not have information available that may help protect them in the event of a crash.



What should you do?

- We are asking you to inspect your sun visors to make sure that the air bag warning labels are securely attached. If the labels are secure, do not take any further action. If any label is distorted, not securely attached or missing, we urge you to replace that label. Enclosed with this letter are two replacement labels for each of the above air bag warning label types. An instruction sheet is enclosed to help you to properly install the replacement labels, if it is necessary.

What will Hyundai do?

- If any of your sun visor air bag warning labels are distorted or not securely attached, we are providing you with replacement labels and installation instructions, included with this letter. If you do not feel confident that you can properly check your vehicle's sun visor air bag warning labels or install replacement labels, we are asking you to schedule an appointment as soon as possible to take your vehicle to your Hyundai dealer. The Hyundai dealer will replace your vehicle's sun visor air bag warning labels, if necessary. This procedure will be performed at no charge to you. You should plan to leave your vehicle at your Hyundai dealer to have this service performed. Repair times will vary and depend on your dealer's appointment schedule.

What if you have other questions?

- If you have any difficulty having this repair performed, we recommend that you call the Hyundai Customer Assistance Center at 1-800-633-5151. If you are still not satisfied that we have remedied this situation without charge, and within a reasonable amount of time, you may wish to write to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, S. W., Washington, D.C. 20590, or call their toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153), or go to <http://www.safercar.gov>.

We urge your prompt attention to this important safety matter.

Hyundai Motor America