

**GM SERVICE AND PARTS OPERATIONS
DCS1634
URGENT - DISTRIBUTE IMMEDIATELY**

Date: August 24, 2006

Subject: Product Safety Recall 06080
Fuel Rail Pulse Damper Retainer Clip

Models: 2004-2006 Chevrolet Avalanche, Silverado, Suburban
2004-2006 GMC Sierra, Yukon XL
2006 Chevrolet Kodiak
2006 GMC TopKick
Equipped with 8.1 L Engine (RPO L18 - VIN G) V8 Engine

To: All Chevrolet and GMC Dealers

Attention: Service Manager, Parts Manager and Warranty Administrator

IMMEDIATE ACTION REQUIRED

General Motors is announcing Product Safety Recall 06080 today. The total number vehicles involved is 50,923.

Mailing Information

Customer notification mailing will begin on August 31, 2006

GM Vehicle Inquiry System (GMVIS)

GMVIS information will be available on August 24, 2006.

Service Information System (SI)

Bulletin 06080 will be available in SI on August 25, 2006.

Campaign Initiation Detail Report (CIDR)

The CIDR will be available in GM DealerWorld on August 24, 2006.

DOUBLE CLICK ON THE ICON BELOW
THEN SINGLE CLICK ON THE LAUNCH BUTTON
TO VIEW OR PRINT THE BULLETIN

(See attached file: 06080 bulletin.pdf)

END OF MESSAGE
GM SERVICE AND PARTS OPERATIONS



Recall Bulletin



PRODUCT SAFETY RECALL

SUBJECT: FUEL RAIL PULSE DAMPER RETAINER CLIP

**MODELS: 2004-06 CHEVROLET SILVERADO, SUBURBAN, AVALANCHE
 2004-06 GMC SIERRA, YUKON XL
 2006 CHEVROLET KODIAK
 2006 GMC TOPKICK
 EQUIPPED WITH 8.1L V8 (RPO L18 – VIN G) ENGINE**

CONDITION

General Motors has decided that a defect, which relates to motor vehicle safety, exists in **certain** 2004-06 Chevrolet Silverado, Suburban, Avalanche; GMC Sierra, Yukon XL; 2006 Chevrolet Kodiak and GMC TopKick model vehicles equipped with an 8.1L V8 (RPO L18 – VIN G) engine. Some of these vehicles have a condition in which the engine fuel rail pulse damper retainer clip may fracture, resulting in inadequate retention of the damper. If the damper comes loose, a fuel leak may result and may cause a fire if an ignition source is present.

CORRECTION

Dealers are to replace the engine fuel rail pulse damper retainer clip.

VEHICLES INVOLVED

Involved are **certain** 2004-06 Chevrolet Silverado, Suburban, Avalanche; GMC Sierra, Yukon XL; 2006 Chevrolet Kodiak and GMC TopKick model vehicles equipped with an 8.1L V8 (RPO L18 – VIN G) engine and built within these VIN breakpoints:

YEAR	DIVISION	MODEL	FROM	THROUGH
2004	Chevrolet	Silverado	4E100001	4E403748
			4F100001	4F268892
2004	Chevrolet	Suburban	4G100017	4G323424
2004	Chevrolet	Avalanche	4G100021	4G342507
2004	GMC	Sierra	4E100026	4E403746
			4F100005	4F268978
2004	GMC	Yukon XL	4G100063	4G330196
2005	Chevrolet	Silverado	5E100005	5E341749
			5F800001	5F974205
2005	Chevrolet	Suburban	5G100028	5G293856

YEAR	DIVISION	MODEL	FROM	THROUGH
2005	Chevrolet	Avalanche	5G100021	5G294214
2005	GMC	Sierra	5E100148	5E342417
			5F800037	5F973935
2005	GMC	Yukon XL	5G100081	5G294588
2006	Chevrolet	Silverado	6E100015	6E240507
			6F100008	6F210567
2006	Chevrolet	Suburban	6G100627	6G207941
2006	Chevrolet	Avalanche	6G100015	6G207955
2006	Chevrolet	Kodiak	6F400012	6F429180
2006	GMC	Sierra	6E100017	6E238551
			6F100215	6F243466
2006	GMC	Yukon XL	6G100254	6G207939
2006	GMC	TopKick	6F400001	6F903959

Important: Dealers are to confirm vehicle eligibility prior to beginning repairs by using GMVIS. Not all vehicles within the above breakpoints may be involved.

For dealers with involved vehicles, a listing with involved vehicles containing the complete vehicle identification number, customer name, and address information has been prepared and will be provided through the applicable system listed below. Dealers will not have a report available if they have no involved vehicles currently assigned.

- US GM dealers - GM DealerWorld Recall Information
- Canadian GM dealers - GMInfoNet Recall Reports
- Export dealers - sent directly to dealers

The listing may contain customer names and addresses obtained from Motor Vehicle Registration Records. The use of such motor vehicle registration data for any purpose other than follow-up necessary to complete this recall is a violation of law in several states/provinces/countries. Accordingly, you are urged to limit the use of this report to the follow-up necessary to complete this recall.


PARTS INFORMATION

Parts required to complete this recall are to be obtained from General Motors Service and Parts Operations (GMSPO). Please refer to your "involved vehicles listing" before ordering parts. Normal orders should be placed on a DRO = Daily Replenishment Order. In an emergency situation, parts should be ordered on a CSO = Customer Special Order.

Part Number	Description	Quantity/Vehicle
12575017	Clamp-Fuel Pulse Dpnr	1

SERVICE PROCEDURE

IMPORTANT: The service procedure contained in this recall is different from the service procedure found in the appropriate service manual. As a result, the labor time allowance has been revised to correspond with this new service procedure


Service Procedure – Light Duty Trucks (Silverado, Suburban, Avalanche, Sierra, Yukon XL)

SIO 843779

1. Unsnap the intake manifold sight shield from the stud.
2. Remove the sight shield from the sight shield bracket.

J 34730-1A Fuel Pressure Gage


Caution: Relieve the fuel system pressure before servicing fuel system components in order to reduce the risk of fire and personal injury. After relieving the system pressure, a small amount of fuel may be released when servicing the fuel lines or connections. In order to reduce the chance of personal injury, cover the regulator and the fuel line fittings with a shop towel before disconnecting. This will catch any fuel that may leak out. Place the towel in an approved container when the disconnection is complete.



SIO 180378

3. Disconnect the negative battery cable. Refer to Battery Negative Cable Disconnection and Connection in SI.
4. Loosen the fuel fill cap in order to relieve fuel tank vapor pressure.

5. Remove the fuel rail pressure cap.
6. Connect the J 34730-1A to the fuel pressure valve. Wrap a shop towel around the fitting while connecting the gage in order to avoid spillage.
7. Install the bleed hose on J 34730-1A into an approved container.
8. Open the valve on the J 34730-1A in order to bleed the system pressure. The fuel connections are now safe for servicing.
9. Once the system pressure is completely relieved, remove the J 34730-1A
10. Remove the bleed hose on the J 34730-1A from the approved container.
11. Remove the shop towel from around the fitting and discard into an approved container.
12. Disconnect the J 34730-1A from the fuel pressure valve.
13. Drain any fuel remaining in the gage into an approved container.
14. Install the fuel rail pressure fitting cap.




SIO 1254422

15. Clean any dirt from the fuel pressure dampener (i.e. damper) retainer (clip) and the surrounding area.

Note: Do not remove the fuel dampener from the fuel rail. If the dampener is removed the fuel dampener o-ring must be replaced.

16. Push down on the fuel dampener and remove the fuel pressure dampener clip (1) and discard.



SIO 1254422

17. Push down on the fuel dampener and install the fuel pressure dampener clip (1).
18. Install the fuel fill cap.

19. Connect the negative battery cable. Refer to Battery Negative Cable Disconnection and Connection in SI.


20. Use the following procedure to inspect for leaks:

20.1 Turn the ignition ON, with the engine OFF, for 2 seconds.

20.2 Turn the ignition OFF for 10 seconds.

20.3 Turn the ignition ON, with the engine OFF.

20.4 Inspect for fuel leaks.




SIO 843779

21. Install the intake manifold sight shield to the bracket.

22. Snap the intake manifold sight shield onto the stud.

23. Close the hood.

Service Procedure – Medium Duty Trucks (Chevrolet Kodiak and GMC TopKick)




SIO 882676

1. Turn the wheels to the left.

2. Tilt the hood open.


3. Remove the clip retaining the wheel housing panel to the radiator support bracket.

4. Remove the clip retaining the wheel housing panel to the rear cowl panel.
5. Remove the wheel housing panel, from the retainer tabs.
6. Remove the wheel house panel from the vehicle.



SIO 1556841


7. Remove the Under Hood Fuse Block Cover.
8. Remove the 20A/25A ECM-B/FUEL PUMP fuse.
9. Start the engine to relieve fuel rail pressure. (Engine should start and stall.)



SIO 1254422


Notice: Do not remove the fuel dampener (i.e. damper) from the fuel rail. If the dampener is removed, the fuel dampener o-ring must be replaced.

10. Clean any dirt from the fuel pressure dampener retainer (clip) and the surrounding area.



SIO 1254422

11. Remove the fuel pressure dampener retainer (1).
12. Install a new fuel pressure dampener retainer (1).
13. Install the 20A/25A ECM-B/FUEL PUMP fuse.
 - 13.1 Turn ON the ignition for 2 seconds.
 - 13.2 Turn OFF the ignition for 10 seconds.
 - 13.3 Turn ON the ignition.
 - 13.4 Inspect for fuel leaks.
14. Install the Under Hood Fuse Block Cover.



SIO 882676

15. Install the wheel housing panel to the retainer tabs.
16. Install the clip retaining the front of the panel to the radiator support bracket.
17. Install the clip retaining the wheel housing panel to the rear cowl panel.
18. Tilt the hood closed.

COURTESY TRANSPORTATION

The General Motors Courtesy Transportation Program is intended to minimize customer inconvenience when a vehicle requires a repair that is covered by the New Vehicle Limited Warranty. The availability of courtesy transportation to customers whose vehicles are within the warranty coverage period and involved in a product recall is very important in maintaining customer satisfaction. Dealers are to ensure that these customers understand that shuttle service or some other form of courtesy transportation is available and will be provided at no charge. Dealers should refer to the General Motors Service Policies and Procedures Manual for courtesy transportation guidelines.

CLAIM INFORMATION

Submit a Product Recall Claim with the information indicated below:

REPAIR PERFORMED	PART COUNT	PART NO.	PARTS ALLOW	CC-FC	LABOR OP	LABOR HOURS	NET ITEM
Replace engine fuel rail pulse damper retainer clip. Light Duty Truck Medium Duty Truck	1	12575017	*	MA-96	V1506	0.3 0.5	N/A
Courtesy Transportation for vehicles within the New Vehicle Limited Warranty (US & Canadian GM Dealers)	N/A	N/A	N/A	MA-96	**	N/A	***

- * The "Parts Allowance" should be the sum total of the current GMSPO Dealer net price plus applicable Mark-Up or Landed Cost Mark-Up (for Export) for engine fuel rail pulse damper retainer clip needed to complete the repair.
- ** Submit courtesy transportation using normal labor operations for courtesy transportation as indicated in the GM Service Policies and Procedures Manual for vehicles within the New Vehicle Limited Warranty.
- *** The amount identified in the "Net Item" column should represent the actual dollar amount for courtesy transportation.

Refer to the General Motors WINS Claims Processing Manual for details on Product Recall Claim Submission.

CUSTOMER NOTIFICATION – For US and Canada

General Motors will notify customers of this recall on their vehicle (see copy of customer letter included with this bulletin).

CUSTOMER NOTIFICATION – For Export

Letters will be sent to known owners of record located within areas covered by the US National Traffic and Motor Vehicle Safety Act. For owners outside these areas, dealers should notify customers using the attached sample letter.

DEALER RECALL RESPONSIBILITY – For US and Export (US States, Territories, and Possessions)

The US National Traffic and Motor Vehicle Safety Act provides that each vehicle that is subject to a recall of this type must be adequately repaired within a reasonable time after the customer has tendered it for repair. A failure to repair within sixty days after tender of a vehicle is prima facie evidence of failure to repair within a reasonable time. If the condition is not adequately repaired within a reasonable time, the customer may be entitled to an identical or reasonably equivalent vehicle at no charge or to a refund of the purchase price less a reasonable allowance for depreciation. To avoid having to provide these burdensome remedies, every effort must be made to promptly schedule an appointment with each customer and to repair their vehicle as soon as possible. In the recall notification letters, customers are told how to contact the US National Highway Traffic Safety Administration if the recall is not completed within a reasonable time.

DEALER RECALL RESPONSIBILITY – All

All unsold new vehicles in dealers' possession and subject to this recall must be held and inspected/repaired per the service procedure of this recall bulletin before customers take possession of these vehicles.

Dealers are to service all vehicles subject to this recall at no charge to customers, regardless of mileage, age of vehicle, or ownership, from this time forward.

Customers who have recently purchased vehicles sold from your vehicle inventory, and for which there is no customer information indicated on the dealer listing, are to be contacted by the dealer. Arrangements are to be made to make the required correction according to the instructions contained in this bulletin. A copy of the customer letter is provided in this bulletin for your use in contacting customers. Recall follow-up cards should not be used for this purpose, since the customer may not as yet have received the notification letter.

In summary, whenever a vehicle subject to this recall enters your vehicle inventory, or is in your dealership for service in the future, you must take the steps necessary to be sure the recall correction has been made before selling or releasing the vehicle.



August 2006

Dear General Motors Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

General Motors has decided that a defect, which relates to motor vehicle safety, exists in certain 2004-06 Chevrolet Silverado, Suburban, Avalanche; GMC Sierra, Yukon XL; 2006 Chevrolet Kodiak and GMC TopKick model vehicles equipped with an 8.1L V8 engine. As a result, GM is conducting a safety recall. We apologize for this inconvenience. However, we have taken this action for your safety and continued satisfaction with our products.

I M P O R T A N T

- Your vehicle is involved in safety recall 06080.
- Schedule an appointment with your GM dealer.
- This service will be performed for you at **no charge**.

Why is your vehicle being recalled?

Some of these vehicles have a condition in which the engine fuel rail pulse damper retainer clip may fracture, resulting in inadequate retention of the damper. If the damper comes loose, a fuel leak may result and may cause a fire if an ignition source is present.

What will we do?

Your GM dealer will replace the engine fuel rail pulse damper retainer clip. This service will be performed for you at **no charge**. It is likely that your dealer will need your vehicle longer than the actual service correction time of approximately 35 minutes because of service scheduling requirements.

If your vehicle is within the New Vehicle Limited Warranty your dealer may provide you with shuttle service or some other form of courtesy transportation while your vehicle is at the dealership for this repair. Please refer to your Owner's Manual and your dealer for details on courtesy transportation.

What should you do?

You should contact your GM dealer to arrange a service appointment as soon as possible. Bring the enclosed customer reply form with you when you visit your dealer. The form identifies the repairs required. If you no longer own this vehicle, please let us know by completing the form and mailing it back to us.

Do you have questions?

If you have questions or concerns that your dealer is unable to resolve, please contact the appropriate Customer Assistance Center at the number listed below. More information about this recall can be found at the Owner Center at MyGMLink, <http://www.gm.com/recall>.

Division	Telephone Number	Text Telephones (TTY)
Chevrolet	1-800-630-2438	1-800-833-2438
GMC	1-866-996-9463	1-800-462-8583
Guam	1-671-648-8650	
Puerto Rico – English	1-800-496-9992	
Puerto Rico – Español	1-800-496-9993	
Virgin Islands	1-800-496-9994	
GMCT	1-800-862-4389	

If, after contacting your dealer and the Customer Assistance Center, you are still not satisfied we have done our best to remedy this condition without charge and within a reasonable time, you may wish to write the Administrator, National Highway Traffic Safety Administration, 400 Seventh St., SW, Washington DC 20590, or call the toll-free Vehicle Safety Hotline at 1.888.327.4236 (TTY 1.800.424.9153), or go to <http://www.safercar.gov>.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

Scott Lawson
General Director,
Customer and Relationship Services

Enclosure
06080