

OWNER NOTIFICATION

Dear Nissan Owner:

IMPORTANT

- **Your 2004-2006 model year Nissan Titan King Cab is involved in a safety recall because there is the possibility that the wires may break in the passenger side harness due to over bending as the doors are opened and closed.**
- **Please schedule an appointment with your Nissan dealer.**
- **This service will be performed for you at no charge.**

This third notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Nissan has decided that a defect that relates to motor vehicle safety exists in some 2004-2006 model year Nissan Titan King Cab vehicles. Our records indicate that you own or lease the Nissan vehicle identified by the VIN on the cover of this notice.

Reason for Recall

In some affected vehicles, there is the possibility that the wires in the harness routed through the rear doors and into the body on each side of the vehicle may break due to over bending of the harness as the doors are opened and closed. The wires in the harness control various systems including the seat belt pretensioners, the passenger side seat belt tension sensor, and rear audio speakers.

If the wire for the seat belt pretensioners breaks and makes contact with a wire for the speaker, there is a possibility that the pretensioner may deploy and tighten the seat belt. If this happens when the belt is retracted, it will not be possible to use the seat belt. Driving without the seatbelt is dangerous and could increase your risk of injury in a crash.

If one of the wires for the seat belt tension sensor breaks inside the passenger side harness, the passenger side front air bag will not deploy as designed in a frontal crash, possibly resulting in an injury.

What Nissan Will Do

Your Nissan dealer will inspect the wire harness cover for damage and, if necessary, a new wiring harness with a new type cover will be installed and rerouted. This free service should take between 2 and 5 hours to complete depending on the repair required, but your Nissan dealer may require your vehicle for a longer period of time based upon their work schedule.

What You Should Do

If you have not done so already, we urge you to please contact your Nissan dealer at your earliest convenience in order to arrange an appointment to have your vehicle repaired. Please bring this notice with you when you keep your service appointment. Instructions have been sent to your Nissan dealer.

If you have paid to have your wire harness replaced prior to this campaign, you may be eligible for reimbursement of the related expense. If you have additional questions you may contact the National Consumer Affairs Department, Nissan North America, Inc., P.O. Box 685003, Franklin, TN 37068-5003. The toll free number is 1-800-NISSAN1 (1-800-647-7261). You may also contact the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE., Washington, DC 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

Thank you for your cooperation. We are indeed sorry for any inconvenience this may cause you.