Around Town Transportation Products, LLC.

307 Dividend Dr. Peachtree City, GA 30269 Telephone: 678-364-1323 Fax: 678-364-8594

September 16, 2008

Mr. Alex Ansley
US DOT- NHTSA
Office of Defects Investigation
Recall Management / W46-437
1200 New Jersey Ave SE
Washington, DC 20590
P. (202) 493-0481
F. (202) 366-7882

08V-478 (7 pages)

Dear Mr. Ansley:

On June 25, 2008, Around Town Transportation Products, LLC decided that (a defect which relates to motor vehicle safety)(a noncompliance with Federal Motor Vehicle Safety Standard No. 403) exists in the motor vehicles listed below, and is furnishing notification to the National Highway Traffic Safety Administration in accordance with 49 CFR Part 573 <u>Defect and Noncompliance Responsibility and Reports.</u>

This report was prepared on September 12, 2008. The manufacturer's identification code for this recall is **07E-095**.

1. The full corporate name and the mailing address of the fabricating manufacturer is:

Around Town Transportation Products, LLC.

307 Dividend Dr. Peachtree City, GA 30269

The corporate officials whom the agency should contact, with respect to this recall are:

Scott Benton - Director of Manufacturing Brian Burroughs - Parts and Warranty Manger

sbenton@aroundtowntp.com brian@aroundtowntp.com

Telephone: 678-364-1323 ext. 108 Telephone: 678-364-1323 ext. 107

Sincerely,

Brian Burroughs
Parts and Warranty Manager

RECEIVED

2008 SEP 18 10:35 AM

DEFECTS INVESTIGATION RECALL MGMT DIV.

		September 16, 2008
Make: Ford Model: Econoline	Model Year: <u>2003</u>	<u> </u>
Production Dates: Beginning: 8/1/06 End	ling: <u>12/31/06</u>	
Vehicle Type: Van Body style: Wheelcha	air conversion van	
Verlide Type. <u>Vari</u> Body Style. <u>vvriced Re</u>	all conversion vari	
Make: Ford Model: Econoline	Model Year: 2006	<u>: </u>
Production Dates: Beginning: <u>8/1/06</u> End	ling: <u>12/31/06</u>	
Vehicle Type: Van Body style: Wheelcha	air conversion van	
Descriptive information which characterizes/disincluded in the recall:	stinguishes the recalle	d vehicles from those vehicles not
A.T.T.P., LLC. purchased and installed a ver conversion vans. Of all the wheelchair vans the affected by this Ricon lift recall. This number about 2%.	hat A.T.T.P., LLC. has	s manufactured, only six vans are
II. Identify the Recal	I Population	
3. Furnish the total number of vehicl noncompliance.	les recalled potent	ially containing the defect or
Model		Number of Vehicles
Model	Year	Potentially Involved
Ford E-350	Year 2003	1
Ford E-350	2003	1
Ford E-350	2003 2006	1
Ford E-350 Ford E-250	2003 2006 ecall:	1 5 Six
Ford E-350 Ford E-250 Total Number Potentially Affected by the Ref. 4. Furnish the approximate percentage of	2003 2006 ecall: f the total number of ation was determined.	1 5 Six f vehicles estimated to actually din particular how the recalled
Ford E-350 Ford E-250 Total Number Potentially Affected by the Ref. 4. Furnish the approximate percentage of contain the defect or noncompliance: 100% Identify and describe how the recall popula models were selected and the basis for the second	2003 2006 ecall: f the total number of ation was determined beginning and firms	1 5 Six f vehicles estimated to actually din particular how the recalled hal dates of manufacture of the
Ford E-350 Ford E-250 Total Number Potentially Affected by the Research A. Furnish the approximate percentage of contain the defect or noncompliance: 100% Identify and describe how the recall popula models were selected and the basis for the recalled vehicles:	2003 2006 ecall: f the total number of ation was determined the beginning and first/heelchair lifts, supplied	Six f vehicles estimated to actually din particular how the recalled hal dates of manufacture of the
Ford E-350 Ford E-250 Total Number Potentially Affected by the Ref. 4. Furnish the approximate percentage of contain the defect or noncompliance: 100% Identify and describe how the recall popula models were selected and the basis for the recalled vehicles: Ricon Corporation, the manufacturer of the warms.	2003 2006 ecall: f the total number of the t	Six Six f vehicles estimated to actually din particular how the recalled hal dates of manufacture of the ed A.T.T.P., LLC. with a list of all After submitting the serial numbers
Ford E-350 Ford E-250 Total Number Potentially Affected by the Research A. Furnish the approximate percentage of contain the defect or noncompliance: 100% Identify and describe how the recall popular models were selected and the basis for the recalled vehicles: Ricon Corporation, the manufacturer of the waserial numbers of lifts that could possibly be affected.	2003 2006 ecall: f the total number of the total number of the beginning and fire the delication was determined beginning and fire the delication with the delication with the delication which of the delication with the delic	Six f vehicles estimated to actually din particular how the recalled hal dates of manufacture of the ed A.T.T.P., LLC. with a list of all After submitting the serial numbers of lifts that were actually affected by
Ford E-350 Ford E-250 Total Number Potentially Affected by the Research A. Furnish the approximate percentage of contain the defect or noncompliance: 100% Identify and describe how the recall popula models were selected and the basis for the recalled vehicles: Ricon Corporation, the manufacturer of the waserial numbers of lifts that could possibly be affected to Ricon's support team via their website, we describe the recalled vehicles:	2003 2006 ceall: f the total number of the beginning and fire the diffected by this recall. A discovered which of the diffication (#07E-095).	Six Six f vehicles estimated to actually din particular how the recalled hal dates of manufacture of the ed A.T.T.P., LLC. with a list of all After submitting the serial numbers e lifts that were actually affected by Once the affected serial numbers
Ford E-350 Ford E-250 Total Number Potentially Affected by the Ref. 4. Furnish the approximate percentage of contain the defect or noncompliance: 100% Identify and describe how the recall popula models were selected and the basis for the recalled vehicles: Ricon Corporation, the manufacturer of the waserial numbers of lifts that could possibly be affected to Ricon's support team via their website, we described to Safety Standard Non-Compliance Recall Notice.	2003 2006 ceall: f the total number of the beginning and fire the diffected by this recall. A discovered which of the diffication (#07E-095).	Six Six f vehicles estimated to actually din particular how the recalled hal dates of manufacture of the ed A.T.T.P., LLC. with a list of all After submitting the serial numbers e lifts that were actually affected by Once the affected serial numbers
Ford E-350 Ford E-250 Total Number Potentially Affected by the Research A. Furnish the approximate percentage of contain the defect or noncompliance: 100% Identify and describe how the recall popular models were selected and the basis for the recalled vehicles: Ricon Corporation, the manufacturer of the wasterial numbers of lifts that could possibly be affected to Ricon's support team via their website, we described Safety Standard Non-Compliance Recall Notice were cross-referenced to the VIN numbers in	2003 2006 ceall: f the total number of the beginning and fire the diffected by this recall. A discovered which of the diffication (#07E-095).	Six Six f vehicles estimated to actually din particular how the recalled hal dates of manufacture of the ed A.T.T.P., LLC. with a list of all After submitting the serial numbers e lifts that were actually affected by Once the affected serial numbers

• Page 3 September 16, 2008

III. Describe the Defect or Noncompliance

physical location of the defect or noncompliance. Illustrations should be provided as appropriate.
Please refer to Ricon Corporation's Safety Standard Non-Compliance Recall Notification (#07E-095).
Describe the cause(s) of the defect or noncompliance condition.
Please refer to Ricon Corporation's Safety Standard Non-Compliance Recall Notification (#07E-095).
Describe the consequence(s) of the defect or noncompliance condition.
Please refer to Ricon Corporation's Safety Standard Non-Compliance Recall Notification (#07E-095).
Identify any warning which can (a) precede or (b) occur.
Please refer to Ricon Corporation's Safety Standard Non-Compliance Recall Notification (#07E-095).
If the defect or noncompliance is in a component or assembly purchased from a supplier, identify the supplier by corporate name and address.
Ricon Corporation
7900 Nelson Road
Panorama City, CA 91402
Identify the name and title of the chief executive officer or knowledgeable representative of the supplier: Stanton Saucier – General Manager William Hinze – Director - Marketing

Page 4September 16, 2008

IV. Provide the Chronology in Determining the Defect/Noncompliance

If the recall is for a defect, complete item 6, otherwise item 7.

6. With respect to a defect, furnish a chronological summary (including dates) of all the principle events that were the basis for the determination of the defect. The summary should include, but not be limited to, the number of reports, accidents, injuries, fatalities, and warranty claims.

Please refer to Ricon Corporation's Safety Standard Non-Compliance Recall Notification (#07E-095).		
7. With respect to a noncompliance, identify and provide the test results or other data (in chronological order and including dates) on which the noncompliance was determined.		
Please refer to Ricon Corporation's Safety Standard Non-Compliance Recall Notification (#07E-095).		
V. Identify the Remedy		
8. A description of the manufacturer's program for remedying the defect or noncompliance. This program shall include a plan for reimbursing an owner or purchaser who incurred costs to obtain a remedy for the problem addressed by the recall within a reasonable time in advance of the manufacturer's notification of owners, purchasers and dealers, in accordance with §573.13 of this part. A manufacturer's plan may incorporate by reference a general reimbursement plan it previously submitted to NHTSA, together with information specific to the individual recall. Information required by §573.13 that is not in a general reimbursement plan shall be submitted in the manufacturer's report to NHTSA under this section. If a manufacturer submits one or more general reimbursement plans, the manufacturer shall update each plan every two years, in accordance with §573.13. The manufacturer's remedy program and reimbursement plans will be available for inspection by the public at NHTSA headquarters.		
Please refer to Ricon Corporation's Safety Standard Non-Compliance Recall Notification (#07E-095).		

9. Furnish a description of the manufacturer's remedy for the defect or noncompliance. Clearly describe the differences between the recall condition and the remedy.
Please refer to Ricon Corporation's Safety Standard Non-Compliance Recall Notification (#07E-095).
Clearly describe the distinguishing characteristics of the remedy component/assembly versus the recalled component/assembly.
Please refer to Ricon Corporation's Safety Standard Non-Compliance Recall Notification (#07E-095).
Identify and describe how and when the recall condition was corrected in production. If the production remedy was identical to the recall remedy in the field, so state. If the product was discontinued, so state.
Please refer to Ricon Corporation's Safety Standard Non-Compliance Recall Notification (#07E-095).
VI. Identify the Recall Schedule
10. Furnish a schedule or agenda (with specific dates) for notification to other manufacturers, dealers/retailers, and purchasers. Please, identify any foreseeable problems with implementing the recall.
After notification to our customers (with the affected lifts), A.T.T.P., LLC. will accept appointments to
repair the lifts according to Ricon's instructions. Should a customer not be able to travel to our facility for repairs, we will assist them in making an appointment at another certified Ricon Dealer.

September 16, 2008

• Page 5

Page 6September 16, 2008

VII. Furnish Recall Communications

11. Furnish a final copy of all notices, bulletins, and other communications that relate directly to the defect or noncompliance and which are sent to more than one manufacturer, distributor, or purchaser. This includes all communications (including both original and follow-up) concerning this recall from the time your company determines the defect or noncompliance condition on, not just the initial notification. A DRAFT copy of the notification documents should be submitted to this office by Fax (202-366-7882) or by E-Mail to RMD.ODI@dot.gov for review prior to mailing.

<u>Note</u> that these documents are to be submitted separately from those provided in accordance with Part 579.5 requirements.

Around Town Transportation Products, LLC.

307 Dividend Dr. Peachtree City, GA 30269 Telephone: 678-364-1323 Fax: 678-364-8594

September 15, 2008

Dear Ricon wheelchair lift owner:

Around Town Transportation Products, LLC. sent this notice to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

REASON FOR THIS RECALL

A.T.T.P., LLC. has determined that a defect, which relates to motor vehicle safety, exists in certain Ford Econoline wheelchair vans. These vehicles have been equipped with Ricon S-Series wheelchair lifts in them. The non-compliance with S6.1 of the 403 is the result of the Threshold Warning System not detecting the presence of a wheelchair or mobility aid user in a certain spot within the defined threshold area. In the event this condition occurs during passenger operations the wheelchair or mobility aid, user may move toward the vehicle lift door when the lift platform is below floor level. This situation could cause personal injury.

WHAT WE WILL DO

Upon notification, Ricon will provide you or the A.T.T.P., LLC. the replacement parts kit. We will provide all the necessary adjustment instructions and/or replacement parts Free of Charge.

Thank you for your prompt attention to this matter. If you have any questions concerning these procedures, please contact Brian at (678) 364-1323 or by email at brian@aroundtowntp.com.

WHAT YOU SHOULD DO

Please contact your Ricon dealer as soon as possible to arrange a service date and so the dealer may order the necessary parts for the repair. If you are already factory trained to perform service on Ricon lifts, the repairs can be done at your location. If you are not factory trained to service Ricon lifts, you should contact Brian at Around Town Transportation Products, LLC.

A.T.T.P., LLC. or another Ricon certified Dealer is best equipped to obtain parts and provide service to ensure that your vehicle is corrected as promptly as possible.

After contacting your Ricon dealer, if you are still not able to have the safety defect remedied without charge and within a reasonable time, you may wish to write Alex Ansley: US DOT- NHTSA Office of Defects Investigation Recall Management / W46-437 1200 New Jersey Ave SE Washington, DC 20590 P. (202) 493-0481 F. (202) 366-7882

We are sorry to cause this inconvenience; however, we have taken this action in the interest of your safety and continued satisfaction with our products.

Sincerely,

Brian Burroughs
Parts and Warranty Manager
Around Town Transportation Products, LLC.