

08V-641 (3 Pages)

December 4, 2008

Mr. Daniel C. Smith
Associate Administrator for Enforcement
National Highway Traffic Safety Administration
1200 New Jersey Avenue, SE
West Building, Fourth Floor
Washington, D.C. 20590

Dear Mr. Smith:

Attached is Chrysler LLC's ("Chrysler") Defect Information Report, complying with the requirements of 49 CFR Part 573, Defect and Noncompliance Reports, which contains details of a potential safety related defect in some 2007 and 2008 model year Dodge Ram heavy duty (2500/3500) pick up trucks equipped with 6.7L diesel engines. A silencer pad may sag and contact the exhaust gas recirculation cooler, which can result in an engine compartment fire.

Chrysler will conduct a safety recall to add a bracket to support the silencer pad.

Sincerely,

Lawrence J. Sak

Enclosure: Defect Information Report for Chrysler Recall H34

cc: K.C. DeMeter, NHTSA

aurent for

Division of Occupational Safety & Health California Department of Industrial Relations

RECEIVED 2008 DECEMBER 5 – 10:00 AM OFFICE OF RECALL MANAGEMENT DIVISION Submission date: December 4, 2008

Identifying classification of vehicles potentially affected:

Make	Model	Model Year	Inclusive Dates of Manufacture	Volume	Other
Dodge	Ram 2500/3500 pick up	2007-2008	January 1, 2007 through November 5, 2007	108,429 (estimated)	With 6.7L diesel engine only

Estimated percentage containing defect: 7%

Description of defect:

A silencer pad can sag and contact the exhaust gas recirculation (EGR) cooler, which can result in an engine compartment fire.

The following chronology of principal events led to the determination of a defect:

- In October of 2007 an internal investigation was initiated based on two reports of engine compartment silencer pads burned away in the area of the EGR cooler. Both were heavy duty pick ups equipped with 6.7L diesel engines, introduced during the 2007 model year.
- As a precautionary measure, in November of 2007 aluminum scrim and additional silencer pad fasteners were added adjacent to the EGR cooler while the investigation continued.
- Thermal studies determined the EGR cooler may achieve temperatures in excess of 900 F under certain driving conditions.
- A survey was initiated to evaluate silencer pad clearance to EGR cooler. Although the vast majority of vehicles exhibited significant clearance, 2 of 29 silencer pads exhibited contact with the EGR cooler (7%).
- Ongoing evaluation of high mileage vehicles determined engine compartment moisture may contribute to silencer pad sagging in the area of the EGR cooler.
- Monitoring of vehicles built post-November of 2007 has verified elimination of the sag potential with addition of the aluminum scrim and additional fasteners.
- Chrysler is currently aware of 14 complaints of engine compartment fire with vehicles built prior to November of 2007 that may be related to this issue.
- This data was presented to the Vehicle Regulations Committee on November 25, 2008 who
 decided to conduct a safety recall.

DEFECT INFORMATION REPORT FOR CHRYSLER LLC RECALL H34

Page 2

Statement of measures to be taken to correct defect:

Chrysler will conduct a safety recall to add a bracket to support the engine compartment silencer pad adjacent to the EGR cooler. Chrysler expects to initiate national notification to both dealers and owners in December of 2008.

Chrysler has a longstanding policy and practice of reimbursing owners who have incurred the cost of repairing a problem that subsequently becomes the subject of a field action. To ensure consistency, Chrysler, as part of the owner letter, will request that customers send original receipt and/or other adequate proof of payment to the company for confirmation of the expense.