



AFFECTED VEHICLES
MODELS: 2004-2008 Endeavor

Date: July, 2008

Dear Mitsubishi Owner,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Reason For Notice: Mitsubishi Motors North America, Inc. (MMNA) has decided that a defect that relates to vehicle safety exists in certain 2004-2008 Endeavor vehicles. The gearshift to ignition switch interlock system may allow the ignition key to be removed from the ignition switch without placing the gearshift in the Park position. If the driver does not shift to Park before removing the key from the ignition, and does not engage the parking brake, the vehicle could roll and a crash could occur.

What you should do: Please contact your Authorized Mitsubishi Dealer to schedule an appointment to have the shift interlock system repaired on your vehicle, free of charge. When you bring your vehicle in, please show the dealer this letter. (If you misplace this letter, the dealer will still install the new parts on your vehicle, free of charge.)

What your dealer will do: The dealership will install a repair parts kit into the shift interlock assembly.

How long will it take? The time needed for the installation of these new parts is approximately 30 minutes. The dealer may need your vehicle for a longer period of time due to service scheduling issues, but every effort will be made to minimize your inconvenience.

If you have any trouble having your vehicle repaired promptly and at no charge, please inform us by calling the Mitsubishi Customer Relations Department at **888-648-7820**.

Hours: Monday through Friday 6 a.m. to 5 p.m. (Pacific Time)

If, after contacting Mitsubishi Customer Relations, you still have a problem having this repair made promptly and without charge, write to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue SE, Washington, D.C. 20590, or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153), or go to <http://www.safercar.gov>.

If you have already encountered a problem regarding the above and have paid for the repair, you may send your original receipts and/or other adequate proof of payment to the following address for reimbursement:
Mitsubishi Customer Relations Department, P.O. Box 6400, Cypress, CA 90630-0064

Notice to Lessors: If you are a lessor of five or more leased vehicles as of the date of this letter, you have an obligation under federal law, (49 CFR Part 577), to provide the lessee of the above referenced vehicle with a copy of this letter by first class mail within ten days of receipt. Further, you must maintain a record, which identifies the lessee to whom you sent a copy of this letter, the date you sent it, and the vehicle identification number (VIN) of the subject vehicle.

We appreciate your prompt attention to this matter.

Sincerely,

Mitsubishi Motors North America, Inc.

C0803MXX