

July 30, 2008

RE: Recall P045 - Rotary Coupler Wiring Fracture Vehicles Affected: Land Rover LR3 and Range Rover Sport Model Year: 2005 - 2006

Dear Land Rover Owner,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Land Rover has decided that a defect which relates to motor vehicle safety exists in certain 2005-2006 model year LR3 and 2006 model year Range Rover Sport vehicles. Your vehicle is part of this Recall action.

What is the concern?

Through ongoing quality data analysis, Land Rover has identified a concern on a number of 2005 - 2006 model year LR3 and 2006 model year Range Rover Sport vehicles built between November 2004 & December 2005 where the supplementary restraints system (SRS) warning light may illuminate.

The wiring that connects the rotary coupler to the driver's air bag module may fracture leading to an intermittent open circuit as a result of relative motion between the rotary coupler and the steering wheel hub. The SRS warning lamp will illuminate when circuit high resistance is detected by the supplementary restraints system. In the event of a collision of sufficient severity, the driver's airbag may not deploy correctly, increasing the risk of injuries to the driver.

Vehicle safety for normal use is not compromised. The SRS is, as its name suggests, supplementary. The primary safety system is the correct use of the seat belts. The SRS is only called into operation when there is a collision of sufficient severity. This condition is unique to the driver's airbag; no other aspect of the SRS is impacted. The SRS warning lamp notifies the driver of a potential concern with the SRS and the driver is strongly advised to seek Retailer assistance should the SRS or any other warning lamp be illuminated. All vehicle occupants should use the seat belts fitted or approved child restraints in the case of babies and younger children.

What will Land Rover and your Land Rover Retailer do?

An authorized Land Rover Retailer will perform a modification to improve the alignment of the steering column switch mounting platform and to provide assured clearance between the cowl and the rotary coupler face. Retailers will also be instructed to inspect the rotary coupler's drive peg sleeve and, if necessary, replace with the latest ribbed design. The work will be carried out free of charge.

What should you do?

Please contact your Retailer at your earliest convenience to schedule an appointment to have Recall P045 completed on your vehicle.

How long will it take?

The repair process should take no longer than half an hour, although your vehicle may be required for a longer time due to service scheduling requirements.

Attention Leasing Agencies:

Federal regulations require that you forward this Recall notification to the lessee within TEN days.

Moved or no longer own a Land Rover?

If you are no longer the owner of this vehicle, Land Rover would greatly appreciate the name and address of the new owner (if known); please fill out and return the enclosed return postage-paid card.

Jaguar Land Rover North America, LLC 555 MacArthur Boulevard Mahwah, NJ 07430 Telephone: 800-637-6837 Fax: 201-760-8514

What should you do if you have already paid to have this repair completed?

If you meet all the following requirements, you are eligible to receive reimbursement:

- 1. You own or have owned a 2005-2006 LR3 and / or a 2006 Range Rover Sport.
- 2. You have paid to replace the rotary coupler for this defect.
- 3. The repair was performed before July 31, 2008.
- 4. You have an original or legible copy of the paid repair order or invoice showing:
 - Description of the concern reported
 - Itemized parts and labor charges
 - · Vehicle model, year and the vehicle identification number
 - Repair date
 - Repair mileage
 - · Name and address of the authorized Land Rover Retailer or licensed repair shop
 - Your name and address at the time of the repair

If you have all of the above information, present it to the Service Manager at your authorized Land Rover Retailer and they will arrange reimbursement of your claim. Please ensure that you retain copies of all of the paperwork supporting this claim.

If you have concerns

If you experience any problems getting your vehicle repaired promptly and without charge, please contact the Service Manager at your authorized Land Rover Retailer for assistance.

If you have any queries or concerns that your local Retailer cannot address, please contact the Land Rover Customer Relationship Center at 800-637-6837, Option 9, and one of our representatives will be happy to assist you.

This Recall action is being undertaken in accordance with the legislative or industry requirements concerning vehicle problems. The authorities will closely monitor the response rate of this Recall Action.

Should you have the need to contact Land Rover by mail, please use the following address:

Jaguar Land Rover North America, LLC ATTN: Customer Relationship Center 555 MacArthur Blvd Mahwah, NJ 07430 - 2327

What should you do if you have further questions?

Should you have any questions regarding this Recall or need assistance in locating your nearest authorized Land Rover Retailer, please contact the Land Rover Customer Relationship Center at:

o 800-637-6837, Option 9

You can also contact Land Rover by e-mail: Visit the web site <u>www.landroverusa.com</u> and send an email from the 'Contact Us' section located within the 'Company' tab.

If you are having difficulty getting your vehicle repaired in a reasonable time or without charge, you may write to the National Highway Traffic Safety Administration at:

Administrator, National Highway Traffic Safety Administration 1200 New Jersey Avenue, SE Washington, D.C. 20590

You may also call the toll-free Vehicle Safety Hotline at 888-327-4236 (TTY: 800-424-9153), or log on to www.safercar.gov to submit a complaint electronically.

We appreciate your confidence in our product and wish to do everything we can to retain that confidence. We ask that you please treat this matter with the urgency it requires. Land Rover regrets any inconvenience this Recall may cause and thanks you for your co-operation.

Sincerely

Sphit

Stephanie P. Lutz Customer Satisfaction Manager

IMPORTANT SAFETY INFORMATION ENCLOSED - P045

SORTED CLASS MAIL POSTAGE	POSTAGE PAID	NT NO. 348 NL OAK, MI
PRI-TSRI-	U.S.	PERN R0YJ



Jaguar Land Raver North America, LLC 555 MicuMillur Bonevard Kohwah New Insc. 07430