

AFFECTED VEHICLES

MODELS: 2005-2007 GALANT
2005-2007 ENDEAVOR
2006-2007 ECLIPSE
2007 ECLIPSE SPYDER

Date: September, 2008

Dear Mitsubishi Owner,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Reason For Notice: Mitsubishi Motors North America, Inc. (MMNA) has decided that a defect that relates to vehicle safety exists in certain affected vehicles listed above. A bracket that secures the left side of fuel tank may have been improperly formed during the metal stamping process. If improperly formed, the fuel tank may become dislodged and drop down in a severe collision. Should this occur, there is a potential for fuel to spill from the fuel tank. Fuel in the presence of an ignition source could result in a fire.

What you should do: Please contact your Authorized Mitsubishi Dealer to schedule an appointment to have the fuel tank bracket inspected on your vehicle, free of charge. When you bring your vehicle in, please show the dealer this letter. (If you misplace this letter, the dealer will still inspect your vehicle and repair if necessary, free of charge.) To speed up the process and to make the repair easier for the dealer to perform, please have no more than ¼ tank of fuel in the vehicle upon arrival for your appointment, and clear the back seat of any personal items.

What your dealer will do: The dealership will inspect the fuel tank bracket to determine if it is properly formed. If they find the bracket improperly formed, they will install a repair parts kit to repair and reinforce the fuel tank bracket.

How long will it take? The time needed for the inspection is 30 minutes however if repairs are required it will take approximately 2½ hours. The dealer may need your vehicle for a longer period of time due to service scheduling issues, but every effort will be made to minimize your inconvenience.

If you have any trouble having your vehicle repaired promptly and at no charge, please inform us by calling the Mitsubishi Customer Relations Department at **888-648-7820**.

Hours: Monday through Friday 6 a.m. to 5 p.m. (Pacific Time)

If, after contacting Mitsubishi Customer Relations, you still have a problem having this repair made promptly and without charge, write to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue SE, Washington, D.C. 20590, or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153), or go to <http://www.safercar.gov>.

If you have already encountered a problem regarding the above and have paid for the repair, you may send your original receipts and/or other adequate proof of payment to the following address for reimbursement:
Mitsubishi Customer Relations Department, P.O. Box 6400, Cypress, CA 90630-0064

Notice to Lessors: If you are a lessor of five or more leased vehicles as of the date of this letter, you have an obligation under federal law, (49 CFR Part 577), to provide the lessee of the above referenced vehicle with a copy of this letter by first class mail within ten days of receipt. Further, you must maintain a record, which identifies the lessee to whom you sent a copy of this letter, the date you sent it, and the vehicle identification number (VIN) of the subject vehicle.

We appreciate your prompt attention to this matter.

Sincerely,

Mitsubishi Motors North America, Inc.

C0805KXX