

Daimler Trucks North America LLC

Daimler Trucks North America LLC
P.O. Box 4090
Portland, OR 97208-4090
800.547.0712 Phone
503.745.9009 Fax

May 2008
FL521AB
NHTSA #08V-029
REMINDER NOTICE

Subject: Air Disk Brake Caliper Bolts

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. This notice is also sent in accordance with the Canadian Motor Vehicles Safety Act.

Daimler Trucks North America LLC, on behalf of its Freightliner Trucks Division and its wholly owned subsidiary, Freightliner Custom Chassis Corporation, has decided that a defect which relates to motor vehicle safety exists on specific Freightliner Argosy, Business Class M2, Cascadia, Century Class S/T, and Columbia vehicles and Freightliner Custom Chassis XC-R motor home chassis manufactured between January 1, 2007, and November 19, 2007, with air disk brakes.

Standard fasteners may have been used rather than metric fasteners to attach the brake caliper to the brake anchor plate. Incorrect fasteners may not provide adequate clamping force between the brake caliper and the brake anchor plate. This may reduce brake effectiveness, resulting in a possible vehicle crash.

Potentially affected brake caliper bolts will be inspected. The bolts will be replaced on any caliper that has one or more incorrect bolts.

This is a follow up to a previous communication. Our records indicate that your vehicle has not yet had this recall performed. Please make arrangement to have this repair done as soon as possible. If it has been completed, please disregard this letter.

Parts are now available for authorized dealers to order. Contact your authorized dealer to arrange to have the recall completed and to ensure that parts are available at the dealership. Please note, in rare cases, additional parts may need to be ordered after the vehicle is inspected. To locate a dealer, search online at www.FreightlinerTrucks.com or contact the Warranty Campaigns Department for assistance.

When you contact your dealer, refer to campaign number **FL521AB**. Once kit(s) are received at the dealership, the recall will take between approximately half an hour and an hour (rarely up to two and a half hours), depending on the work needed, and will be performed at no charge to you.

IMPORTANT: When the Recall has been completed, please ensure that a label has been affixed to your vehicle referencing **FL521AB**.

If you do not own the vehicle that corresponds to the identification number(s) which appears on the Recall Notification, please return the notification to the Warranty Campaigns Department with any information you can furnish that will assist us in locating the present owner. If you have leased this vehicle, Federal law requires that you forward this notice to the lessee within 10 days. If you are a subsequent stage manufacturer, Federal law requires that you forward this notice to your distributors and retail outlets within five working days.

If you are not able to have the defect remedied without charge and within a reasonable time, which is not longer than 60 days after you tender the vehicle for repair, please contact the Warranty Campaigns Department at (800) 547-0712, 7:00 a.m. to 4:00 p.m. Pacific Time, Monday through Friday, e-mail address WarrantyCampaigns@freightliner.com, or the Customer Assistance Center at (800) FTL-HELP or (800) STL-HELP, after normal business hours. You may also wish to submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE., Washington, DC 20590; or call the Vehicle Safety Hotline at (888) 327-4236 (TTY: 800-424-9153); or to <http://www.safercar.gov>. If your vehicle is involved in the Canadian portion, you may wish to notify Transport Canada, ASFAD, Place de Ville Tower C, 330 Sparks Street, Ottawa, ON K1A 0N5, or phone (800) 333-0510.

We regret any inconvenience this action may cause but feel certain you understand our interest in motor vehicle safety.

WARRANTY CAMPAIGNS DEPARTMENT

Enclosure