

May 4, 2009

NHTSA

1200 New Jersey Ave SE Washington, DC 20590 Attn.: Assoc. Admin. for Enforcement

To Whom It May Concern:

Attached you will find documents mailed to dealers about the following Mazda campaigns:

- > Recall 4707H 1998-2002 Mazda B-Series Cruise Control Deactivation Switch
- > Recall 5409D 2010 Mazda3 Emission Harness
- ➤ MSP23 2010 Mazda3 Malfunction Indicator Light Illumination (DTC P2183, P0111)

Thank you,

Gabriela Laur

Program Manager, Recalls and Compliance Mazda North American Operations (949) 442-6590

glaur@mazdausa.com



April 14, 2009

2010 Mazda3 Upcoming Service Campaign

Dear Mazda Service Manager,

The parts in this shipment are for an upcoming 2010 Mazda3 service campaign. These parts are to address most of the affected units in your dealer inventory. You will receive more information about this service campaign as soon as it becomes available.

Following is an estimated timeline:

- 4/15/09: List of affected vehicles in dealer inventory available on MS3
- 4/15/09: Repair procedure available on MS3
- 4/17/09: Warranty Information available on MS3 for claim submission

Additional parts will be available at your facing PDC late next week. You will be able to order these parts using the DAG website.

If you have any questions please contact Gaby Laur at 949-442-6590 or e-mail glaur@mazdausa.com

Sincerely,

Mazda Technical Services

8

Mazda North American Operations

Date:	Information Tuesday, April 14, 2009
IENT	
Dept: Phone:	Service and Parts Information 949-442-6567
	a UPS Next Day Shipment of 2010 er immediately.
Concur:	Julie Ireland
	Dept: Phone: ers will receive ervice Manage

Communication

On **04-15-09 or 4-16-09**, Parts Managers will receive repair parts for **2010 MAZDA3** vehicles in dealer inventory. These parts will arrive with the UPS shipment.

The UPS Next Day Delivery box will be clearly labeled to **Deliver Immediately to the Service Manager.**

The attached Dealer Email will be released 4-13-09 and contains the contents of this shipment and further details.

Should you have any questions, please contact Gaby Laur at 949-442-6590 or Darrel Chin at 949-442-6525.

Kiyoshi Yagi Director, Technical Service Mazda North American Operations



Addressees - Check appropriate division, department, region or position

<u>MNAO</u>		REGION OTHER (include GAL listing or email)			
Executive Committee (Executive Committee)		Regional General Manager (ALLRGM)		Port Managers (All Port Mgrs)	
Executive Committee Assistants (EC Asst)		Executive Assistants (Admin-Exec Asst)		Port Employees (All Ports)	
Sales Operations Division		Region Sales Managers (RSM)		Other: Kiyoshi Yagi	⊠
Sales		Sales Operations Manager (SOM)		Other: Yasou Kunita	⊠
Fleet		District Operations Manager (ALL DOM)		Other:	
Distribution		District Sales Manager (ALLDM)		Other:	
Logistics (Logistics Department)		All Sales Operations Specialists		Other:	
Dealer Operations Division		Region Customer Service & Parts Manager (RCSPM/formerly RSPM)	⊠	Other:	
Dealer Profitability		Service Field Operations Manager (SFOM)	Ø	Other:	
Retail Development		Parts Operations Manager (POM/formerly ASPM)	✓	Other:	
Customer Service & Parts Mgmt (CS&P mgmt)	⊠	District Service Manager (DSM)	⊠	Other:	
Customer Service & Parts Misc. (CS&P Misc)	⋈	Area Parts Manager (APM)	Ø	Other:	
Service & Parts Marketing (Svc & Parts Mkt)	⋈	Technical Operations Manager (TOM)	×	Other:	
L.I.D. (Corp. Only)		Technical Specialist	×	Other:	
Accessory		Technical Training		Other:	
Warranty & Service Assurance		Cust Satisfaction Mgr (CSM)		Other:	
Cust Satisfaction & Loyalty	⊠	Fixed Ops Process Managers		Other:	
CAC Management	⊠	Sales Process Manager (Sales Pro Mgr)		Other:	
Customer Mediation Department		Dealer Development Managers (DDM)		Other:	
Dealer Affairs (DLR Affairs)		Business Development Mgrs (BDM)	Ò	Other:	
Marketing Operations Division		Market Rep. Managers (Mkt Rep Mgr)		Other:	
Product Planning (Product Planning)		Market Rep. Coordinator/Specialist		Other:	
Audit (Internal Audit)		Sales Planning Manager (ALLSPM)		Other:	
Legal		Sales Planning Coordinator/Specialist		Other:	
Finance Division (Finance)		Marketing Manager (Marketing Mgr)		Other:	
Human Resources (HR)		Marketing Coordinator/Specialist		Other:	
Public Relations (Public Affairs)		Midwest Region (All Midwest)		Other:	
Dealer Assistance Group-All	⊠	Northeast Region (All Northeast)		Other:	
Dealer Assistance Group-Corp		Southeast Region (All Southeast)		Other:	
Dealer Assistance Group-Field		Western Region (All Western Region)		Other:	
Employees Only – (Corp)		Gulf Region (All Gulf)		Other:	
Employees Only – (All MNAO)		McGaw (All McGaw)	⊠	Other:	
IT- Helpdesk		Mazda Parts Operation Guide		Other:	



ATTENTION: PARTS MANAGERS

On **April 15th or 16th** your dealership will receive repair parts for **2010 MAZDA3** vehicles in dealer inventory. These parts will arrive with your UPS shipment.

The UPS Next Day Delivery box will be clearly labeled to **Deliver Immediately to the Service Manager**.

The content of the shipment is as follows:

PART NUMBER	DESCRIPTION	NOTE
0000-99-HRK-AT	Harness Repair ATX	Clip and Spacer
0000-99-HRK-MT	Harness Repair MTX	Clip and Pad
0000-99-TAPE	Butyl Tape	

NOTE: The box also contains a timeline providing dates for all future activity related to this repair.

Service Managers and dealer personnel will receive additional information regarding this repair on MS3 starting 04-15-09.

Should you have any questions regarding this message, please contact Gaby Laur at 949-442-6590 or Darrel Chin at 949-442-6525.

Thanks you for your prompt action and support.

Kiyoshi Yagi Director, Technical Service Mazda North American Operations



ATTENTION: PARTS MANAGERS

On **April 15th or 16th** your dealership will receive repair parts for **2010 MAZDA3** vehicles in dealer inventory. These parts will arrive with your UPS shipment.

The UPS Next Day Delivery box will be clearly labeled to **Deliver Immediately to the Service Manager**.

The content of the shipment is as follows:

PART NUMBER	DESCRIPTION	NOTE
0000-99-HRK-AT	Harness Repair ATX	Clip and Spacer
0000-99-HRK-MT	Harness Repair MTX	Clip and Pad
0000-99-TAPE	Butyl Tape	

NOTE: The box also contains a timeline providing dates for all future activity related to this repair.

Service Managers and dealer personnel will receive additional information regarding this repair on MS3 starting 04-15-09.

Should you have any questions regarding this message, please contact Gaby Laur at 949-442-6590 or Darrel Chin at 949-442-6525.

Thanks you for your prompt action and support.

Kiyoshi Yagi Director, Technical Service Mazda North American Operations



Mazda North American Operations

Julie Ireland

Electronic Field Communication eFC Number: eFC-A-09-00002	Date:	Wednesday, April 15, 20	Action 009
Subject: STOP DELIVERY/HOLD - 201 SAFETY RECALL 5409D.	0 MAZDA3 E	MISSION HARNESS VC	LUNTARY
Originating Name: Gabriela Laur Email ID: glaur@mazdausa.com	Dept: Phone:	TSD 949-442-6590	
Summary: Stop Delivery/Hold for 2010 Mazda through April 10, 2009 due to voluntary safety			7, 2008
See Also eFC Number(s): eFC-I-09-00022,eFC-I-09-00022a,	, ,		
Dealer Communication: Yes ⊠			·
Additional Contacts:			

Concur:

Communication:

Sales Operations:

Fixed Operations:

eFC Type:

This is to inform you of a Stop Delivery notification for certain 2010 Mazda3 vehicles due out today.

The attached Dealer Email will be sent to dealers on Wednesday, April 15, 2009. Also attached is a copy of the letter that was included in the 2010 Mazda3 Parts shipments that arrived at dealerships 4/15/09 & 4/16/09.

Action Required:

Beginning today, April 15 2009, certain 2010 Mazda3 vehicles produced from October 7, 2008 through April 10, 2009 in dealer inventory must be inspected and repaired prior to customer delivery.

Due Date: This action is effective immediately.

 \boxtimes

 \boxtimes

If you have any questions, please contact Gaby Laur at (949) 442-6590 or glaur@mazdausa.com.



Addressees – Check appropriate positions, regions or activity

MNAO	REGION			<u>OTHER</u> (include GAL listing or email)	
Executive Committee (Executive Committee)	X	Regional General Manager (ALLRGM)	Ø	Port Managers (All Port Mgrs)	×
Executive Committee Assistants (EC Asst)		Executive Assistants (Admin-Exec Asst)		Port Employees (All Ports)	
Sales Operations Division	×	Region Sales Managers (RSM)	⊠	Other: Charles Kim	⊠
Sales		Sales Operations Manager (SOM)	Ø	Other: Dan Ryan	⊠
Fleet		District Operations Manager (ALL DOM)	⊠	Other: Rob Murdoch (MCI)	⊠
Distribution		District Sales Manager (ALLDM)	Ø	Other: Francisco Rangel (MMdM)	⊠
Logistics (Logistics Department)		All Sales Operations Specialists	☒	Other: Don MacPhee	⊠
Dealer Operations Division	Į.	Region Customer Service & Parts Manager (RCSPM/formerly RSPM)	×	Other: Rob Fecher	×
Dealer Profitability		Service Field Operations Manager (SFOM)	Ø	Other: Ryan Kita	⊠
Retail Development		Parts Operations Manager (POM/formerly ASPM)	Ø	Other: Rob Milne	⊠
Customer Service & Parts Mgmt (CS&P mgmt)	☒	District Service Manager (DSM)	Ø	Other:	
Customer Service & Parts Misc. (CS&P Misc)		Area Parts Manager (APM)	×	Other:	
Service & Parts Marketing (Svc & Parts Mkt)		Technical Operations Manager (TOM)	Ø	Other:	
L.I.D. (Corp. Only)	\Box	Technical Specialist	×	Other:	
Accessory		Technical Training	×	Other:	
Warranty & Service Assurance	×	Cust Satisfaction Mgr (CSM)	⊠	Other:	
Cust Satisfaction & Loyalty		Fixed Ops Process Managers	×	Other:	
CAC Management	⊠	Sales Process Manager (Sales Pro Mgr)	Ø	Other:	
Customer Mediation Department		Dealer Development Managers (DDM)		Other:	
Dealer Affairs (DLR Affairs)	Ø	Business Development Mgrs (BDM)		Other:	
Marketing Operations Division		Market Rep. Managers (Mkt Rep Mgr)	ı.	Other:	
Product Planning (Product Planning)		Market Rep. Coordinator/Specialist		Other:	
Audit (Internal Audit)		Sales Planning Manager (ALLSPM)	Ø	Other:	
Legal	⊠	Sales Planning Coordinator/Specialist	Ø	Other:	
Finance Division (Finance)		Marketing Manager (Marketing Mgr)	· 🗖:	Other:	
Human Resources (HR)		Marketing Coordinator/Specialist		Other:	
Public Relations (Public Affairs)	⊠	Midwest Region (All Midwest)		Other:	
Dealer Assistance Group-All	⊠	Northeast Region (All Northeast)		Other:	
Dealer Assistance Group-Corp		Southeast Region (All Southeast)		Other:	
Dealer Assistance Group-Field		Western Region (All Western Region)		Other:	
Employees Only – (Corp)		Gulf Region (All Gulf)		Other:	
Employees Only – (All MNAO)		McGaw (All McGaw)	Ø	Other:	
IT- Helpdesk		Mazda Parts Operation Guide		Other:	

Action eFC Rev10.17.08 Pg. 2 of 2

MAZDA DEALER EMAIL 2009/04/2007

Dear Mazda Dealer,

We regret to inform you that retail delivery of certain 2010 Mazda3 vehicles in your inventory must immediately be suspended. Mazda Motor Corporation has decided that a defect which relates to motor vehicle safety exists in certain 2010 Mazda3 vehicles produced from October 7, 2008 through April 10, 2009.

On certain 2010 Mazda3 vehicles, the clearance between the emission harness and the housing of the starter motor may be insufficient. Due to this, the covering of the harness may be damaged from vibration during operation, resulting in a short-circuit between the harness wires and the starter housing. This condition could cause an engine control malfunction and/or poor shift quality. In the worst case, the main fuse may blow out, causing the engine to stall and an inability to restart, increasing the risk of a crash.

Action Required:

Beginning today, April 15, 2009, certain 2010 Mazda3 vehicles produced from October 7, 2008 through April 15, 2009 in your inventory must be inspected and repaired prior to customer delivery. Delivering subject vehicles without performing the necessary inspection and/or repair is prohibited. Failure to perform applicable recalls before delivery can result in extensive dealer fines and penalties from the Federal Government.

SUBJECT VEHICLES

Niodel	MN#Range	(Emild Date Range
2010 Mazda3	JM1 BL**** A1 100120 – 148098	From October 7. 2008
		through April 10, 2009

Note: The asterisk symbol "*" can be any letter or number.

PLEASE NOTE: Many of these vehicles have already been repaired at the factory and will be reworked at the ports as well. A list of vehicles in dealer inventory will be available on MS3 later today.

The Repair Procedure will be available on MS3 later today.

A previous dealer email communication was sent out to you yesterday, April 14th, regarding a parts shipment for 2010 Mazda3. You should receive parts to address most of the vehicles in your inventory today April 15, or tomorrow April 16.

Due Date: This action is effective immediately.

Once 2010 Mazda3 vehicles in dealer inventory have been inspected and repaired, customer delivery may resume. Mazda will initiate the recall campaign to address retailed vehicles on May 8, 2009. We apologize for any inconvenience that this stop delivery may cause, and we appreciate your cooperation in the interest of safety and customer satisfaction. If you have any questions, please contact your District Service Manager.

Sincerely,

Eric Johnston

Sun K. Johnto

Vice President, Sales and Field Operations

Mazda North American Operations



Attention Mazda Service and Parts Managers:

Mazda Motor Corporation has decided that a defect which relates to motor vehicle safety exists in certain 2010 Mazda3 vehicles equipped with LF or L5 engine and produced from October 7, 2008 through April 10, 2009.

On certain 2010 Mazda3 vehicles, the clearance between the emission harness and the housing of the starter motor may be insufficient. Due to this, the covering of the harness may be damaged from vibration during operation, resulting in a short-circuit between the harness wires and the starter housing. This condition could cause an engine control malfunction and/or poor shift quality. In the worst case, the main fuse may blow out, causing the engine to stall and an inability to restart, increasing the risk of a crash.

TIMING

Dealer mailing date: April 24, 2009

Owner mailing date: May 6, 2009

SUBJECT VEHICLES

Model"	VIN Range	Build Date Range
2010 Mazda3 LF, L5 Engine	1 IK/17 RT """" AT TISHTON _ 1/18NU8	From October 7, 2008 through April 10, 2009

Note: The asterisk symbol "*" can be any letter or number.

PLEASE NOTE: Many of these vehicles have already been repaired at the factory and at the ports as well.

PARTS INFORMATION

Description	Part Number :	generality :	Notes
Automatic Transmission Parts Set	0000-99-HRK -AT	1 set/vehicle	Includes: -25mm protector clip (1 pc) - Spacer (1 pc)
Manual Transmission Parts Set	0000-99-HRK -MT	1 set/vehicle	Includes: -22mm protector clip (1 pc) - Rubber pad (1 pc)
Butyl Tape	0000-99-TAPE	As needed	3/4in x 1.5in x 0.04in
Campaign Label	9999-95-065A-05	1=50 labels	Obtain in MStore (no charge)

Please note the space after the "K" in both the A/T and M/T part numbers.

You may have received a series of parts pre-shipments to complete repairs to your dealer inventory. For those of you that have received pre-shipments, you will be automatically billed via debit memo with a reference ID of Recall 5409D Pre-Shipment.

Parts will be available for ordering at Olive Branch on Friday April 24, 2009.

PARTS ORDERING

Please follow these instructions to order additional parts:

Orders will only be accepted through the Dealer Assistance Group (DAG) website "eMail Inquiries" page as follows:

- Go to the Dealer Assistance Group web page, or click on the link below: https://portal.mazdausa.com/dealershome/service parts/dag/index.htm
- Click on "eMail Inquiries" at the top of the screen 2.
- Click on "Corporate Dealer Assistance Group"
 Fill in the following required fields:

 First name 3.
- 4.

 - Last name
 - Phone Number
 - Email Address
 - MNAO Sales Order: (enter the PO number you would like to use for the order or simply enter N/A)
 - Part Number
 - Techline Ref #: (Leave Blank)
 - Comments: Enter the VIN(s) of the vehicle(s) requiring the part(s). VIN is required for the order to be placed. Also, if you require more than one part number, enter the additional part numbers here.

Once all the fields have been entered, click on the "Submit" button. This sends an email to DAG. Your order will be placed as a CSO order with the freight charge waived, and you will be contacted with confirmation of the order and the order number. You do not need to call DAG once this email request has been sent.

For parts ordering assistance, contact the Corporate Dealer Assistance Group at (877) 727-6626. option 2.

PARTS PRICING

Parts pricing can be found in eMDCS on the parts order screen. NOTE: Although this screen will show pricing, parts will only be orderable through the Dealer Assistance Group Website.

For your convenience, pricing is also listed below:

Part Number	. Dealer Price	Retail Price	Warrianty Price
0000-99-HRK -AT	\$1.60	\$2.67	\$2.24
0000-99-HRK -MT	\$1.60	\$2.67	\$2.24
0000-99-TAPE	\$0.50	\$0.83	\$0.70

WARRANTY INFORMATION

ARRANTI INFORMATION	Inspection & Glip Installation	Inspection, Clip Installation & Harness Taping
Warranty Type Code	R	R
Symptom Code	99	99
Damage Code	99	99
Process Number	A0909B	A0909B
Part Number Main Cause / Qty	7777-SP-E14 / 0	7777-SP-E14 / 0

	A/T vehicles: 0000-99-HRK -AT / 1	A/T vehicles: 0000-99-HRK -AT / 1 0000-99-TAPE / 1
Related Part Number / Qty	M/T vehicles: 0000-99-HRK -MT / 1	M/T vehicles: 0000-99-HRK -MT / 1
Labor Operation Code	XXE1MARX	0000-99-TAPE / 1 XXE1MBRX
Labor Hours	0.3 hrs	0.4 hrs

Inspection and repair procedures are attached and are available on the Mazda Service Support System (MS3) website and on eMDCS using Campaign Inquiry by entering the recall number. Warranty Vehicle Inquiry will not display affected vehicles until after customer notification on May 6.

For technical assistance, call the Technical Assistance Hotline at (888) 832-8477.

For warranty questions, contact the Corporate Dealer Assistance Group at (877) 727-6626 Option 3.

Please make certain that the appropriate personnel in your dealership are aware of these resources and are familiar with the details of this recall before responding to customer inquiries. If you have any questions, please contact your region manager or DSM.

We apologize for any inconvenience this recall may cause you and your customers. Your understanding and support in carrying out this campaign are greatly appreciated.


in estimation of the second experimental and the configuration of the second experimental and the configuration of the configuration of

Mazda Technical Services

A. VEHICLE INSPECTION PROCEDURE

- 1. Verify that the vehicle is within the following ranges:
 - Year Range (2010) Model (Mazda3) Produced (October 7, 2008-April 10, 2009)
 - VIN Range: JM1 BL**** A1 100120-148098
 - If the vehicle is within the above range, proceed to step 2.
 - If the vehicle is not within the above range, return the vehicle to the customer or inventory.
- 2. Perform a Warranty Vehicle Inquiry using your eMDCS System and inspect vehicle for a Campaign Label **5409D** attached to the vehicle's hood or bulkhead. Refer to eMDCS System Warranty Vehicle Inquiry Results table below.

NOTE: Verify Recall number as the vehicle may have multiple Recalls.




eMDCS System - Warranty Vehicle Inquiry Results

If eMDCS displays:	Campaign Label is:	Action to perform:
5409D OPEN	Present	Contact the Mazda Corporate Dealer Assistance Group at (877) 727-6626 to update vehicle history.
	Not present	Proceed to "B. REPAIR PROCEDURE".
5409D CLOSED	Present	Return vehicle to inventory or customer.
	Not present	Proceed to "C. CAMPAIGN LABEL INSTALLATION". Complete a label and apply to vehicle's bulkhead.
5409D is not displayed	Does not apply	Recall does not apply to this vehicle. Return vehicle to inventory or customer.

B. REPAIR PROCEDURE

CONCERN

The emission harness may contact the engine starter housing (A) causing damage to the harness, and in some rare cases, the damage may cause the emission harness wiring to short to ground. This shorting to ground will cause the MIL to illuminate and / or driveability concerns.



VIEWED FROM UNDERNEATH THE VEHICLE (LOOKING UP) WITH UNDERCOVER REMOVED


NECESSARY PARTS

The installation procedure and parts differ depending on the type of transmission the vehicle is equipped with. Please verify you have the correct parts for the transmission type, and then follow the proper installation instructions


AUTOMATIC TRANSMISSION PARTS SET NUMBER 0000-99-HRKAT		MANUAL TRANSMISSION PARTS SET NUMBER 0000-99-HRK -MT	
(1) 25MM PROT	ECTOR CLIP	(1) 22MM PROTECTOR CLIP	
(1) SPACER		(1) RUBBER PAD	
54090ba	AT (25)	MT	

PROCEDURE "A" - HARNESS INSPECTION

- 1. Lift vehicle on hoist to access the undercover.
- 2. Remove the fasteners (A) and bolts (B) to remove the undercover from the vehicle.




- 3. Carefully inspect the harness (A) in the area closest to the engine starter housing (B). DOES THE HARNESS TOUCH THE ENGINE STARTER HOUSING?
 - YES Go to next step.
 - NO Go to PROCEDURE "B".



ATTACHMENT II 5409D

- 4. Inspect the vehicle's harness and compare to the illustration below to determine procedure.
 - Starter contacts area of corrugated sheath (A) Go to PROCEDURE "B".
 - Starter contacts area of tape (B) with no corrugated sheath Go to PROCEDURE "C".



PROCEDURE "B" - EMISSION HARNESS PROTECTOR CLIP / SPACER INSTALLATION


NOTE: The installation procedure and parts differ depending on the type of transmission the vehicle is equipped with. Please verify you have the correct parts for the transmission type, and then follow the proper installation instructions.

VEHICLES WITH AUTOMATIC TRANSMISSIONS

NOTE: Some harnesses may be routed very close to the starter housing which could make the following procedures difficult to perform. Refer to PROCEDURE "D" – INCREASING WORK SPACE.

- 1. Install the spacer (A) on the emission harness by positioning it over harness in area shown, then squeeze together until tight.
- 2. Install the protector clip (B) on the emission harness by positioning it on the harness as shown, then squeeze the clip together until it snaps.


IMPORTANT: MAKE SURE TO PLACE PROTECTOR CLIP WITH THE FLAT SIDE SHOWING "25" CLOSEST TO THE STARTER CONTACT AREA (C).



3. Refasten the lower harness anchor if unfastened in PROCEDURE "D" - INCREASING WORK SPACE.

VEHICLES WITH MANUAL TRANSMISSIONS


1. Add the rubber pad to the protector clip as shown.



Barbara Barbara Barbara

2. Install the protector clip on the emission harness by positioning it on the harness at the point shown (A), then squeeze the clip together until it snaps.

IMPORTANT: MAKE SURE TO PLACE PROTECTOR CLIP WITH THE FLAT SIDE SHOWING "22" CLOSEST TO THE STARTER CONTACT AREA (B).



PROCEDURE "C" - WATERPROOFING HARNESS

NOTE: This procedure prevents water entry if harness tape was damaged by engine starter housing contact.


IMPORTANT: IF VEHICLE IS EXPERIENCING MILS, BLOWN FUSES OR DRIVEABILITY CONCERNS
THE EMISSION HARNESS WIRING MAY BE WORN THROUGH TO BARE COPPER CONDUCTER WIRE AND TOUCHING THE ENGINE STARTER HOUSING.

IS THE VEHICLE CURRENTLY EXPERIENCING MILS, DRIVEABILITY CONCERNS, BLOWN FUSES ETC ..?


- YES Carefully inspect the emission harness for damage resulting in bare copper wire contact with engine starter housing. If you confirm wires are shorted, contact the NATIONAL TECHNICAL ASSISTANCE HOT-LINE for further instructions.
- NO Go to step 1.

NOTE: Some harnesses may be routed very close to the starter housing which could make the following procedures difficult to perform. Refer to PROCEDURE "D" – INCREASING WORK SPACE.


1. Note the area of harness at the engine starter housing contact point (A) to be waterproofed as shown (B).




2. Apply butyl tape in this area by following these steps.




- a. Remove the backing paper of one side of the butyl tape (PN 0000-99-TAPE).
- b. Apply butyl tape to contact area of the emission harness.
- c. Remove the remaining paper backing of the butyl tape.



3. Using 35 inches of electrical tape, wrap the harness to completely cover the butyl taped area as shown.



TIP: The work space for taping the harness is limited and may be difficult using a full roll of tape. Precutting 35 inches of tape, then wrapping it onto a 9mm or 10mm socket (A), allows easier application of the tape to the harness.




4. Perform PROCEDURE "B" - INSTALL EMISSION HARNESS PROTECTOR CLIPS.

PROCEDURE "D" - INCREASING WORK SPACE

NOTE: There may be limited space to perform some procedures, especially on vehicles with an automatic transmissions. More work space can be obtained by temporarily releasing the lower harness anchor and moving the harness.

- 1. Release the anchor (A) of the main emission harness.
- 2. Pull the harness away from the AT Shifter cable bracket (B) to gain more work space.



C. CAMPAIGN LABEL INSTALLATION

1. Fill out a blue "Campaign Label" (9999-95-065A-06) with Campaign No: "5409D", your dealer code, today's date, and affix it to the vehicle's bulkhead or hood as shown in "A. VEHICLE INSPECTION PROCEDURE".


CAMPAIG	N NO:		
DEALER (CODE:_		
DATE:	an Commence La	//	**************************************

2. Return vehicle to customer.

A. VEHICLE INSPECTION PROCEDURE

- 1. Verify that the vehicle is within the following ranges:
 - Year Range (2010) Model (Mazda3) Produced (October 7, 2008-April 10, 2009)
 - VIN Range: JM1 BL**** A1 100120-148098
 - If the vehicle is within the above range, proceed to step 2.
 - If the vehicle is not within the above range, return the vehicle to the customer or inventory.
- Perform a Warranty Vehicle Inquiry using your eMDCS System and inspect vehicle for a Campaign Label 5409D attached to the vehicle's hood or bulkhead. Refer to eMDCS System - Warranty Vehicle Inquiry Results table below.

NOTE: Verify Recall number as the vehicle may have multiple Recalls.




eMDCS System - Warranty Vehicle Inquiry Results

If eMDCS displays:	Campaign Label is:	Action to perform:
5409D OPEN	Present	Contact the Mazda Corporate Dealer Assistance Group at (877) 727-6626 to update vehicle history.
	Not present	Proceed to "B. REPAIR PROCEDURE".
5409D CLOSED	Present	Return vehicle to inventory or customer.
	Not present	Proceed to "C. CAMPAIGN LABEL INSTALLATION". Complete a label and apply to vehicle's bulkhead.
5409D is not displayed	Does not apply	Recall does not apply to this vehicle. Return vehicle to inventory or customer.

B. REPAIR PROCEDURE

CONCERN


The emission harness may contact the engine starter housing (A) causing damage to the harness, and in some rare cases, the damage may cause the emission harness wiring to short to ground. This shorting to ground will cause the MIL to illuminate and / or driveability concerns.



VIEWED FROM UNDERNEATH THE VEHICLE (LOOKING UP) WITH UNDERCOVER REMOVED


NECESSARY PARTS

The installation procedure and parts differ depending on the type of transmission the vehicle is equipped with. Please verify you have the correct parts for the transmission type, and then follow the proper installation instructions.




PROCEDURE "A" - HARNESS INSPECTION

- 1. Lift vehicle on hoist to access the undercover.
- 2. Remove the fasteners (A) and bolts (B) to remove the undercover from the vehicle.




- 3. Carefully inspect the harness (A) in the area closest to the engine starter housing (B). DOES THE HARNESS TOUCH THE ENGINE STARTER HOUSING?
 - YES Go to next step.
 - NO Go to PROCEDURE "B".



ATTACHMENT II 5409D

- 4. Inspect the vehicle's harness and compare to the illustration below to determine procedure.
 - Starter contacts area of corrugated sheath (A) Go to PROCEDURE "B".
 - Starter contacts area of tape (B) with no corrugated sheath Go to PROCEDURE "C".



PROCEDURE "B" - EMISSION HARNESS PROTECTOR CLIP / SPACER INSTALLATION


NOTE: The installation procedure and parts differ depending on the type of transmission the vehicle is equipped with. Please verify you have the correct parts for the transmission type, and then follow the proper installation instructions.

VEHICLES WITH AUTOMATIC TRANSMISSIONS

NOTE: Some harnesses may be routed very close to the starter housing which could make the following procedures difficult to perform. Refer to PROCEDURE "D" – INCREASING WORK SPACE.

- 1. Install the spacer (A) on the emission harness by positioning it over harness in area shown, then squeeze together until tight.
- 2. Install the protector clip (B) on the emission harness by positioning it on the harness as shown, then squeeze the clip together until it snaps.


IMPORTANT: MAKE SURE TO PLACE PROTECTOR CLIP WITH THE FLAT SIDE SHOWING "25" CLOSEST TO THE STARTER CONTACT AREA (C).



3. Refasten the lower harness anchor if unfastened in PROCEDURE "D" - INCREASING WORK SPACE.

VEHICLES WITH MANUAL TRANSMISSIONS


1. Add the rubber pad to the protector clip as shown.



STR.

2. Install the protector clip on the emission harness by positioning it on the harness at the point shown (A), then squeeze the clip together until it snaps.

IMPORTANT: MAKE SURE TO PLACE PROTECTOR CLIP WITH THE FLAT SIDE SHOWING "22" CLOSEST TO THE STARTER CONTACT AREA (B).



PROCEDURE "C" - WATERPROOFING HARNESS

NOTE: This procedure prevents water entry if harness tape was damaged by engine starter housing contact.


IMPORTANT: IF VEHICLE IS EXPERIENCING MILS, BLOWN FUSES OR DRIVEABILITY CONCERNS
THE EMISSION HARNESS WIRING MAY BE WORN THROUGH TO BARE COPPER CONDUCTER WIRE AND TOUCHING THE ENGINE STARTER HOUSING.

IS THE VEHICLE CURRENTLY EXPERIENCING MILS, DRIVEABILITY CONCERNS, BLOWN FUSES ETC ..?


- YES Carefully inspect the emission harness for damage resulting in bare copper wire contact with engine starter housing. If you confirm wires are shorted, contact the NATIONAL TECHNICAL ASSISTANCE HOT-LINE for further instructions.
- NO Go to step 1.

NOTE: Some harnesses may be routed very close to the starter housing which could make the following procedures difficult to perform. Refer to PROCEDURE "D" – INCREASING WORK SPACE.


1. Note the area of harness at the engine starter housing contact point (A) to be waterproofed as shown (B).




2. Apply butyl tape in this area by following these steps.



- a. Remove the backing paper of one side of the butyl tape (PN 0000-99-TAPE).
- b. Apply butyl tape to contact area of the emission harness.
- c. Remove the remaining paper backing of the butyl tape.




3. Using 35 inches of electrical tape, wrap the harness to completely cover the butyl taped area as shown.



ATTACHMENT II 5409D

TIP: The work space for taping the harness is limited and may be difficult using a full roll of tape. Precutting 35 inches of tape, then wrapping it onto a 9mm or 10mm socket (A), allows easier application of the tape to the harness.




4. Perform PROCEDURE "B" – INSTALL EMISSION HARNESS PROTECTOR CLIPS.

PROCEDURE "D" - INCREASING WORK SPACE


NOTE: There may be limited space to perform some procedures, especially on vehicles with an automatic transmissions. More work space can be obtained by temporarily releasing the lower harness anchor and moving the harness.

- 1. Release the anchor (A) of the main emission harness.
- 2. Pull the harness away from the AT Shifter cable bracket (B) to gain more work space.



C. CAMPAIGN LABEL INSTALLATION

1. Fill out a blue "Campaign Label" (9999-95-065A-06) with Campaign No: "5409D", your dealer code, today's date, and affix it to the vehicle's bulkhead or hood as shown in "A. VEHICLE INSPECTION PROCEDURE".



A 4 11 4 1 1 1 1

· Company of the Com

2. Return vehicle to customer.