

DAIMLER

Daimler Trucks North America
Nasser Zamani
Senior Manager
Compliance and Regulatory Affairs

November 3, 2010

Dan Smith
Associate Administrator for Vehicle Safety
National Highway Traffic Safety Administration
1200 New Jersey Avenue SE
Washington D.C. 20590

**Re: Defect Information Report - Supplemental Report No. 4
09V-128, FL-547, Condor Cab Tilt Brackets
Owner Re-notification**

Mr. Smith,

In accordance with Part 573.6(c)(10) of Title 49 of the Code of Federal Regulations, Daimler Trucks North America LLC herewith submits supplemental defect information and a copy of documents distributed to owners. 516 owners were re-notified beginning and ending on October 25, 2010. A copy of communications sent to owners is attached.

Please contact me if you have any questions.

Sincerely yours,



Nasser Zamani

Cc: Michael Mason, CAL-OSHA
Enclosure

A Daimler Company

Daimler Trucks North America LLC
4747 N. Channel Avenue
Portland OR 97217-7699
503-745-6910 Phone
503-745-5544 Fax
Nasser.Zamani@Daimler.com

Daimler Trucks North America LLC

Daimler Trucks North America LLC
P.O. Box 4090
Portland, OR 97208-4090
800.547.0712 Phone
503.745.9009 Fax

October 2010
FL547A
NHTSA #09V-128
REMINDER NOTICE

Subject: Condor Cab Tilt Brackets

This notice is sent to you in accordance **with** the requirements of the National Traffic and Motor **Vehicle** Safety Act. This notice is also sent in accordance with the Canadian Motor Vehicles Safety Act.

Daimler Trucks North America LLC, on behalf of its Freightliner Trucks Division and its wholly owned subsidiary, Sterling Truck Corporation, has decided that a defect which relates to motor vehicle safety exists on specific Freightliner and Sterling Condor model vehicles manufactured May 12, 2000, through December 14, 2005, with certain aluminum cab tilt brackets.

The aluminum cab tilt bracket attached to the hydraulic cylinder, used to raise and lower the cab for maintenance, may wear. Worn brackets may provide inadequate restraint, allowing the cab to fall forward onto the ground or rearward onto the chassis, resulting in possible personal injury.

The cab tilt bracket will be replaced with a more robust iron bracket.

This is a follow up to a previous communication. Our records indicate that your vehicle has not yet had this recall performed. Please make **arrangements to** have this repair done as soon as possible. If it has been completed, please disregard this letter.

Parts are now available for authorized dealers to order. Contact your authorized Daimler Trucks North America dealer to arrange to have the recall performed and to ensure that parts are available at the dealership. To locate a dealer, search online at www.FreightlinerTrucks.com, www.SterlingTrucks.com, or contact the Warranty Campaigns Department for assistance.

When you contact your dealer, refer to campaign number **FL547A**. Once **kit(s)** are received at the dealership, the Recall will take approximately two and a half hours and will be performed at no charge to you.

IMPORTANT: When the Recall has been completed, please ensure that a label has been affixed to your vehicle referencing **FL547A**.

If you do not own the vehicle that corresponds to the identification **number(s)** which appears on the Recall Notification, please return the notification to the Warranty Campaigns Department with any information you can furnish that will assist us in locating the present owner. If you have leased this vehicle, Federal law requires that you forward this notice to the lessee within 10 days. If you are a subsequent stage manufacturer, Federal law requires that you forward this notice to your distributors and retail outlets within five working days. If you have paid to have this recall condition corrected prior to this notice, you may be eligible to receive reimbursement. Please see the reverse side of this notice for details.

If you are not able to have the defect remedied without charge and within a reasonable time, which is not longer than 60 days after you tender the **vehicle** for repair, please contact the Warranty Campaigns Department at (800) 547-0712, 7:00 a.m. to 4:00 p.m. Pacific Time, Monday through Friday, e-mail address DTNA.Warranty.Campaigns@Daimler.com, or the Customer Assistance Center at (800) FTL-HELP or (800) **STL-HELP**, after normal business hours. You may also wish to submit a complaint to the Administrator, National Highway Traffic Safety **Administration**, 1200 New Jersey Avenue, SE.; Washington, DC 20590; or call the Vehicle Safety **Hotline** at (888) 327-4236 (TTY: 800-424-9153); or to <http://www.safercar.gov>. If your vehicle is involved in the Canadian portion, you may wish to notify Transport Canada, **ASFAD**, Place de **Ville** Tower C, 330 Sparks Street, Ottawa, ON **K1A 0N5**, or phone (800) 333-0510.

We regret any inconvenience this action may **cause** but feel certain you **understand** our interest in motor vehicle safety.

WARRANTY CAMPAIGNS DEPARTMENT

Enclosure

Reimbursement to Customers for Repairs Performed Prior to Recall

If you have already paid to have this recall condition corrected you may be eligible to receive reimbursement.

Requests for reimbursement may include parts and labor. Reimbursement may be limited to the amount the repair would have cost if completed by an authorized Freightliner LLC dealer. The following documentation must be presented to your dealer for consideration for reimbursement.

Please provide original or clear copies of all receipts, invoices, and repair orders that show:

The name and address of the person who paid for the repair.

- The Vehicle Identification Number (VIN) of the vehicle that was repaired.
- What problem occurred, what repair was done, when the repair was done.
- Who repaired the vehicle.
- The total cost of the repair expense that is being claimed.
- Proof of payment for the repair (such as the front and back of a cancelled check or a credit card receipt).

Reimbursement will be made by check from your Freightliner LLC dealer.

Please speak with your Freightliner LLC authorized dealer concerning this matter.