

**Volvo Trucks North America**

June 23, 2010

10V-282
(3 Pages)**Subject: New Safety Recall
RVXX1003, Drag Link****Attention:**Associate Administrator for Enforcement
National Highway Traffic Safety Administration
1200 New Jersey Avenue, S.E.
Washington, DC 20590**Submitted via Email to George Person**

The following information is submitted in accordance with the requirements of 49 CFR Part 573.6 as it applies to a defect relating to motor vehicle safety.

573.6(c)(1)Volvo Trucks North America ("Volvo")
7900 National Service Rd.
P.O. Box 26115
Greensboro, NC 27409**573.6(c)(2)**

Volvo model vehicles manufactured with certain TRW sealed (i.e. non-greasable) drag links. The selection of vehicles was based on the component part number.

Models Affected: VNL and VNM
Model Year: 2001 through 2006**Component Manufacturer:**TRW Automotive U.S. LLC
800 Heath Street
P O Box 60
Lafayette, IN 47904**573.6(c)(3)**

There are approximately sixty three thousand seven hundred eighty-eight (63,788) vehicles sold in the United States that are affected by the recall.



573.6(c)(4)

The percentage of the vehicles expected to contain the defect is unknown.

573.6(c)(5)

Certain factors can exist, which if left untreated may result in a ball socket separation. Ball socket separation at the drag link results in complete loss of steering and therefore can result in a vehicle crash.

573.6 (c)(6)

Chronology of principle events that were the basis for the determination:

- 1/15/09 NHTSA opens Engineering Analysis 09-003
- 5/27/09 Technical Review held at TRW facility in Livonia, Michigan
- 9/30/09 NHTSA sends information request to Volvo
- 11/6/09 Volvo submits information to NHTSA as requested
- 12/17/09 Meeting at NHTSA office to review documents submitted on 11/6
- 1/19/10 Owner Notice showing proper inspection submitted to NHTSA for review
- 2/22/10 Volvo releases inspection letter as discussed with NHTSA
- 5/26/10 Volvo/ NHTSA mtg to discuss investigation
- 6/23/10 Volvo submits recall information report to NHTSA.

573.6(c)(7)

Not applicable

573.6(c)(8)

Volvo will initiate a voluntary safety recall, and recall all 63,788 vehicles.

The number, which has been assigned to this recall by Volvo, is **RVXX1003**.

Reimbursement for cost incurred by the owner for “prenotification remedies” will be addressed on a case-by-case basis according to the “General Plan for Reimbursement of Pre-notification Remedies” which was published December 8th, 2004.

A Safety Recall Alert will be released to dealers on or before June 28, 2010, which informs the dealers of the recall.



Vehicles in build years 2000-2005 (63,788 vehicles) will be inspected for the TRW sealed drag link. If this drag link is found, the vehicle will be repaired by replacement of the ball socket or the drag link as required.

For vehicles manufactured with the TRW sealed drag link prior to 2000, owners will be notified of the condition and risk.

The number assigned to this recall by Volvo is **RVXX1003**.

Owner letters are tentatively scheduled to be mailed on or before August 15, 2010. An advance copy of the owner letter is attached for your review.

If there are any questions regarding this information, please feel free to contact me.

Sincerely,

A handwritten signature in blue ink, appearing to read "T. LaFon", followed by a long, sweeping horizontal line.

Tim L. LaFon
Manager, Regulatory Affairs
Volvo Trucks North America
P.O. Box 26115
Greensboro, NC 27409
timothy.lafon@volvo.com
(336) 393-2233