## GM CUSTOMER CARE AND AFTERSALES

## DCS2445

## URGENT - DISTRIBUTE IMMEDIATELY

| Date:      | July 20, 2010  |
|------------|--|
| Subject:   | 10153B – Safety Recall<br>Heated Windshield Washer Module Short Circuit  |
| Models:    | 2006-2009 Buick Lucerne<br>2008-2009 Buick Enclave<br>2006-2009 Cadillac DTS<br>2007-2009 Cadillac Escalade, Escalade ESV, Escalade<br>EXT<br>2008-2009 Cadillac CTS<br>2007-2009 Chevrolet Avalanche, Silverado, Suburban,<br>Tahoe<br>2009 Chevrolet Traverse<br>2007-2009 GMC Acadia, Sierra, Yukon, Yukon XL<br>2006-2009 HUMMER H2<br>2007-2009 Saturn OUTLOOK<br>Equipped with Heated Washer Fluid System (RPO<br>XA7/CHW) |
| To:        | All Buick, Cadillac, Chevrolet, GMC, HUMMER, and<br>Saturn<br>Dealers  |
| Attention: | General Manager, Service Manager, Parts Manager,<br>Used Vehicle Manager and Warranty Administrator  |

Safety Recall Bulletin #10153 was originally released in June, 2010 to help correct approximately 1.4 million U. S. vehicles. The bulletin was later amended in July, 2010 as #10153A. The purpose of this message is to further amend this document as #10153B.

Please discard all previous bulletin copies.

Specifically, the new bulletin has been revised to include:

- A note in the Service Procedure section asking dealership personnel to confirm that the customer is aware of this safety recall is being performed on their vehicle prior to performing the repair.

- A "T" labor code in the Claim Information section for customers who refuse to have the recall performed. Note that this labor code will NOT close the recall. If a customer refuses to have the recall performed, dealers are to provide the customer with a copy of the Notice to Customer document contained in this bulletin and record on the repair order "customer declined recall repair". If possible, have the customer sign the repair order and request that the notice be placed in the vehicle's glove box for future reference by subsequent owners. If at a later date the current customer, or a new owner, decides to have this recall performed, the required repair should be completed as soon as possible and a claim submitted using the appropriate "V" labor code.

- A clarification in the Question and Answer section regarding appropriate proof of vehicle ownership.

Please ensure that all involved dealership personnel are aware of this revised bulletin.

END OF MESSAGE

## GM CUSTOMER CARE AND AFTERSALES

Nothing in this message is intended to constitute an electronic signature unless a specific statement to the contrary is included in this message.

Confidentiality Note: This message is intended only for the person or entity to which it is addressed. It may contain confidential and/or privileged material. Any review, transmission, dissemination or other use, or taking of any action in reliance upon this message by persons or entities other than the intended recipient is prohibited and may be unlawful. If you received this message in error, please contact the sender and delete it from your computer.