

TO: Winnebago Industries, Inc. Dealers

SUBJECT: Campaign #120 – Model 32H Dinette Seat Belt Anchorages

The National Traffic and Motor Vehicle Safety Act, as amended, provides that each vehicle which is subject to a recall campaign of this type must be adequately repaired within a reasonable time after the owner has tendered it for repair. A failure to adequately repair within 60 days after tender of a vehicle is prima facie evidence of failure to repair within a reasonable time.

If the condition is not adequately repaired within a reasonable time, the owners may be entitled to an identical or reasonably equivalent vehicle at no charge or to a refund of the purchase price less a reasonable allowance for depreciation.

To avoid having to provide these burdensome solutions, every effort must be made to promptly schedule an appointment with each owner and to repair their vehicle as soon as possible. As you will see in reading the enclosed copy of the letter which is being sent to owners, the owners are being instructed to contact Winnebago Industries, Inc. if you do not remedy the condition within five days of the mutually agreed upon service date. If the condition is not remedied within a reasonable time, they are instructed on how to contact the National Highway Traffic Safety Administration.

REASON FOR THIS RECALL

Winnebago Industries, Inc. has decided a noncompliance with Federal Motor Vehicle Safety Standard No. 210 exists with the dinette area seat belts. In a collision, stress can cause the attachment to tear and allow the anchor to separate from the body of the vehicle. The safety belt may not protect an occupant in the event of a vehicle crash. These motor homes were manufactured from May 10, 2007 through August 4, 2010.

OWNER NOTIFICATION

Owners will be notified of this campaign on their vehicles by Winnebago Industries, Inc. For all units in your inventory, the notification will be mailed to you. **DO NOT DELIVER TO A CUSTOMER ANY SUBJECT UNIT UNTIL CORRECTIVE ACTION HAS BEEN TAKEN.** Enclosed is a list of vehicles shipped to you.

DEALER CAMPAIGN RESPONSIBILITY

Dealers are to service all vehicles subject to this campaign at no charge to owners regardless of mileage, age of vehicle, or ownership from this time forward.

Whenever a vehicle subject to this campaign is taken into new or used vehicle inventory or it is in your dealership for service in the future, you should take the steps necessary to be sure the campaign correction has been made before reselling or releasing the vehicle. Owners of vehicles recently sold from your new vehicle inventory are to be contacted by the dealer and arrangements made to make the required correction according to instructions contained in this campaign.

INSTRUCTION TO PERFORM CAMPAIGN #120

Affected Models:

- 2008 Model F32H Winnebago Voyage® and Itasca Sunrise®.
- 2009 Model J32H Winnebago Adventurer®.
- 2009 Model K32H Itasca Suncruiser®.
- 2010 and 2011 Model J32H Winnebago Adventurer and Itasca Suncruiser.

These motor homes were manufactured between May 10, 2007 through August 4, 2010.

Repair Procedure:

Refer to instruction sheet for installation of seat belt anchorage reinforcement plates.

Parts Information:

To minimize any inconvenience to your customers, we strongly encourage you to promptly order part kits for the vehicles on the attached list. This will ensure you have adequate inventory for your customers. Order the following Part Kit from Winnebago Industries® using the WIN NET system. You will be placing the order as a recall order. You will need the recall dealer number and the Winnebago Industries serial number of the affected vehicle to place the order.

Dealer Number: 7690

Quantity	Part Description	Winnebago Industries Part Number
=====	=====	=====
1	Recall #120 (Model 32H Plate Kit)	RC7690-11-720

REIMBURSEMENT

When the service has been completed, submit the labor amount and labor operation number listed below. Your repair order must be properly signed by both the dealer and the owner.

	<u>OPERATION NUMBER</u>	<u>TIME ALLOWANCE</u>
Install additional seat belt anchorage plates	<u>24200101</u>	<u>1.2 hr</u>

Thank you for your cooperation.

Winnebago Industries, Inc.
Forest City, Iowa 50436

RP138 US/4

Enclosures