do?

Dear General Motors Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

General Motors has decided that a defect that relates to motor vehicle safety exists in certain 2006-2009 model year Buick Lucerne; Cadillac DTS; HUMMER H2; 2008-2009 model year Buick Enclave; Cadillac CTS; 2007-2009 model year Cadillac Escalade, Escalade ESV, Escalade EXT; Chevrolet Avalanche, Silverado, Suburban, Tahoe; GMC Acadia, Sierra, Yukon, Yukon XL; Saturn OUTLOOK; and 2009 model year Chevrolet Traverse vehicles equipped with a heated washer fluid system (HWFS). As a result, GM is conducting a safety recall. We apologize for this inconvenience. However, we are concerned about your safety and continued satisfaction with our products.

IMPORTANT • Your vehicle is involved in safety recall 10153. Schedule an appointment with your GM dealer/retailer. This service will be performed for you at **no charge**. A recall was implemented on some vehicles in 2008 to add a fuse to Why is your vehicle being the HWFS control circuit harness to address the potential consequences of a printed circuit board electrical short. However, recalled? there have been new reports of thermal incidents on HWFS modules after this improvement was installed. These incidents resulted from a new failure mode attributed to the device's thermal protection feature. Their significance varies from minor distortion to considerable melting of the plastic around the HWFS fluid chamber. In some circumstances, it is possible for the heated washer module to cause a fire. What will we Your GM dealer/retailer will permanently disable and remove the heated washer fluid system. In addition, because the heated washer feature will be disabled, the dealer will provide a customer satisfaction payment of \$100 to the customer. This service will be performed for you at **no charge**. Because of service scheduling requirements, it is likely that your dealer/retailer will need your vehicle longer than the actual service correction time of approximately 20 minutes. An updated page for your Owner Manual will be provided and inserted at the time of service to document that the feature has been permanently disabled and removed from your vehicle. If your vehicle is within the New Vehicle Limited Warranty, your dealer/retailer may provide you with shuttle service or some other form of courtesy transportation while your vehicle is at the

Page 28	July 2010	Bulletin No.: 10153B
	dealership/facility for this repair. Please refer to your Owner Manual and your dealer/retailer for details on courtesy transportation.	
What should you do?	You should contact your GM dealer/retailer to arrange a service appointment as soon as possible.	
Did you already pay for this repair?	The enclosed form explains what reimburseme how to request reimbursement if you have pai recall condition. Even though you may have a condition repaired in the past, you will still nee to your dealer/retailer for this recall.	d for repairs for the already had this
Do you have questions?	If you have questions or concerns that your de to resolve, please contact the GM Customer A More information about your vehicle can be fo Center at www.gmownercenter.com.	Assistance Center.

If after contacting your dealer/retailer and the Customer Assistance Center, you are still not satisfied we have done our best to remedy this condition without charge and within a reasonable time, you may wish to write the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington DC 20590, or call the toll-free Vehicle Safety Hotline at 1.888.327.4236 (TTY 1.800.424.9153), or go to http://www.safercar.gov.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

Scott Lawson Director, Customer and Relationship Services

Enclosure 10153

NOTICE TO CUSTOMER

General Motors released this product recall in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act because a defect that relates to motor vehicle safety exists in your vehicle.

It was implemented to address the potential consequences of a printed circuit board electrical short within the Heated Washer Fluid System (HWFS). The significance of this failure can vary from minor distortion to considerable melting of the plastic around the HWFS fluid chamber. In some circumstances, it is possible for the heated washer module to cause a fire.

This failure can occur at any time, even when the vehicle is unattended - parked and key not in the "ON" position. Note that a resulting under hood fire could also involve other nearby vehicles or structures.

Performance of this recall procedure will allow your GM dealer to eliminate these risks by permanently removing the HWFS from your vehicle.

In addition to the risk of a thermal incident, including a fire, it is possible that the HWFS will become inoperative at a future time. If this occurs, it will not be repaired or replaced by GM. Note that GM does not endorse or otherwise approve the use of any similar HWFS products that may be sold by aftermarket suppliers.

Even though you have declined to have this safety recall performed on your vehicle, please be advised that if you change your mind, your GM dealer will always be available to remove the HWFS from your vehicle and provide reimbursement according to the terms described in the recall notification letter.

As part of this declination process, your dealer will ask you to document your refusal to have Safety Recall 10153 performed on your vehicle by signing a Repair Order stating "customer declined recall repair". You will be given a copy of this document for your records. Of course, your signature is voluntary but doing so will help prevent the mailing of recall reminder notices to you as the current owner of record.

If you sell this vehicle, you should advise the buyer that this safety recall was not performed on the vehicle and that the recall repair is still available. This notice should also be placed in the glove box so that a future owner of this vehicle will be aware of this safety recall.