

TBD, 2011

VIN:

SUBJECT: SAFETY RECALL # 1210F
FOLLOWUP NOTIFICATION
SPL170XL Interaxle Driveline
EXPIRATION DATE: NONE

Dear Peterbilt Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Peterbilt Motors has decided that a defect which relates to motor vehicle safety, exists in certain model year 2007 and 2008 vehicles built between January 4, 2006 and April 30, 2007 and equipped with certain extended lube interaxle drivelines. Our records indicate that your vehicle, identified by the VIN at the top of this letter, was manufactured within this time period and may contain a defect.

The bearing surfaces of the SPL170XL extended lube universal joints that attach the interaxle driveline to the drive axles may become prematurely worn due to breakdown of lubrication and/or excessive heat. Prematurely worn bearing surfaces may result in a loose and/or bound universal joint. If undetected, the condition may result in universal joint failure, allowing the interaxle driveline to detach from the axle. A detached driveline may pose a personal injury or property damage hazard.

<i>The problem is...</i>	Interaxle driveline universal joint
<i>What your dealer will do...</i>	Inspect and replace parts when necessary and re-index the driveline
<i>What you must do ...</i>	Contact your Peterbilt Dealer to schedule an appointment for repair

Peterbilt Motors Company has issued this recall to inspect and replace parts when necessary and to re-index the interaxle driveline. **Replacement parts are now available.** Please contact your authorized Peterbilt dealer immediately to schedule an appointment. The service should take no more than two (2) hours and will be provided at no charge to you. **Please advise the repairing dealer if you have already had u-joints replaced under this recall and are now requiring only driveline re-indexing and boot installation.**

NOTE: Lubrication intervals for a non-factory installed universal joint are 100,000 mile/6 months (whichever occurs first).


If you require further information, have already experienced this condition and have paid to have it repaired, or experience any difficulty in making arrangements for the repair, please contact: Peterbilt Motors Company, 1700 Woodbrook Street, Denton, Texas 76205; Customer Service Department, phone 940-591-4196.

If you conclude that Peterbilt has not enabled you to remedy this defect within a reasonable time and without charge, you may submit a complaint to: The Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue SE, Washington DC 20590, or call the toll free Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days. If you no longer own this vehicle, we would appreciate your advising us of the new owner if you know their name. The enclosed card may be used for this purpose.

We regret any inconvenience this work may cause you and appreciate your cooperation in this matter.

Sincerely,



Rick Wood
Customer Service Manager