



PERFORM THE PROCEDURE OUTLINED IN THIS SERVICE INFORMATION ON ALL AFFECTED VEHICLES BEFORE CUSTOMER DELIVERY OR THE NEXT TIME THEY ARE IN THE SHOP FOR MAINTENANCE OR REPAIRS.

Under the National Traffic and Motor Vehicle Safety Act of 1966, as amended, if there has been a recall campaign, dealers must assure that all new vehicles and new items of replacement equipment are free of safety defects and comply with all applicable Federal Motor Vehicle Safety Standards at the time of delivery to the consumer. This means that dealers may not deliver new motor vehicles or new items of replacement equipment to consumers unless the safety defect or noncompliance has been remedied before delivery.

SUBJECT

Recall Campaign 10V-047: Inspect Tire Information Placard

MODEL

7 Series (F02)

5 Series Gran Turismo (F07)

SITUATION

Certain vehicles were produced with the incorrect Tire Information Label installed. The Tire Information Label may not reflect the proper seating capacity for the vehicle. This Recall Campaign is being performed to inspect and correct the label, as necessary.

Customers will receive notification letters. Tire Information Labels should be ordered in advance of the customer's service appointment. The necessary order form is attached to this bulletin.

AFFECTED VEHICLES

This Recall Campaign involves 750Li and 5 Series Gran Turismo models which were produced from September 7, 2009, to November 26, 2009.

In order to determine whether a specific vehicle has had this Recall Campaign completed or is affected by this Recall Campaign, first check the B-pillar label for code number **559**. If code number **559** has been punched out, the campaign has already been performed. If code number **559** has not been punched out, it will be necessary to utilize the "Service Menu" of DCSnet (Dealer Communication System) or the Key Reader. Based on the response of the system, either proceed with the corrective action or take no further action.

PROCEDURE

Open the driver's door and inspect the Tire Information Label located on the B-pillar. The affected vehicles were produced with a label which indicates a seating capacity of 5. However, the vehicle has a seating capacity of 4.

If the seating capacity listed on the label indicates 4, no further action is necessary.

If the seating capacity indicates 5, wipe off the label with a clean, lint-free cloth and apply a new label


directly over the existing label.

PARTS INFORMATION

Part Number	Description	Quantity
71 24 6 781 271	Tire Information Label	1

Tire Information Label to be ordered using attached order form.

LABEL INSTRUCTIONS



This Recall Campaign has been assigned code number **559**. After the vehicle has been checked and/or corrected, obtain a label (SD 92-366) and:

- A. Emboss your BMW center warranty number in the middle of the label (1);
- B. Punch out code number **559** (2) printed on the label; and
- C. Affix the label to the **B**-pillar as shown.

If the vehicle already has a label from a previous Service Action/Recall Campaign, affix the new label next to the old one. Do not affix one label on top of another one, because a number from an underlying label could appear in the punched-out hole of the new label.

WARRANTY INFORMATION

The repair described in this bulletin is covered under warranty regardless of time or mileage. Reimbursement for this Recall will be via normal claim entry utilizing the following information:

Defect Code:	00 71 47 01 00	
Labor Operation:	Labor Allowance:	Description:
00 58 993	Refer to KSD	Inspect/install tire pressure label

ATTACHMENTS

view PDF attachment [B710110Customer Letter](#).

view PDF attachment [B710110Order Form](#).

[Copyright © 2010 BMW of North America, LLC]