

Applies To: 2007–08 Fit – ALL

January 7, 2011

Safety Recall: 2007–08 Fit Low Beam Headlights May Not Work

BACKGROUND

A terminal in the combination light switch 16P harness connector can overheat and may cause the low-beam headlights to fail without warning. Although the high-beam position remains operational, an unexpected loss of low beam functionality could result in a crash.

CUSTOMER NOTIFICATION

All owners of affected vehicles will be sent a notification of this campaign. An example of the customer notification is at the end of this service bulletin.

To verify vehicle eligibility, you must check at least one of these items:

- The customer has a notification letter.
- The vehicle is shown as eligible on an iN VIN status inquiry.

In addition to the listed items, check for a punch mark above the seventh character of the engine compartment VIN. A punch mark in that location means the vehicle has already been repaired.

Some of the vehicles affected by this campaign may be in your used vehicle inventory. **These vehicles must be repaired before they are sold or leased.** To see if a vehicle is affected by this campaign, do an iN VIN status inquiry before selling it, leasing it, or returning it to a service customer.

Should an unrepaired vehicle that was in inventory, or that came in for service after this service bulletin was issued, cause an injury or property damage because of the campaigned item, the dealership will be solely responsible to the damaged party, and will be required to defend and indemnify American Honda for any resulting claims.

CORRECTIVE ACTION

Inspect the combination light switch wire harness 16P connector and, depending on what you find, install a Combination Light Switch Wire Kit, or a Combination Light Switch Repair Kit.

PARTS INFORMATION

NOTE: Most vehicles require only the Combination Light Switch *Wire Kit*, which is currently available. Combination Light Switch *Repair Kits* are not available until late-January 2011.

Combination Light Switch Wire Kit:

P/N 06322-SAA-305

(Includes 250 mm wire with attached terminal, wire splice connector, and wire tie)

Combination Light Switch Repair Kit:

Base models: P/N 06323-SAA-307

Sport models: P/N 06323-SAA-309

(Includes switch, 16P wire harness connector, 250 mm wire with attached terminal, wire splice connector, and wire tie)

TOOL INFORMATION

NOTE: The tools listed below were previously sent to your dealership for the completion of Service Bulletin 04-015, *Safety Recall: Combination Light Switch*. If you need additional tools, order them through the parts ordering system.

Terminal Pin Kit C: T/N 07QAZ-003020C

(Contains the wire crimper and the heat gun used for wire splicing.)

Terminal Maintenance Set: T/N 070AZ-S5A0100

[Contains Terminal Remover Set (six small, plastic tools used to remove terminals from the 16P headlight wire harness connector), and Secondary Lock Opener (a miniature, flat-tip screwdriver used to open the secondary locks on the 16P headlight wire harness connector)]

WARRANTY CLAIM INFORMATION

OP#	Description	FRT
7280A3	Install a Combination Light Switch <i>Wire Kit</i> .	0.6
7280A4	Install a Combination Light Switch <i>Repair Kit</i> .	0.7

Failed Part: P/N 35255-S5A-A02

Defect Code: 5LS00


Symptom Code: R5800

Skill Level: Repair Technician

REPAIR PROCEDURE


NOTE:

- Over 90 percent of affected vehicles should be repairable with the Combination Light Switch *Wire Kit*.
 - SRS components are located in this area. Before you begin, review the SRS component locations, cautions, and procedures in the service manual.
 - Be careful not to damage the dashboard or other interior trim pieces.
 - For more information on wire terminal replacement and wire splicing, refer to Service Bulletin 00-099, *Terminal Replacement Instructions*.
1. Make sure you have the anti-theft code for the radio, then disconnect the negative cable from the battery.
 2. Remove the driver's dashboard undercover.
 3. Remove the steering column covers.




4. Remove the steering column front nuts and rear bolts.

5. Disconnect the 16P connector from the combination light switch and the 5P or 13P connector from the cable reel. Then carefully pull the wire harness to the right of the steering column.




6. Turn the ignition switch to ACC (I), then turn the steering wheel 90 degrees to the left to allow room for removal of the combination light switch.
7. Remove the two screws from the combination light switch.



8. Using a flat-tip screwdriver wrapped with tape, slightly lift the switch cover, then remove the switch.
NOTE: To allow removal clearance for the combination light switch, slightly shift the steering column to the right.

9. Using the secondary lock opener from the Terminal Maintenance Set (T/N 070AZ-S5A0100), carefully pry open the secondary lock on the RED/WHT wire side of the combination light switch 16P connector.




10. Twist off a terminal remover from the Terminal Maintenance Set (T/N 070AZ-S5A0100). Insert the terminal remover into the center row cavity of the 16P connector, above the RED/WHT wire cavity, then remove the RED/WHT wire from the 16P connector.

11. Using the photos below, check for signs of heat damage on the 16P connector, the terminal end of the RED/WHT wire, and the 16P terminals of the combination light switch.


- If you don't find any signs of heat damage, *retain the combination light switch* because you'll only be installing a Combination Light Switch Wire Kit. Go to step 14.
- If you do find signs of heat damage, *discard the combination light switch* because you'll be installing a Combination Light Switch Repair Kit. Go to step 12.

NOTE: Combination Light Switch Repair Kits are not available until late-January 2011. If a vehicle needs a Combination Light Switch Repair Kit prior to late-January 2011, call Tech Line for repair information.




12. Using the secondary lock opener from the Terminal Maintenance Set (T/N 070AZ-S5A0100), carefully pry open the other secondary lock on the 16P connector.

13. Twist off a terminal remover from the Terminal Maintenance Set (T/N 070AZ-S5A0100). Insert the terminal remover into a center row cavity of the original 16P connector, remove the corresponding wire from its cavity, and transfer it to the same cavity in the new 16P connector from the repair kit. Repeat this for all the wires *except* the original RED/WHT wire; this wire will be installed later.




14. On the new RED/WHT wire provided in either kit, measure 50 mm from the terminal end, and wrap a 50 mm section of the wire with three turns of electrical tape. This taped section of the wire will be secured to the combination light switch in step 22.



15. Strip off 7 mm of insulation from the opposite end of the new RED/WHT wire.


16. Cut the vehicle side RED/WHT wire near the terminal, then strip off 7 mm of insulation from the end of the wire.

NOTE: If there was any heat damage to the RED/WHT wire, make sure to cut off the damaged area before you strip off the insulation.



17. Insert the stripped end of the new and the original RED/WHT wire into each side of the splice connector from the kit, then, using the wire crimper from Terminal Pin Kit C, crimp the connector. Slightly pull on both sides of the wire to make sure it's secured in the splice connector.


NOTE: To get the correct amount of pressure on the splice connector, you need to use the wire crimper from Terminal Pin Kit C.



18. With a non-combustible material between the RED/WHT wire and the vehicle wire harness, use a heat gun to shrink the splice connector casing.

NOTE:

- Be careful not to get burned.
- Do not overheat the wire.



19. Place the wire splice on top of the combination switch wire harness, then attach the splice to the harness by wrapping them together with electrical tape.


Attach the RED/WHT wire splice to the harness with electrical tape.



20. Insert the new RED/WHT wire into its proper position in the 16P connector, then snap the connector secondary lock(s) closed.

21. Release the cover locks on the combination light switch, then remove the switch cover.


Release the switch cover locks.



SWITCH COVER Remove.



22. As shown below, route the wire tie from the kit through the hole in the lower corner of the switch cover. Then use the wire tie to secure the RED/WHT wire (in the section you taped in step 14) to the switch cover. Cut off the excess wire tie.



Secure the taped section of the RED/WHT wire to the switch cover with the wire tie.

23. Reattach the switch cover to the combination light switch. Make sure the switch cover is properly locked in place.

**SWITCH COVER REATTACHED
AND CONNECTOR RECONNECTED.**



24. Connect the 16P connector to the combination light switch, then route the RED/WHT wire under the 5P or 13P cable reel connector, and reconnect the connector. Make sure the connectors are securely connected.
25. Install the combination light switch with the two original screws.
26. Connect the negative cable to the battery.
27. Check the operation of the headlights, the parking lights, and the turn signals.
28. Install the steering column covers.
29. Reinstall the driver's dashboard lower cover.
30. Enter the radio anti-theft code.
31. Center-punch a completion mark above the seventh character of the engine compartment VIN.

Center-punch here.

JHMGD3XXXXXXXXXXXX

January 2011

Safety Recall Campaign: Headlight Switch

Dear Fit Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

What is the reason for this notice?

Honda has decided that a defect which relates to motor vehicle safety exists in certain 2007–08 model year Fit vehicles. There is a potential failure with the wiring of the low beam headlights which may cause the low beam headlights to fail. The loss of the low beam headlights will increase the risk of a crash.

What should you do?

Call any authorized Honda dealer and make an appointment to have your vehicle repaired. The dealer will inspect and repair the headlight wiring if necessary. This work will be done free of charge. Please plan to leave your vehicle for half a day to allow the dealer flexibility in scheduling.

Who to contact if you experience problems.

If you are not satisfied with the service you receive from your Honda dealer, you may write to:

American Honda Motor Co., Inc.
Honda Automobile Customer Service
Mail Stop 500-2N-7A
1919 Torrance Blvd.
Torrance, CA 90501-2746

If you believe that American Honda or the dealer has failed or is unable to remedy the defect in your vehicle, without charge, within a reasonable period of time (60 days from the date you first contact the dealer for a repair appointment), you may submit a complaint to:

Administrator
National Highway Traffic Safety Administration
1200 New Jersey Ave., SE
Washington, DC 20590

Or call the toll-free Safety Hotline at 888-327-4236 (TTY 800-424-9153), or go to <http://www.safercar.gov>.

What to do if you feel this notice is in error.

Our records show that you are the current owner or lessee of a 2007 or 2008 Fit involved in this campaign. If this is not the case, or the name/address information is not correct, please fill out and return the enclosed, postage-paid Information Change Card. We will then update our records.

If you previously paid to have the headlight switch replaced, you may be eligible for reimbursement. Refer to the attached Instructions for Reimbursement for the eligibility requirements and the reimbursement procedure.

Lessor Information.

Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within 10 days.

If you have questions.

If you have any questions about this notice, or need assistance with contacting a Honda dealer, please call Honda Automobile Customer Service at 800-999-1009, and select option 4.

We apologize for any inconvenience this campaign may cause you.

Sincerely,

**American Honda Motor Co., Inc.
Honda Automobile Division**

January 7, 2011

Dear Service Manager:

Honda has announced a safety recall campaign for 2007–08 Fits. A terminal in the combination light switch 16P harness connector can overheat and may cause the low-beam headlights to fail without warning. Although the high-beam position remains operational, an unexpected loss of low beam functionality could result in a crash.

Repair Strategy

Inspect the combination light switch wire harness 16P connector and, depending on what is found, install a Combination Light Switch *Wire Kit*, or a Combination Light Switch *Repair Kit*. For repair, tools, parts, and warranty information, refer to Service Bulletin 10-082, *Safety Recall: 2007–08 Fit Low Beam Headlights May Not Work*.

Some vehicles affected by this campaign may be in your used vehicle inventory. As a matter of federal law, these vehicles must be repaired before they are sold. Should a dealership sell an unrepaired vehicle that subsequently causes an injury or damage because of the recalled item, the dealership will be solely responsible to the damaged party, and will be required to defend and indemnify American Honda for any resulting claims.

To see if a vehicle is affected by this campaign, make sure the customer has a notification letter or do an iN VIN status inquiry. In addition, check for a punch mark above the seventh character of the engine compartment VIN. A punch mark in that location means the vehicle has already been repaired.

Customer Notification

Owners of affected vehicles will begin receiving notifications of this campaign the week of January 24, 2011. An example of the customer notification is at the end of Service Bulletin 10-082.

Parts Information

An initial allocation of Combination Light Switch *Wire Kits* (P/N 06322-SAA-305) was allocated to dealers on December 17, 2010. The allocation quantity is based on certified used vehicle inventory and number of sold units. An additional allocation of this kit will follow in January 2011. **This kit can be used to repair most vehicles.**

Combination Light Switch *Repair Kits* (P/N 06323-SAA-307 for Base models, and P/N 06323-SAA-309 for Sport models), are not available until late-January 2011. If a vehicle needs a Combination Light Switch *Repair Kit* prior to late-January 2011, call Tech Line for repair information.

Sincerely,

American Honda Motor Co., Inc.
Honda Automobile Division