



903 South Main Street • P.O. Box 460 • Middlebury, IN 46540 • (574) 825-0608 • Fax (574) 825-0572

November 15, 2011

11V-554
(2 Pages)

Associate Administrator for Enforcement
Department of Transportation
National Highway Traffic Safety Administration
Office of Enforcement NVS-200 Room W45-306
1200 New Jersey Avenue S.E.
Washington, DC 20590

Dear Sir or Madam:

Pursuant to 49 CFR Part 573, Jayco, Inc. (“Jayco” or the “Company”) is submitting this report to NHTSA concerning a recall campaign, which is being voluntarily initiated. Specific information is as follows:

573.6(c)(2)

Affected vehicles are 2012 Jay Flight Travel Trailers and 2012 Eagle Super Lite 1/2 ton Travel Trailers.

The affected vehicles were manufactured between October 6, 2011 and October 17, 2011.

The recall population was determined from the manufacturing records for the Company’s manufacturing plant in Middlebury, Indiana, which produced the affected recreational vehicles.

573.6(c)(3)

A total of 80 vehicles are subject to this recall. Specific Vehicle Identification Numbers (VIN) are as follows:

Model year 2012 vehicles with a starting VIN of 1UJBJ0BN6C18T0267 and ending with 1UJCJ0BNXC1PY0154.

573.6(c)(4)

Jayco is recalling 100 percent of the affected vehicles identified in the scope.

573.6(c)(5)

Jayco has decided that certain 2012 Jay Flight Travel Trailers and 2012 Eagle Super Lite 1/2 ton Travel Trailers may have an improperly built converter. The equipment supplier may have installed an undersized input coil. This may cause overheating, smoking, and melting of the converter. If this condition is not addressed, it may result in a fire, injury or death.

573.6(c)(6)

During the course of routine inspection, it was noticed that the input coil on the Iota converter was undersized. Jayco immediately contacted the supplier and quarantined and inspected all affected product. We are in the process of contacting the dealers who have affected units that shipped prior to being quarantined and inspected.

573.6(c)(8)

The remedy for the affected recreational vehicles is to inspect the converter to determine if an undersized input coil was installed in the converter and to replace the converter if the wrong coil was used.

Copies of the repair instructions, dealer notification letters, and owner letters will be provided to the agency within 10 business days. Jayco is contacting all dealers and retail owners of the affected vehicles. Upon notification Jayco is prepared to begin dealer notification within 5 business days after approval, and to owner's ten business days subsequent to dealer notification.

Thank you for your assistance,

A handwritten signature in cursive script that reads "Joseph J. Resil".

Sincerely,

Joe Resil
Regulatory Compliance Manager