



Toyota Motor Sales, U.S.A., Inc.
19001 South Western Avenue
P.O. Box 2991
Torrance, CA 90509-2991

**Certain 2011 Model Year Tundra Vehicles
Inspection and Possible Replacement of Rear Propeller Shaft
SAFETY RECALL FOLLOW-UP NOTICE**

URGENT

VIN:

Dear Toyota Customer:

This notice is being sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Toyota has decided that a defect, which relates to motor vehicle safety, exists in certain 2011 model year Tundra vehicles. Our records indicate that you own a vehicle that has not yet had this condition corrected.

What is the condition?

On certain 2011 Model Year Tundra vehicles equipped with a 3-Joint type propeller shaft, the rear propeller shaft slip yoke may have been improperly cast. The improperly cast yokes are from a specific production lot. In vehicles with a slip yoke from that lot, there is the possibility that the slip yoke may break and the rear propeller shaft may separate at the joint. If this occurs the propeller shaft could contact the road surface, which could increase the risk of a crash.

What will Toyota do?

Any authorized Toyota dealer will inspect the rear propeller shaft to determine if it might contain an improperly manufactured slip yoke. Based upon the inspection results, in a limited number of cases, the dealer may need to replace the rear propeller shaft. The inspection and, if necessary, replacement will be performed at **NO CHARGE** to you.

What should you do?

This is an important Safety Recall

Please contact your authorized Toyota dealer to make an appointment to have the rear propeller shaft inspected as soon as possible. Most vehicles will only require an inspection, which will take approximately 10 minutes. However, depending upon the dealer's work schedule, it may be necessary to make your vehicle available for a longer period of time.

If replacement of the rear propeller shaft is necessary, your dealer will need to order the specific part for your vehicle. It will take a few days for the dealer to order and receive the part, and then to perform the replacement. During this time, Toyota will offer to provide you with a rental vehicle (upon proof of adequate insurance) at no charge to you.

The actual time needed to replace the rear propeller shaft is approximately 1 hour.

You do not need an owner letter to have this recall completed; however, to assist the dealer in confirming vehicle eligibility, we request that you present this notice at the time of your service appointment.

If you would like to update your vehicle ownership or contact information, please go to www.toyota.com/ownersupdate. You will need your full17-digit Vehicle Identification Number (VIN) to input the new information.

What if you have other questions?

Your local Toyota dealer will be more than happy to answer any of your questions and set up an appointment to perform this important Safety Recall. If you require further assistance, you may contact the Toyota Customer Experience Center at 1-888-270-9371 Monday through Friday, 5:00 am to 6:00 pm, Saturday 7:00 am through 4:00 pm Pacific Time.

If you believe that the dealer or Toyota has failed or is unable to remedy the defect within a reasonable time, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue S.E., Washington, DC 20590 or call the toll free Vehicle Safety Hot Line at 1-888-327-4236 (TTY: 1-800-424-9153), or go to www.safercar.gov.

If you are a vehicle lessor, Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

We have sent this notice in the interest of your continued satisfaction with our products, and we sincerely regret any inconvenience this condition may have caused you.

Thank you for driving a Toyota.

Sincerely,

TOYOTA MOTOR SALES, U.S.A., INC.

Spanish translation on back side
Traducción en español en el reverso