Volvo Cars of North America, LLC



1 Volvo Drive P.O. Box 914 Rockleigh, NJ 07647 Phone: 201-768-7300 www.volvocars.us

Product Safety & Compliance

***** IMPORTANT VEHICLE RECALL NOTICE *****

DATE: June 24, 2011

TO: All U.S. and Canadian Volvo Retailers

RE: Volvo Recall 245

Certain Model Year 2012 S60T5 Vehicles

The sale or lease of defective or non-compliant motor vehicles or equipment is prohibited by law. Vehicles in retailer inventory must be remedied prior to sale. Repair information is attached to this communication.

Volvo Cars of North America, LLC (Volvo) has decided to conduct a voluntary safety recall on certain model year 2012 S60T5 vehicles.

The male part of the fuel line quick connector end was produced with dimensions out of specification, leading to excessive assembly force on the female connector assembly and the possibility that the locking function may not be engaged.

If a vehicle exhibits this condition, the fuel line quick connector may detach and the engine may stall, increasing the risk of a crash. The customer may also notice a fuel smell and leakage. A fuel leak in the presence of an ignition source could result in a fire.

The corrective action will be to replace the fuel lines per TJ 24868.

This recall affects 442 vehicles in the U.S., 27 in Canada and 6 in Puerto Rico.

OWNER NOTIFICATION

Owner notification is scheduled to begin in June.

RETAILER RESPONSIBILITIES

Retailers must perform this recall campaign on eligible vehicles regardless of miles/kilometers or vehicle age. All work performed under this recall is free of charge to the owner.

In the event that a customer does not have a notification letter, the owner is not to be refused the work. Your regional representative will follow up to ensure that this recall campaign is proceeding smoothly.

A complete description of the recall campaign requirements and claim submission procedures is below. It is the retailer's responsibility to review the details provided in the materials listed below with all involved personnel.

- Service Manager Bulletin
- Technical Journal
- Parts Bulletin

Your cooperation in completing this important recall is greatly appreciated.

Drive Safely,

Adam Kopstein

Manager, Product Safety and Compliance

201-768-7300 ext# 7908

A. Kopster

akopstei@volvocars.com

				TITLE:	GROUI	P:	NO:
VOLVO				Recall 245: Replace Fuel Lines	23		245
90	rvic.	20		Model Year 2012	ISSUING DEPARTMENT:		
Service				S60T5	Warranty		
	Mar	1206	or		CARMARKET:		
						ted Sta Canada	,
	В	ulle	tin	REFERENCE BULLETINS:		DATE:	
				TJ 24868, PB 23-245	YEAR	MONTH	DAY
Service Person-	SERVICE MANAGER	SERVICE WRITER	WARRANTY ADMINISTRATOR		2011	06	24
nel: read and initial.					Pa	age 1 o	f 2

- A. RECALL 245 DESCRIPTION
- B. VEHICLES INVOLVED
- C. PARTS INFORMATION/PARTS RETURN
- D. OWNER NOTIFICATION
- E. VEHICLES IN RETAILER INVENTORY
- F. RETAILER RESPONSIBILITY
- G. TECHNICIAN COMPETENCY REQUIREMENT
- H. CAMPAIGN REIMBURSEMENT PROCEDURES

A. RECALL 245 DESCRIPTION

Volvo Cars of North America, LLC (Volvo) has decided to conduct a voluntary safety recall on certain model year 2012 S60T5 vehicles.

The male part of the fuel line quick connector end was produced with dimensions out of specification, leading to excessive assembly force on the female connector assembly and the possibility that the locking function may not be engaged.

If a vehicle exhibits this condition, the fuel line quick connector may detach and the engine may stall, increasing the risk of a crash. The customer may also notice a fuel smell and leakage. A fuel leak in the presence of an ignition source could result in a fire.

The corrective action will be to replace the fuel lines per TJ 24868.

This recall affects 442 vehicles in the U.S., 27 in Canada and 6 in Puerto Rico.

B. VEHICLES INVOLVED

NOTE: RETAILERS MUST CONFIRM VEHICLE ELIGIBILITY PRIOR TO BEGINNING THIS RECALL REPAIR.

Vehicle eligibility must be confirmed:

• Inquire in VRC² - Vehicle Warranty where the message "RECALL 245 - Replace Fuel Lines (R29218)" will appear for eligible vehicles.

"Fixed Right — First Time"





All vehicles should be checked for any other incomplete recalls or service campaigns or service upgrades. All open Recall, Service Campaign or Service Action repairs should be completed.

RETAILER VEHICLE CAMPAIGN LIST

The "Unperformed Recall Report" will be posted on VRC² in the Reports Menu under the Service Tab. This report lists all affected vehicles that are on record as retailed/serviced or currently in stock at your facility with incomplete recalls and service campaigns, and is updated monthly.

C. PARTS INFORMATION / PARTS RETURN

Please refer to Parts Bulletin 23-245.

PARTS RETURN

Parts are not required to be returned for repairs done in accordance with this recall.

D. OWNER NOTIFICATION

Owner notification is scheduled to begin in June.

E. VEHICLES IN RETAILER INVENTORY

All vehicles in retailer inventory and qualifying for this recall must be repaired prior to a customer taking possession of the vehicle.

F. RETAILER RESPONSIBILITY

Retailers are to perform this recall on eligible vehicles regardless of mileage/kilometers or vehicle age. The repairs included in Recall 245 are free of charge to the owner. If a customer presents a recall or service campaign letter for a vehicle that is not found via the VRC² inquiry function, please verify that the letter applies to the customer's vehicle and call the Warranty Assistance Desk at 1-800-807-7712 for instructions. If the Warranty Assistance Desk verifies that the vehicle qualifies for the Recall or Service Campaign, please perform the repair and place the recall or service campaign letter in the customer's file. Under no circumstances should a customer be denied the required service without a confirmation from VCNA/VCCC.

G. TECHNICIAN COMPETENCY REQUIREMENT

The technician competency requirement for this campaign repair is: Level 2 Quality Tech.

H. CAMPAIGN REIMBURSEMENT PROCEDURES (LONG FORM APPLICATION)

Labor reimbursement allowance is effective at time of release and may change in the future.

Claim Type: R29218
Cause Code: 02
CSC Code: XW
Main OP: 23598

Operation Number	Repair Description	<u>Oty</u>	Labor Time
23598	Replace Fuel Lines	1	2.1 Hrs



Parts Bulletin

Recall 245: Replace Fuel Lines					GROUP 23			245
Model Y	Model Year 2012 S60T5 COPY TO / CIRCULATIONS (PLEASE INITIAL)					United States, Canada		
GENERAL MGR	PARTS MGR	SERVICE MGR	SALESMGR	DATE	YEAR	MONTH	DAY	
					2011	06	24	

Reference Bulletins: TJ 24868

SMB 23-245

Volvo Cars of North America, LLC (Volvo) has decided to conduct a voluntary safety recall on certain model year 2012 S60T5 vehicles.

The male part of the fuel line quick connector end was produced with dimensions out of specification, leading to excessive assembly force on the female connector assembly and the possibility that the locking function may not be engaged.

If a vehicle exhibits this condition, the fuel line quick connector may detach and the engine may stall, increasing the risk of a crash. The customer may also notice a fuel smell and leakage. A fuel leak in the presence of an ignition source could result in a fire.

The corrective action will be to replace the fuel lines per TJ 24868.

This recall affects 442 vehicles in the U.S., 27 in Canada and 6 in Puerto Rico. Due to the low volume of cars affected, there will not be an allocation for this recall. Please only order these parts as needed.

The following part numbers apply:

Part Number	Description	Qty
30751368	Delivery Pipe	1
31336649	Plastic Pipe	1

"Fixed Right — First Time"

Page 1 of 1 This document contains 2 items totaling 7 pages



Volvo Car Corporation
TIE - Technical Information Exchange

TIE - Technical Journal

Title Recall 245: Fuel pipe end connector

Ref No US24868.1.2 en-GB

Partner 3 US 7510 Volvo Cars North America

Func Group 2330 Func Desc fuel pump and strainer

Status Released

Status Date 2011-06-24 **Issue Date** 2011-06-13

Reference SMB 23-245, PB 23-245

Attachment

File Name	File Size
Attachment TJ 24868.pdf	1.0809 MB

Vehicle Type

Туре		Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
134	62	B5254T5					2012 -2012		0030902 -0032474	0 -0

CSC

Code	Description
XW	Service action/Recall/Service action/Recall

DTC

Text

CSC = Customer Symptom Code

DTC = Diagnostic Trouble Code

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

DESCRIPTION:

Volvo Cars of North America, LLC (Volvo) has decided to conduct a voluntary safety recall on certain model year 2012 S60T5 vehicles.

The male part of the fuel line quick connector end was produced with dimensions out of specification, leading to excessive assembly force on the female connector assembly and the possibility that the locking function may not be engaged.

If a vehicle exhibits this condition, the fuel line quick connector may detach and the engine may stall, increasing the risk of a crash. The customer may also notice a fuel smell and leakage. A fuel leak in the presence of an ignition source could result in a fire.

SERVICE:

The corrective action is to replace the fuel lines according to the attached instructions.

		Volvo Car Customer Service
		TJ Instruction
		TJ No 24868
		June-11 Issue 0G
Title	Fuel pipe end connector	

Materials

Description	Qty.	Part No.
Delivery pipe	1	30751368
Plastic pipe	1	31336649

Special tools

<u> </u>		
Description	Part No.	
Removal tool	999 7298	



TJ Instruction 24868 Page 2 (6)

Depressurizing

Perform depressurizing fuel system, refer to:

Cleaning, Inspection and Adjustment

2 - Engine with mountings and equipment

23 - Fuel system

234 - fuel tank, fuel lines, evaporator

system

Removal


Remove the fuel rail, refer to:


Removal, replacement and installation

2 - Engine with mountings and equipment


23 - Fuel system

237 - injector and delivery pipe





TJ Instruction 24868 Page 3 (6)



Warning! Be prepared to collect escaping

Special Tool: T9997298, REMOVAL TOOL


Follow instructions for lifting points body frame, refer to:

Specifications, mechanical


8 - Body and interior


81 - Body frame


810 - general




TJ Instruction 24868 Page 4 (6)









TJ Instruction 24868 Page 5 (6)






Warning! Be prepared to collect escaping fluid.



TJ Instruction 24868 Page 6 (6)



Installation

To install, reverse the removal procedure.



1 Volvo Drive P.O. Box 914 Rockleigh, NJ 07647 Phone: 201-768-7300 www.volvocars.us

IMPORTANT RECALL NOTICE

June 24, 2011

Dear Volvo Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Volvo Cars of North America, LLC (Volvo) has decided to conduct a voluntary safety recall on certain model year 2012 S60T5 vehicles.

The reason for Recall 245:

Volvo has identified that the male part of the fuel line quick connector end was produced with dimensions out of specification, leading to excessive assembly force on the female connector assembly and the possibility that the locking function may not be engaged.

If a vehicle exhibits this condition, the fuel line quick connector may detach and the engine may stall, increasing the risk of a crash. The driver may also notice a fuel smell and leakage. A fuel leak in the presence of an ignition source could result in a fire.

The corrective action will be to replace the fuel lines.

What you need to do:

Please contact your authorized Volvo retailer for an appointment. This procedure will be completed at no cost and can take up to 3 hours to complete; however, due to service scheduling and parts availability, the time your Volvo retailer requires to service your vehicle may vary.

If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall. For more information please refer to the Volvo Customer Care Center contact information in this letter.

Please contact:

If you have any questions, please contact your Volvo retailer. If your retailer is unable to answer your questions, please contact Volvo Customer Care Center at 1 Volvo Drive, P.O. Box 914, Rockleigh, NJ 07647 or phone 1-800-458-1552, Monday through Friday, 8:30 A.M. to 5:00 P.M. EST. You may also e-mail us at <u>customercare@volvoforlife.com</u>.

We have advised the National Highway Traffic Safety Administration (NHTSA) that we are conducting this recall. If you are unable to have this procedure performed without charge and within a reasonable period of time, you may contact the NHTSA Administrator at: National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE., Washington, DC 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to http://www.safercar.gov.

Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days. Lessor means a person or entity that is the owner, as reflected on the vehicle title, of any five or more leased vehicles.

Your safety and continued satisfaction with your Volvo and the Volvo organization are very important to us. We apologize for any inconvenience this may cause and we appreciate your cooperation in arranging to have this important service completed as quickly as possible.

Sincerely,

Mike Assainte

Manager, Customer Support

Mike Christe

Volvo Cars of Canada Corp.



175 Gordon Baker Road North York, ON, Canada M2H 2N7 Telephone (416) 493-3700 Facsimile (416) 496-0552 www.volvocanada.com

June 2011

IMPORTANT RECALL NOTICE

Dear Volvo Owner:

This notice is sent to you in accordance with the requirements of the Motor Vehicle Safety Act.

Volvo Cars of North America, LLC (Volvo) has decided to conduct a voluntary safety recall on certain model year 2012 S60T5 vehicles.

The reason for Recall 245:

Volvo has identified that the male part of the fuel line quick connector end was produced with dimensions out of specification, leading to excessive assembly force on the female connector assembly and the possibility that the locking function may not be engaged.

If a vehicle exhibits this condition, the fuel line quick connector may detach and the engine may stall, increasing the risk of a crash. The driver may also notice a fuel smell and leakage. A fuel leak in the presence of an ignition source could result in a fire.

The corrective action will be to replace the fuel lines.

What you need to do:

Please contact your authorized Volvo retailer to schedule an appointment. This procedure will be completed at no cost and can take up to 3 hours to complete; however, due to service scheduling and parts availability, the time your Volvo retailer requires to service your vehicle may vary.

If you previously paid to have this corrective action performed, prior to the date on this letter, your authorized Volvo retailer will honor your receipt with a refund. Please contact your authorized Volvo retailer service department for details.

Please contact:

If you have any questions, please contact your authorized Volvo retailer. If your retailer is unable to answer your questions, please contact Volvo Customer Relations at 1-800-663-8255, Monday through Friday, 8:30 A.M. to 5:00 P.M. EST or by e-mail at vclcust@volvocars.com. You may also write to us at 175 Gordon Baker Road, Toronto, Ont. M2H 2N7.

Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days. Lessor means a person or entity that is the owner, as reflected on the vehicle title, of any five or more leased vehicles.

We have advised Transport Canada that we are conducting this recall.

Thank you for being a member of the Volvo family. We hope you will appreciate our efforts to continually provide you with updated information of importance to your safety and the quality of your Volvo vehicle.

Sincerely,

Carol Kitchen

V.P. Customer Service

Laketehen



Juin 2011

La Compagnie des Automobiles Volvo du Canada

175, chemin Gordon Baker North York (Ontario) Canada M2H 2N7 Téléphone : 416-493-3700 Télécopieur : 416-496-0552 www.volvocanada.com

AVIS DE RAPPEL IMPORTANT

Madame, Monsieur,

Cet avis vous est envoyé en conformité avec les exigences de la *Loi sur la sécurité automobile*.

Volvo Cars of North America, LLC (Volvo) a décidé de procéder à un rappel de sécurité volontaire sur certaines S60 T5 de l'année-modèle 2012.

Raisons du rappel 245 :

Volvo a déterminé que les dimensions de l'élément mâle du raccord rapide de canalisation à carburant ne sont pas conformes aux spécifications, ce qui peut exercer une pression excessive sur l'élément femelle du raccord et empêcher ainsi le verrouillage du raccord.

Dans un tel cas, il est possible que le raccord rapide de canalisation à carburant se détache et que le moteur cale, ce qui pourrait augmenter les risques d'accident. Le conducteur peut également remarquer une odeur de carburant ou des signes de fuite de carburant. Une fuite de carburant, en présence d'une source d'inflammation, risquerait de provoquer un incendie.

La mesure corrective sera de remplacer les canalisations à carburant.

Ce que vous devez faire :

Veuillez communiquer avec votre concessionnaire Volvo autorisé pour prendre rendez-vous. La réparation sera effectuée gratuitement et devrait prendre jusqu'à 3 heures; toutefois, compte tenu des rendez-vous d'entretien et de la disponibilité des pièces, votre concessionnaire Volvo peut avoir besoin de plus de temps.

Si vous avez déjà payé pour faire effectuer cette réparation, avant la date figurant sur la présente lettre, votre concessionnaire Volvo autorisé vous remboursera sur présentation de votre reçu. Veuillez communiquer avec le service d'entretien de votre concessionnaire Volvo autorisé pour de plus amples renseignements.

Veuillez communiquer:

Pour en savoir plus, veuillez communiquer avec votre concessionnaire Volvo autorisé. Si votre concessionnaire n'est pas en mesure de répondre à vos questions, veuillez communiquer avec le Service à la clientèle de Volvo au 1-800-663-8255 (du lundi au vendredi – de 8 h 30 à 17 h HNE) ou envoyer un courriel à velcust@volvocars.com. Vous pouvez également nous écrire à l'adresse suivante : 175, chemin Gordon Baker, Toronto (Ontario) M2H 2N7.

La loi fédérale exige que tout donneur à bail de véhicule concerné par cet avis de rappel remette dans un délai de dix jours une copie de cet avis au preneur à bail. Par donneur à bail, on entend toute personne ou toute entité qui agit en tant que propriétaire, comme il est indiqué sur le titre du véhicule, de cinq véhicules ou plus faisant l'objet d'un bail.

Nous avons informé Transports Canada que nous mettons en place ce rappel.

Nous vous remercions de faire partie de la famille Volvo. Nous espérons que vous apprécierez nos efforts continus pour vous fournir des renseignements à jour sur des éléments importants pour votre sécurité et pour la qualité de votre véhicule Volvo.

Veuillez agréer, Madame, Monsieur, mes salutations distinguées.

Carol Kitchen

& akitchen

Vice-présidente, Service à la clientèle