



NISSAN NORTH AMERICA, INC.

National Headquarters
Consumer Affairs Department

P.O. Box 685003
Franklin, Tennessee 37068-5003

OWNER NOTIFICATION**NHTSA RECALL 12V-069**

Dear Nissan Juke Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Nissan has decided that a defect which relates to motor vehicle safety exists in 2011-2012 Model year Nissan Juke vehicles. Our records indicate that you own or lease the Nissan vehicle identified by the VIN on the inside of this notice.

Reason for Recall

Nissan recently discovered that on some of the affected vehicles, the fuel pressure sensor connection may not have been tightened to the correct specification. As a result, over time, a small amount of fuel may leak from the fuel pressure sensor connection which could increase the risk of a fire in the presence of an ignition source.

What Nissan Will Do

Your Nissan dealer will check for fuel leakage between the fuel rail pressure sensor and fuel rail. If there is no leakage, the pressure sensor will be retightened to the proper torque specification. If a fuel leak is found, the fuel pressure sensor will be removed, the gasket will be replaced and the entire assembly will be retightened to the proper torque specification. This free service may take up to two hours to complete, but your Nissan dealer may require your vehicle for a longer period of time based upon their work schedule.

What You Should Do

Contact your Nissan dealer at your earliest convenience in order to arrange an appointment to have your vehicle repaired. Please bring this notice with you when you keep your service appointment. **If you notice a fuel smell in the cabin of your vehicle, please bring your vehicle into a Nissan dealer for repair as soon as possible.**

If the dealer fails to, or is unable to make the necessary repairs free of charge, you may contact the National Consumer Affairs Department, Nissan North America, Inc. P.O. Box 685003, Franklin, TN 37068-5003. The toll free number is 1-800-NISSAN1 (1-800-647-7261). You may also submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE., Washington, DC 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

Thank you for your cooperation. We are indeed sorry for any inconvenience this may cause you.



Consumer Affairs

P.O. Box 685003

Franklin, Tennessee 37068-5003

A Division of Nissan North America, Inc.

OWNER NOTIFICATION

NHTSA RECALL 12V-069

Dear QX Owner,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Infiniti has decided that a defect which relates to motor vehicle safety exists in 2011-2012 Model year Infiniti QX vehicles. Our records indicate that you own or lease the Infiniti vehicle identified by the VIN on the inside of this notice.

Reason for Recall

Infiniti recently discovered that on some of the affected vehicles, the fuel pressure sensor connection may not have been tightened to the correct specification. As a result, the fuel pressure sensor connection may loosen gradually. If this occurs, over time, a small amount of fuel may leak from the fuel pressure sensor connection which could increase the risk of a fire in the presence of an ignition source.

What Infiniti Will Do

Your Infiniti dealer will check for fuel leakage between the fuel rail pressure sensor and fuel rail. If there is no leakage, the pressure sensor will be retightened to the proper torque specification. If a fuel leak is found, the fuel pressure sensor will be removed, the gasket will be replaced and the entire assembly will be retightened to the proper torque specification. This free service may take up to two hours to complete, but your Infiniti dealer may require your vehicle for a longer period of time based upon their work schedule.

What You Should Do

Contact your Infiniti retailer at your earliest convenience in order to arrange an appointment to have your vehicle repaired. Please bring this notice with you when you keep your service appointment. Instructions have been sent to your Infiniti dealer. **If you notice a fuel smell in the cabin of your vehicle, please bring your vehicle into a Infiniti dealer for repair as soon as possible.**

If the retailer fails, or is unable to make the necessary repairs free of charge, you may contact the National Consumer Affairs Department, Infiniti Division, Nissan North America, Inc., P.O. Box 685003, Franklin, TN 37068-5003. The toll free number is 1-800-662-6200. You may also submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE., Washington, DC 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

Thank you for your cooperation. We are indeed sorry for any inconvenience this may cause you.



Consumer Affairs
P.O. Box 685003
Franklin, Tennessee 37068-5003
A Division of Nissan North America, Inc.

OWNER NOTIFICATION

NHTSA RECALL 12V-069

Dear M Owner,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Infiniti has decided that a defect which relates to motor vehicle safety exists in 2011-2012 Model year Infiniti M vehicles. Our records indicate that you own or lease the Infiniti vehicle identified by the VIN on the inside of this notice.

Reason for Recall

Infiniti recently discovered that on some of the affected vehicles, the fuel pressure sensor connection may not have been tightened to the correct specification. As a result, the fuel pressure sensor connection may loosen gradually. If this occurs, over time, a small amount of fuel may leak from the fuel pressure sensor connection which could increase the risk of a fire in the presence of an ignition source.

What Infiniti Will Do

Your Infiniti dealer will check for fuel leakage between the fuel rail pressure sensor and fuel rail. If there is no leakage, the pressure sensor will be retightened to the proper torque specification. If a fuel leak is found, the fuel pressure sensor will be removed, the gasket will be replaced and the entire assembly will be retightened to the proper torque specification. This free service may take up to two hours to complete, but your Infiniti dealer may require your vehicle for a longer period of time based upon their work schedule.

What You Should Do

Contact your Infiniti retailer at your earliest convenience in order to arrange an appointment to have your vehicle repaired. Please bring this notice with you when you keep your service appointment. Instructions have been sent to your Infiniti dealer. **If you notice a fuel smell in the cabin of your vehicle, please bring your vehicle into a Infiniti dealer for repair as soon as possible.**

If the retailer fails, or is unable to make the necessary repairs free of charge, you may contact the National Consumer Affairs Department, Infiniti Division, Nissan North America, Inc., P.O. Box 685003, Franklin, TN 37068-5003. The toll free number is 1-800-662-6200. You may also submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE., Washington, DC 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

Thank you for your cooperation. We are indeed sorry for any inconvenience this may cause you.