BMW



January 2013

Recall Campaign No. 12V-550: Engine Belt Idler Pulley Bolt

Dear BMW Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

BMW AG has decided that a defect, which relates to motor vehicle safety, exists in certain Model Year 2009-2012 BMW X5 xDrive 35d (Diesel) Sports Activity Vehicles. Our records indicate that you are the owner of a potentially affected vehicle.

We sincerely apologize for any inconvenience this may cause you.

DESCRIPTION OF PROBLEM

This Recall involves the engine belt idler pulley bolt. The engine belt idler pulley bolt can loosen. Over time, loosening of the bolt could lead to additional bending forces on the bolt. Eventually, these additional forces could cause the bolt to break. This would result in a sudden loss of power steering assist, increasing the risk of a crash.

DESCRIPTION OF REPAIR

The idler pulley bolt will be replaced and tightened with a revised procedure. A thread lock coating on the bolt will also be included.

The actual repair will require approximately two hours; however, additional time may be required, depending on the BMW center's schedule. This work will be performed free of charge by your authorized BMW center.

Company BMW of North America, LLC

BMW Group Company

Mailing address PO Box 1227 Westwood, NJ

Westwood, NJ 07675-1227

Telephone (800) 525-7417

Fax (201) 930-8362

E-mail customer.relations@ bmwusa.com

> Website Ibmwusa.com

PRECAUTIONS FOR YOUR SAFETY

- CONTACT YOUR AUTHORIZED BMW CENTER IMMEDIATELY TO HAVE THE NECESSARY REPAIR PERFORMED AS SOON AS POSSIBLE.
- If there is a sudden loss of power steering assist, manual steering capability is still retained, although additional effort will be required to steer the vehicle.
- 3. If there is a sudden loss of power steering assist, the alternator warning lamp (the battery symbol) will illuminate in the vehicle's instrument cluster, along with the warning message "Charging malfunction." The message "Charging malfunction:

Battery is not recharging. Stop carefully. Consult nearest service center." will also be displayed.

- 4. If you experience a loss of power steering assist, carefully move away from traffic and pull over to a safe location as soon as possible. Do not continue to drive your vehicle. Contact BMW Roadside Assistance at 1-800-332-4269 immediately to have your vehicle brought to the nearest authorized BMW center.
- 5. If you are not the only driver of this vehicle, please advise all other drivers and passengers of this important information.

OTHER INFORMATION

Should you need BMW Roadside Assistance, they can be contacted at 1-800-332-4269.

If you are no longer the owner of this vehicle, we would appreciate your furnishing us with the name and address of the new owner, using the enclosed postage-paid card.

If you are a lessor of this vehicle, Federal Regulations require you to forward this notice to your lessee within ten days.

If you have already had this repair performed at your own expense, please see the attachment regarding possible eligibility for reimbursement.

Should you have any questions about this campaign, please contact your authorized BMW center.

Again, we sincerely apologize for any inconvenience this may cause you.

We appreciate your confidence in our product, and we wish to do everything we can to retain your confidence. Should you need additional assistance, you may contact BMW Customer Relations and Services at 1-800-525-7417, or via email at CustomerRelations@bmwusa.com.

If the BMW center is unable to remedy the defect without charge or within a reasonable period of time, you may notify the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave., S.E., Washington, DC 20590; call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to http://www.safercar.gov.

BMW recommends that you always wear your safety belt, and that all passengers are properly seated and restrained at all times.

BMW OF NORTH AMERICA, LLC

TREAD ACT CUSTOMER REIMBURSEMENT PLAN (BMW of North America, LLC)

If you have paid for the repair described in the attached letter, and you would like to be considered for reimbursement, please contact your authorized BMW center. Expenses from repair facilities outside of the BMW center network will be considered; however, the procedure must meet BMW standards.

Your authorized BMW center will request a copy of your owner notification letter, as well as, a copy of your previously paid invoice, and then inspect the vehicle (if it is still in your possession) prior to submitting a claim on your behalf to BMW of North America, LLC for reimbursement.

Please note the following:

- Only a repair that is the subject of this safety recall is reimbursable.
 Consequential expenses such as towing, rental, accommodations, damage repairs, etc will not be reimbursed.
- The Manufacturer's Suggested Retail Price (MSRP) for BMW Genuine Parts will be considered as the guideline for reasonable charges.
- Expenses for repairs performed more than 10 days after the date of the last owner notification letter sent by BMW are not eligible for reimbursement.
- Taxes and hazardous waste disposal, where previously paid, are eligible for reimbursement.

We anticipate that your authorized BMW center will be able to answer any questions that you may have regarding your qualifications for reimbursement of a previous repair. If you qualify for such a reimbursement, they will also be able to advise you of the manner in which you could receive reimbursement.

We recommend that your authorized BMW center be your primary contact on this issue; however, our Customer Relations and Services Department may be contacted at 1-800-831-1117 for any special assistance that you may require.

Alternatively, you may submit your request for reimbursement to the following address:

Customer Relations and Services Department BMW of North America, LLC P.O. Box 1227 Westwood, NJ 07675-1227