



NISSAN NORTH AMERICA, INC.

Corporate Office
P.O. Box 685001
Franklin, TN 37068-5001
Telephone 615.725.1000

OWNER NOTIFICATION

NHTSA RECALL 13V-139

Dear Nissan Pathfinder Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Nissan has decided that a defect that relates to motor vehicle safety exists in some 2013 model year Nissan Pathfinder vehicles. Our records indicate that you own or lease the Nissan vehicle identified by the VIN on the inside of this notice.

Reason for Recall

On some model year 2013 Nissan Pathfinder vehicles, the front brake torque members may crack due to improper manufacturing. This condition could cause the front brake caliper to separate and contact the wheel which could result in reduced braking function and steering control and/or an air leak from the tire. If this occurs, it may increase the risk of a crash. Although this could occur without warning, a noticeable noise or vibration from the front wheels may indicate that your vehicle is affected.

What Nissan Will Do

Your Nissan dealer will inspect the driver and passenger side front torque brake members to determine if the parts are within the affected population range. The free inspection service should take less than an hour to complete. If necessary, one or both of the front brake torque members will be replaced with new, correct ones. If it is necessary to replace the part, the amount of time required to complete the service may take up to two hours. This repair is free of charge to you for parts and labor. Please note that your Nissan dealer may require your vehicle for a longer period of time based upon their work schedule, or parts availability.

What You Should Do

Contact your Nissan dealer at your earliest convenience in order to arrange an appointment to have your vehicle inspected. **If you hear a noticeable noise or feel a vibration from the front wheels, stop driving your vehicle and contact your dealer as soon as possible to have the vehicle inspected.** Please bring this notice with you when you keep your service appointment.

If the dealer fails, or is unable to make the necessary repairs free of charge, you may contact the National Consumer Affairs Department, Nissan North America, Inc. P.O. Box 685003, Franklin, TN 37068-5003. The toll free number is 1-800-NISSAN1 (1-800-647-7261). You may also submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE., Washington, DC 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

Thank you for your cooperation. We are indeed sorry for any inconvenience this may cause you.



Consumer Affairs

P.O. Box 685003

Franklin, Tennessee 37068-5003

A Division of Nissan North America, Inc.

OWNER NOTIFICATION

RECALL NUMBER 13V-139

Dear Infiniti JX35 Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Infiniti has decided that a defect that relates to motor vehicle safety exists in some 2013 model year Infiniti JX35 vehicles. Our records indicate that you own or lease the Infiniti vehicle identified by the VIN on the inside of this notice.

Reason for Recall

On some model year 2013 Infiniti JX35 vehicles, the front brake torque members may crack due to improper manufacturing. This condition could cause the front brake caliper to separate and contact the wheel which could result in reduced braking function and steering control and/or an air leak from the tire. If this occurs, it may increase the risk of a crash. Although this could occur without warning, a noticeable noise or vibration from the front wheels may indicate that your vehicle is affected.

What Infiniti Will Do

Your Infiniti retailer will inspect the driver and passenger side front torque brake members to determine if the parts are within the affected population range. The free inspection service should take less than an hour to complete. If necessary, one or both of the front brake torque members will be replaced with new, correct ones. If it is necessary to replace the part, the amount of time required to complete the service may take up to two hours. This repair is free of charge to you for parts and labor. Please note that your Infiniti retailer may require your vehicle for a longer period of time based upon their work schedule, or parts availability.

What You Should Do

Contact your Infiniti retailer at your earliest convenience in order to arrange an appointment to have your vehicle inspected. **If you hear a noticeable noise or feel a vibration from the front wheels, stop driving your vehicle and contact your retailer as soon as possible to have the vehicle inspected.** Please bring this notice with you when you keep your service appointment.

If the retailer fails, or is unable to make the necessary repairs free of charge, you may contact the National Consumer Affairs Department, Infiniti Division, Nissan North America, Inc., P.O. Box 685003, Franklin, TN 37068-5003. The toll free number is 1-800-662-6200. You may also submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE., Washington, DC 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

Thank you for your cooperation. We are indeed sorry for any inconvenience this may cause you.