



U.S. Department of Transportation  
**National Highway Traffic Safety  
Administration**

1200 New Jersey Avenue SE  
Washington, DC 20590

November 17, 2014

Mr. John Kobylarz  
Automotive Safety Office  
Jaguar Land Rover North America, LLC  
555 MacArthur Boulevard  
Mahwah, NJ 07430

NVS-215SM  
14V-618

**Subject:** TPMS may not Locate Sensors

Dear Mr. Kobylarz:

This letter serves to acknowledge Jaguar Land Rover North America, LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

**Makes/Models/Model Years:**

LAND ROVER/LR4/2013-2014  
LAND ROVER/RANGE ROVER/2014  
LAND ROVER/RANGE ROVER SPORT/2014

**Mfr's Report Date:** October 13, 2014

**NHTSA Campaign Number:** 14V-618

**Components:**

TIRES:PRESSURE MONITORING AND REGULATING SYSTEMS

**Potential Number of Units Affected:** 28,037

**Problem Description:**

Jaguar Land Rover North America, LLC (Land Rover) is recalling certain model year 2014 Range Rover and Range Rover Sport and 2013-2014 LR4 vehicles manufactured September 16, 2013, to June 30, 2014. In the affected vehicles, the Tire Pressure Monitoring System (TPMS) may fail to learn the locations of the individual sensors while the vehicle is being driven. As a result, the low tire pressure warning light will illuminate, despite the the tire pressures being within specification. Should one of the tires subsequently lose air pressure, the driver would not be notified of the change in air pressure.

**Consequence:**

If the TPMS light illuminates because the sensors cannot be located, it could mask an actual low tire pressure condition, possibly resulting in tire failure, increasing the risk of a crash.

**Remedy:**

Land Rover will notify owners, and dealers will update the Body Control Module (BCM) software, free of charge. The recall is expected to begin on December 1, 2014. Owners may contact Land Rover customer service at 1-800-637-6837, Option 9. Land Rover's number for this recall is P050.

**Notes:**

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to [www.safercar.gov](http://www.safercar.gov).

Please revise your Defect Information Report to have the 'Chronology' section conclude at the beginning of the 'Description of Remedy' section.

We have received a draft owner letter for this recall and have approved it for distribution.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Sarah Mcshane who may be reached by phone at 202-366-7401, or by email at [sarah.mcshane@dot.gov](mailto:sarah.mcshane@dot.gov) or through the office email at [rmd.odi@dot.gov](mailto:rmd.odi@dot.gov). We look forward to working with you.

Sincerely,



Jennifer Timian  
Chief, Recall Management Division  
Office of Defects Investigations  
Enforcement