

Part 573 Safety Recall Report**14V-563****Manufacturer Name :** Honda (American Honda Motor Co.)**Submission Date :** SEP 12,2014**NHTSA Recall No. :** 14V-563**Manufacturer Recall No. :** JF9**Manufacturer Information :**

Manufacturer Name : Honda (American Honda Motor Co.)

Address : 1919 Torrance Blvd.

Torrance CA 90501

Company phone : 310-783-2000

Population :

Number of potentially involved : 6,292

Estimated percentage with defect : 0

Vehicle Information :

Vehicle : 2015-2015 Honda Fit

Vehicle Type : LIGHT VEHICLES

Body Style : HATCHBACK

Power Train : GAS

Descriptive Information : The recall population was determined based on manufacturing records. The VIN range reflects all possible vehicles that could potentially experience the problem.

Production Dates : APR 11, 2014 - JUN 09, 2014

VIN (Vehicle Identification Number) Range

Begin : 3HGK5H84FM704547

End : 3HGK5H84FM712888

 Not sequential VINs**Description of Defect :**

Description of the Defect : During vehicle assembly it is possible that the A-pillar interior cover designed for vehicles without side curtain airbags may have been installed on vehicles that contain side curtain airbags.

Description of the Safety Risk : An incorrect A-pillar interior cover could alter the performance of the side curtain airbag during deployment, potentially increasing the risk of injury during a crash.

Description of the Cause : NR**Identification of Any Warning that can Occur :** NR

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

June 3, 2014

Honda Mexico Service notified HDM of one incorrectly assembled A-pillar interior cover.

June 6-14, 2014

HDM vehicle inspection produced 6 vehicles in-house and 1 vehicle at the shipping port with an incorrect A-pillar.

June 16-18, 2014

HDM continued inspection of vehicles in transport and did not find any incorrectly assembled vehicles.

July 23, 2014

Honda determined that a safety defect exists and decided to conduct a safety recall.

As of July 23, 2014, Honda has not received any reports of claims or injuries related to this issue.

Description of Remedy :

Description of Remedy Program : The owners of all affected vehicles will be contacted by mail and asked to take their vehicle to a Honda automobile dealer. The dealer will inspect and if necessary install the correct A-pillar interior cover free of charge

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : JUL 30, 2014 - JUL 31, 2014

Planned Owner Notification Date : SEP 25, 2014 - SEP 25, 2014

* NR - Not Reported