

Part 573 Safety Recall Report**14V-816****Manufacturer Name :** Porsche Cars North America, Inc.**Submission Date :** JUN 15,2015**NHTSA Recall No. :** 14V-816**Manufacturer Recall No. :** AF01**Manufacturer Information :**

Manufacturer Name : Porsche Cars North America, Inc.

Address : 980 Hammond Drive
Suite 1000 Atlanta GA 30328

Company phone : (770) 290-3500

Population :

Number of potentially involved : 39

Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2015-2015 Porsche 918

Vehicle Type : LIGHT VEHICLES

Body Style : 2-DOOR

Power Train : HYBRID ELECTRIC

Descriptive Information : Replacing Front Lower Suspension Control Arms

Production Dates : FEB 25, 2014 - SEP 18, 2014

VIN (Vehicle Identification Number) Range

Begin : WPOCA2A1XFS800024

End : WPOCA2A14FS800911

 Not sequential VINs**Description of Defect :**

Description of the Defect : Internal testing has revealed that the lower control arms of the front axle, produced in a particular production batch, contain a manufacturing error. Due to the manufacturing error the durability of these components installed in the affected vehicles cannot be guaranteed.

FMVSS 1 :NR

FMVSS 2 :NR

Description of the Safety Risk : Due to the manufacturing error the durability of these components installed in the affected vehicles cannot be guaranteed.

Description of the Cause : Internal testing has revealed that the lower control arms of the front axle, produced in a particular production batch, contain a manufacturing error.

Identification of Any Warning that can Occur : None.

Supplier Identification :**Component Manufacturer**

Name : Hirschmann GmbH

Address : Kirchentannenstrasse 9

Fluorn-Winzel FOREIGN STATES 78737

Country : Germany

Chronology :

Please refer to our letter submitted with this notification.

Description of Remedy :

Description of Remedy Program : The affected components from the defective batch will be replaced. Due to safety concerns, Porsche will recommend to customers that the affected vehicles not be driven until the recall remedy has been completed. The repair parts for the recall are scheduled to be ready at the end of February 2015.

How Remedy Component Differs from Recalled Component : To be determined.

Identify How/When Recall Condition was Corrected in Production : To be determined.

Recall Schedule :

Description of Recall Schedule : To be determined.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported