



After-sales Retailer Support

2011-2015 Infiniti QX56/QX80 and 2011-2015 M56/Q70

Fuel Pressure Sensor – Rental & Parts Update

Reference: R1417
Date: January 30, 2015

Attention: Retailer Principal, Sales, Parts and Service Managers

******* Retailer Announcement *******

On December 23rd Infiniti retailers were advised that parts were not readily available. This announcement is to let retailers know that the parts situation is expected to be resolved mid to late February and that rental is available under the campaign until parts are readily available.

******* What Retailers Should Do *******

1. Continue to verify the subject vehicle is affected by this recall campaign using Service Comm I.D. R1417.
2. Continue to repair all vehicles in inventory prior to sale **using the previously provided interim repair procedure.**
3. Continue to order parts for client vehicles only as outlined in the previously provided procedure.

NOTE: If campaign parts are not immediately available, the vehicle can be driven **provided there are no fuel leaks or vapor smell present.** If necessary, a campaign provision for rental is available until parts are available.

EXPENSE CODE	DESCRIPTION	AMOUNT
502	Rental Expense	\$60 (per day)