

Representative Letter – Customer letters are brand, model and model year specific; listing the 17-digit VIN and are personalized.



IMPORTANT SAFETY RECALL

July 2014

Dear General Motors Customer:

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

General Motors has decided that a defect which relates to motor vehicle safety exists in all 2004-2012 model year (MY) Chevrolet Malibu, 2004-2007 MY Chevrolet Malibu Maxx, 2005-2010 MY Pontiac G6 and 2007-2010 MY Saturn Aura vehicles. As a result, GM is conducting a recall. We apologize for this inconvenience. However, we are concerned about your safety and continued satisfaction with our products.

IMPORTANT

- This notice applies to your 2004-2012 model year (MY) Chevrolet Malibu, 2004-2007 MY Chevrolet Malibu Maxx, 2005-2010 MY Pontiac G6 and 2007-2010 MY Saturn Aura vehicle, **VIN:**
_____.
- Your vehicle is involved in GM recall 13036.
- **Parts are not currently available to repair your vehicle.**
- When parts become available, GM will notify you to schedule an appointment with your dealer.

Why is your vehicle being recalled?

On these vehicles, over time an increased resistance can develop in the Body Control Module (BCM) connection system and result in voltage fluctuations or intermittency in the Brake Apply Sensor (BAS) circuit that can cause service brake lamp malfunction. As a result, the service brake lamps may illuminate when the service brakes are not being applied, or may not illuminate when the service brakes are being applied. Additionally, cruise control may not engage. If cruise control is engaged, additional service brake pedal travel may be required to disengage it. Service brake pedal application may not be required to move the shift lever out of PARK, or additional service brake pedal travel may be required to move the shift lever out of PARK. Traction Control, Electronic Stability Control (ECS), and panic braking assist features, if equipped, may be disabled. Service ESC and/or Traction Control tell-tales lights may illuminate with this condition. These conditions may increase the risk of a crash.

What will we do?

PARTS ARE NOT CURRENTLY AVAILABLE, but when parts are available, your GM dealer will attach the wiring harness to the BCM or mag beam, apply dielectric lubricant to both the BCM and

harness connector and on the BAS and harness connector, and relearn the brake pedal home position. This service will be performed for you at **no charge**.

We are working as quickly as possible to correct this condition. When parts are available, we will send you another letter asking you to take your vehicle to your GM dealer to have your vehicle serviced. If you have already paid for repairs for this condition, a reimbursement request form will be included with the letter.

What should you do?

When GM notifies you that parts are available, you should contact your GM dealer to arrange a service appointment.

Do you have questions?

If you have questions or concerns that your dealer is unable to resolve, please contact the appropriate Customer Assistance Center at the number listed below.

Division	Number	Text Telephones (TTY)
Chevrolet	1-800-222-1020	1-800-833-2438
Pontiac	1-800-762-2737	1-800-833-7668
Saturn	1-800-553-6000	1-800-833-6000
Guam	65-6267-1752	
Puerto Rico – English	1-800-496-9992	
Puerto Rico – Español	1-800-496-9993	
Virgin Islands	1-800-496-9994	

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

Jim Moloney
General Director,
Customer and Relationship Services

GM Recall Number: 13036