

Recall Bulletin



PRODUCT SAFETY RECALL

SUBJECT: Long Brake Pedal Travel and/or Reduced Brake Performance

MODELS: 2007 Chevrolet Optra 2009-2010 Chevrolet Aveo 2009 Pontiac G3, Wave Equipped with ABS Brakes (JM4/JL9)

Vehicles involved in Customer Satisfaction Program 12189 that have not had the repair performed on the vehicle have been transferred to this safety recall.

It is a violation of Federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by this notification under a sale or lease until the defect or noncompliance is remedied.

<u>CONDITION</u>

General Motors has decided that a defect which relates to motor vehicle safety exists in certain 2009-2010 MY Chevrolet Aveo and 2009 MY Pontiac G3 vehicles. Certain vehicles equipped with ABS brakes (JM4/JL9), may contain brake fluid that does not inhibit corrosion in the zinc plating on the anti-lock brake system (ABS) module valve armature. Corrosion may lead to a gel build up on the sides of the valve, which could affect the closing motion of the valve. This could result in longer brake pedal travel and/or reduced brake performance, and in rare cases, vehicle instability and a rear wheel lock condition, which may increase the risk of a crash.

CORRECTION

Dealers are to inspect the ABS module and, if necessary, replace the module. Dealers are to also change the brake fluid and provide a supplement to the Owner Manual that instructs customers to use only GM recommended brake fluid.

VEHICLES INVOLVED

All involved vehicles are identified by Vehicle Identification Number on the Investigate Vehicle History screen in GM Global Warranty Management system. Dealership service personnel should always check this site to confirm vehicle involvement prior to beginning any required inspections and/or repairs. It is important to routinely use this tool to verify eligibility because not all similar vehicles may be involved regardless of description or option content. For dealers with involved vehicles, a listing with involved vehicles containing the complete vehicle identification number, customer name, and address information has been prepared and will be provided to US and Canadian dealers through the GM GlobalConnect Recall Reports, or sent directly to export dealers. Dealers will not have a report available if they have no involved vehicles currently assigned.

The listing may contain customer names and addresses obtained from Motor Vehicle Registration Records. The use of such motor vehicle registration data for any purpose other than follow-up necessary to complete this recall is a violation of law in several states/provinces/countries. Accordingly, you are urged to limit the use of this report to the follow-up necessary to complete this recall.

PART INFORMATION

Due to the small number of vehicles expected to require replacement of the ABS module, modules can only be ordered from the Product Quality Center (PQC) when the inspection determines that it is necessary to replace the module. Orders placed without PQC approval will automatically cancel.

Brake fluid and engine coolant, if required, are to be obtained from General Motors Customer Care and Aftersales (GMCC&A). Please refer to your "involved vehicles listing" before ordering parts. Normal orders should be placed on a DRO = Daily Replenishment Order. In an emergency situation, parts should be ordered on a CSO = Customer Special Order.

Part Number	Description	Quantity/Vehicle
95241314	MODULE KIT, ELEK BRK CONT	1
	(Aveo, G3, Wave)	
95242007	MODULE KIT, ELEK BRK CONT	1
	(Optra)	
19299818 – US	BRAKE FLUID	4
19299819 - CN		
10953031	FLUID, EXTENDED LIFE ENG COOLANT	1
	(Optra)	

SERVICE PROCEDURE

Tech 2 Tool Update


Ensure that your Tech 2 is updated with software version 32.005 or higher. You can obtain this in the Software Download section of TIS2Web.

ABS Module Inspection

- 1. Park the vehicle on a flat, level surface.
- 2. Apply the parking brake.
- 3. Connect scan tool.




4. Select "F1: ABS Check" in Special Functions.



5. Start ABS valve check.




6. The Waiting for Data screen will appear.



While this screen is displayed, the pump motor is running (1sec).

7. The "Procedure in Progress" message will appear on the ABS Check screen.



When the Tech 2 screen is prompted to "Apply and Hold the Brake Pedal," the technician should apply and hold heavy brake force during ABS Check.




With the valve open, the pedal will drop for 2 seconds. With the motor pumping, the pedal will push back for 3 seconds.

Note: The Tech 2 test sequence is left front, right front, left rear and right rear during steps 8 through 23.

 If the ABS/ESC module test passes all 4 procedures (4 pedal drops and 4 push backs are "YES"), replace the brake fluid with Delco Supreme 11 Brake Fluid (P/N 19299818 USA, P/N 19299819 Canada). Flush the brake system. Refer to *Brake Valve Cycling* in this bulletin and proceed to *Brake Valve Cycling* on the Tech 2.


- If any of the answers are "NO", replace the ABS/ESC HCU and brake fluid with Delco Supreme 11 Brake Fluid (P/N 19299818 USA, P/N 19299819 Canada). Refer to Chevrolet Optra Brake Pressure Modulator Replacement or Chevrolet Aveo, Pontiac G3 and Pontiac Wave Brake Pressure Modulator Replacement in this bulletin.
- 8. Apply and hold brake pedal.




- 9. Answer the question on the ABS Check screen.
 - If the answer is yes, proceed to the next step.
 - If the answer is no, proceed to Chevrolet Optra Brake Modulator Replacement or Chevrolet Aveo, Pontiac G3 and Pontiac Wave Brake Modulator Replacement in this bulletin.

	ABS CI	neck]
Did you fe			brake	pedal	
	push l	back?			
	Yes	No			
					2915756

- 10. Answer the question on the ABS Check screen.
 - If the answer is yes, proceed to the next step.
 - If the answer is no, proceed to Chevrolet Optra Brake Modulator Replacement or Chevrolet Aveo, Pontiac G3 and Pontiac Wave Brake Modulator Replacement in this bulletin.




11. The ABS Check screen will instruct you to release the brake pedal.



While this screen is displayed, the pump motor is running (1sec).

12. The "Procedure in Progress" message will appear on the ABS Check screen.




When the Tech 2 screen is prompted to "Apply and Hold the Brake Pedal," the technician should apply and hold heavy brake force during ABS Check.



With the valve open, the pedal will drop for 2 seconds. With the motor pumping, the pedal will push back for 3 seconds.

13. Apply and hold brake pedal.




- 14. Answer the question on the ABS Check screen.
 - If the answer is yes, proceed to the next step.
 - If the answer is no, proceed to Chevrolet Optra Brake Modulator Replacement or Chevrolet Aveo, Pontiac G3 and Pontiac Wave Brake Modulator Replacement in this bulletin.

Did you feel significant brake pedal push back?
Yes No 29157

- 15. Answer the question on the ABS Check screen.
 - If the answer is yes, proceed to the next step.
 - If the answer is no, proceed to Chevrolet Optra Brake Modulator Replacement or Chevrolet Aveo, Pontiac G3 and Pontiac Wave Brake Modulator Replacement in this bulletin.




16. The ABS Check screen will instruct you to release the brake pedal.



2915750

While this screen is displayed, the pump motor is running (1sec).

17. The "Procedure in Progress" message will appear on the ABS Check screen.



When the Tech 2 screen is prompted to "Apply and Hold the Brake Pedal," the technician should apply and hold heavy brake force during ABS Check.






With the valve open, the pedal will drop for 2 seconds. With the motor pumping, the pedal will push back for 3 seconds.

18. Apply and hold brake pedal.

ABS Check	
Did you feel significant brake ped travel (drop)?	al
Yes No	
	291575


- 19. Answer the question on the ABS Check screen.
 - If the answer is yes, proceed to the next step.
 - If the answer is no, proceed to Chevrolet Optra Brake Modulator Replacement or Chevrolet Aveo, Pontiac G3 and Pontiac Wave Brake Modulator Replacement in this bulletin.



- 20. Answer the question on the ABS Check screen.
 - If the answer is yes, proceed to the next step.
 - If the answer is no, proceed to Chevrolet Optra Brake Modulator Replacement or Chevrolet Aveo, Pontiac G3 and Pontiac Wave Brake Modulator Replacement in this bulletin.




21. The ABS Check screen will instruct you to release the brake pedal.



2915750

While this screen is displayed, the pump motor is running (1sec).

22. The "Procedure in Progress" message will appear on the ABS Check screen.



When the Tech 2 screen is prompted to "Apply and Hold the Brake Pedal," the technician should apply and hold heavy brake force during ABS Check.



With the valve open, the pedal will drop for 2 seconds. With the motor pumping, the pedal will push back for 3 seconds.

23. Apply and hold brake pedal.

ABS (Check		
Did you feel sign travel	ificant bra (drop)?	ke pedal	
Yes	No	,	
			291575

- 24. Answer the question on the ABS Check screen.
 - If the answer is yes, proceed to the next step.
 - If the answer is no, proceed to Chevrolet Optra Brake Modulator Replacement or Chevrolet Aveo, Pontiac G3 and Pontiac Wave Brake Modulator Replacement in this bulletin.

ABS C	Check]
Did you feel signi	ificant brake pedal	
push	back?	
Yes	No	2915756

- 25. Answer the question on the ABS Check screen.
 - If the answer is yes, proceed to the next step.
 - If the answer is no, proceed to Chevrolet Optra Brake Modulator Replacement or Chevrolet Aveo, Pontiac G3 and Pontiac Wave Brake Modulator Replacement in this bulletin.



26. The ABS Check screen will instruct you to release the brake pedal.

ABS Check	
Procedure Passed	
Refer to the Service Manual for additional instructions and information.	
Press [EXIT] to continue.	
	2915767

27. The "Procedure Passed "message will appear on the ABS Check screen.

Brake Valve Cycling

Warning: Brake fluid may irritate eyes and skin. In case of contact, take the following actions:

- Eye contact—rinse thoroughly with water.
- Skin contact—wash with soap and water.
- If ingested—consult a physician immediately.


Warning: During the Brake Valve Cycling procedure, battery shortage may occur. It is recommended you connect secondary power supply to battery for battery shortage prevention.


- 1. Connect required brake bleeding equipment.
- 2. Raise and support vehicle. Refer to Lifting and Jacking the Vehicle in SI.
- 3. Remove all tire and wheel assemblies. Refer to *Tire and Wheel Removal and Installation* in SI.
- 4. Drain brake fluid from the brake system.

Note: Fill the master cylinder reservoir with brake fluid. Keep the master cylinder at least 1/2 full of fluid during the brake bleeding operation. Fill brake system with Delco Supreme 11 Brake Fluid (P/N 19299818 USA, P/N 19299819 Canada).


5. Bleed the brake system. (DO NOT perform air bleeding through scan tool). Refer to *Hydraulic Brake System Bleeding* in SI.

6. Connect scan tool.





7. Select "F2.Special Functions" and then Select "F2.Brake Valve Cycling".



8. Start brake valve cycling.



This screen displays when the Tech 2 is starting to communicate with the vehicle.


9. Waiting for data.

Brake Valve Cycl:	ing
* Procedure in Progr	cose *
* FLOCEDULE IN FLOSI	633 ×
	29157

10. The "Procedure in Progress" message will appear from the Brake Valve Cycling screen.

	0		0	
Brake	Valve	e Cycl	ing	
Apply and	hold	Brake	Pedal.	
				291577

11. The "Apply and Hold Brake Pedal" message will appear from the Brake Valve Cycling screen.




The auto brake valve cycling process will run for 25 seconds. A little pedal down/up will occur during the process.

12. The "Procedure in Progress" message will appear from the Brake Valve Cycling screen.

Note: Perform base brake bleed for **ONLY the front wheel circuits** after each loop has been completed. Open each front caliper bleeder valve 1 time for 1-2 seconds and then close it. This will only extract a very small quantity of brake fluid from each front caliper. Then proceed to the next loop or count. Repeat steps 11 -13 until the 10th loop has been counted. **The procedure is automatic; the procedure will only complete 10 loops and then stop.**

Brake Valve Cycling	
Release Brake Pedal	
Refer to the service information for additional instructions and perform a base brake bleed.	
When the base brake bleed is complete select [Restart]	
Restart	2915775

13. The "Release Brake Pedal" message will appear from the Brake Valve Cycling screen.



- 14. The "Procedure Complete" message will appear on the Brake Valve Cycling screen.
- 15. To ensure the brake system is functioning properly, perform the ABS Module Inspection procedure again. Refer to ABS Module Inspection in this bulletin.


Chevrolet Optra Brake Pressure Modulator Replacement

Warning: Brake fluid may irritate eyes and skin. In case of contact, take the following actions:


- Eye contact—rinse thoroughly with water.
- Skin contact—wash with soap and water.
- If ingested—consult a physician immediately.

Removal Procedure

- 1. Drain the brake fluid from the brake system.
- 2. Turn the ignition switch to the OFF position.
- 3. Drain the engine coolant to below the level of the surge tank.
- 4. Loosen the return hose clamp and disconnect the return hose from the top of the surge tank.
- 5. Loosen the throttle body hose clamp and disconnect the throttle body hose from the top of the surge tank.




- 6. Loosen the feed hose clamp and disconnect the feed hose from the bottom of the surge tank.
- 7. Remove the surge tank attaching bolt.



8. Remove the surge tank from the support mount.


Warning: Wear safety glasses in order to avoid eye damage.

9. Clean the brake modulator assembly pipe fitting areas of any accumulated dirt and foreign material.




- 10. Disconnect the electrical connector from the electronic brake control module (EBCM).
- 11. Place a shop towel under the brake modulator assembly to catch any brake fluid loss.


Note: Prior to disconnecting the brake pipes from the antilock brake system (ABS) modulator assembly, note the locations of the brake pipes to the valve assembly, to aid during installation.




- 12. Disconnect the brake pipe fitting nuts from the brake pressure modulator valve (BPMV).
- 13. Cap the brake pipe ends to prevent brake fluid loss and contamination.
- 14. Plug the modulator brake pipe openings to prevent brake fluid loss and contamination.
- 15. Remove the mounting bracket bolt and nuts from the body panel.



16. Remove the brake modulator assembly to the mounting bracket damping bolts.



17. Remove the ABS module from bracket.



18. Remove the mounting pins from ABS module.





- 19. Remove the HCU from EBCM. (ABS: 3 bolts, ESC: 4 bolts).
- 20. Install new HCU onto EBCM. Tighten the mounting bolts to 1.8 Nm (16 lb-in).
- 21. Install the mounting pins from ABS module. Tighten mounting pins: 8 Nm (6 lb-ft).
- 22. Install the brake modulator assembly to the modulator bracket. Tighten mounting bolts: 8 Nm (6 lb–ft).
- 23. Install the damping bolts to the brake modulator assembly. Tighten the damping bolts to the brake modulator assembly to 11 N.m (8 lb–ft).
- 24. Install the brake modulator assembly with the mounting bracket attached to the body panel. Tighten the mounting bracket bolt and nuts to 22 Nm (16 lb-ft).
- 25. Remove the caps from the master cylinder brake pipe ends.
- 26. Remove the plugs from the master cylinder ports on the modulator assembly.
- 27. Connect the master cylinder brake pipes to the modulator assembly, in the same location as removed.
- 28. Tighten the brake pipe fittings nuts. Tighten the fitting nuts to 16 Nm (12 lb-ft).
- 29. Connect the electrical connector to the EBCM.

Note: Refill coolant in the reservior tank properly. It may need about one liter.

30. Install the engine coolant reservior tank.


Note: Fill the master cylinder reservoir with brake fluid. Ensure the master cylinder is at least 1/2 full of fluid during the brake bleeding operation. Fill brake system with Delco Supreme 11 Brake Fluid (P/N 19299818 USA, P/N 19299819 Canada).

31. Bleed the brake system. Refer to Hydraulic Brake System Bleeding in SI.

Chevrolet Aveo, Pontiac G3 and Pontiac Wave Brake Pressure Modulator Replacement

Warning: Brake fluid may irritate eyes and skin. In case of contact, take the following actions:


- Eye contact—rinse thoroughly with water.
- Skin contact—wash with soap and water.
- If ingested—consult a physician immediately.
- 1. Drain the brake fluid from the brake system.



1241628


Warning: Unless directed otherwise, the ignition and start switch must be in the OFF or LOCK position, and all electrical loads must be OFF before servicing any electrical component. Disconnect the negative battery cable to prevent an electrical spark should a tool or equipment come in contact with an exposed electrical terminal. Failure to follow these precautions may result in personal injury and/or damage to the vehicle or its components. For Vehicles equipped with OnStar® (UE1) with Back Up Battery: The Back Up Battery is a redundant power supply to allow limited OnStar® functionality in the event of a main vehicle battery power disruption to the VCIM (OnStar® module). Do not disconnect the main vehicle battery or remove the OnStar® fuse with the ignition key in any position other than OFF. Retained accessory power (RAP) should be allowed to time out or be disabled (simply opening the driver door should disable RAP) before disconnecting power. Disconnecting power to the OnStar® module in any way while the ignition is On or with RAP activated may cause activation of the OnStar® Back-Up Battery (BUB) system and will discharge and permanently damage the back-up battery. Once the Back-Up Battery is activated it will stay on until it has completely discharged. The BUB is not rechargeable and once activated the BUB must be replaced.

- 2. Disconnect the negative battery cable and then disconnect the positive battery cable.
- 3. Remove the nuts from the battery rods that fasten the battery hold-down bar clamp.
- 4. Remove the battery from the vehicle.
- 5. Unlock the retaining tabs on the fuse block and remove the cover.



Note: Do not separate the fuse block from the housing. Do not remove the wiring harness from the fuse block.

6. Remove the fuse block positive battery cable nut (1) and the positive battery cable (2).




2786728.

Note: Illustration shows fuse block out of housing for illustration purposes only. Remove the fuse block and housing as one assembly.


7. Remove fuse block housing bolt (1) and fuse block housing (2) from current location with fuse block and housing as one assembly.

Caution: The fuse block wiring harness will limit where you can place the fuse block. Do not attempt to move the fuse block further than what the wiring harness will permit.

8. Move fuse block and fuse block housing away from work area in the engine compartment.




9. Disconnect the electrical connector from the master cylinder reservoir.



1241824

Note: Do not remove the radiator surge tank coolant feed hose. Plug surge tank overflow outlet on the tank, if required.


10. Disconnect the radiator surge tank overflow hose located next to the radiator surge tank attachment fasteners.



11. Remove radiator surge tank attachment nuts.

Caution: The radiator surge tank coolant feed hose will limit where you place the radiator surge tank. Do not attempt to move the radiator surge tank further than the coolant feed hose will permit.


12. Move radiator surge tank away from work area in the engine compartment.



1779013

- 13. Disconnect the electronic brake control module (EBCM) wiring harness connector.
- 14. Cover the connector and the socket with shop cloths to protect them from brake fluid.


Note: Take care not to allow air into the hydraulic unit or into the brake pipes from the master cylinder. If air gets into the hydraulic unit, it will require a bleeding procedure using a scan tool programmed for the ABS 5.3 system. As long as no air enters the hydraulic unit, a simple bleeding procedure is all the system will require.



- 15. Remove the brake pipes from the brake pressure modulator valve (BMPV) assembly.
- 16. Plug the brake pipes.
- 17. Remove the mounting bracket bolts on the BMPV assembly.
- 18. Remove the ABS module bracket assembly from vehicle.




19. Remove the ABS module from bracket.




20. Remove the mounting pins (1) from ABS module.



- 21. Remove the fastners (2) seuring the HCU to the EBCM.
- 22. Install new HCU on the EBCM. Tighten mounting bolts to 1.8 Nm (16 lb-ft).
- 23. Install ABS module mounting pins. Tighten mounting pins: 8 Nm (6 lb-ft).
- 24. Install the brake modulator assembly to the modulator bracket. Tighten mounting bolts: 8 Nm (6 lb–ft).
- 25. Install the BPMV assembly into the mounting bracket. Secure with two nuts and tighten to 16 Nm (12 lb-ft).




26. Remove the plugs from the brake pipes and connect the brake pipes to the BPMV assembly and tighten to 22 Nm (16 lb-ft).






- 27. Connect the wiring harness EBCM connector.
- 28. Place fuse block assembly back into its original location.




Note: Illustration shows fuse block out of housing for illustration purposes only. Install the fuse block and housing as one assembly.

29. Install the fuse block housing bolts (1) and tighten to **7** N·m (62 lb in).




2786707

- 30. Install the fuse block positive battery cable nut (1) and the positive battery cable (2) and tighten to **10 N·m (89 lb in)**.
- 31. Install fuse block cover.




- 32. Connect the master cylinder electrical connector.
- 33. Place the radiator surge tank into its original location.




1241826

34. Install the radiator surge tanks attachment nuts.



35. Connect the radiator surge tank overflow hose.



1241628

- 36. Install the battery into the tray.
- 37. Fasten the bar clamp to the battery by loosely attaching the battery rods from the battery tray cutouts through the bar clamp holes, and loosely tightening the nuts.
- 38. Tighten the battery retainer clamp-to-battery rod nuts to 4 N·m (35 lb in).
- 39. Connect the negative and positive battery cables.
- 40. Tighten the battery cable nuts to 4.5 N·m (40 lb in).

Note: Fill the master cylinder reservoir with brake fluid. Ensure the master cylinder is at least 1/2 full of fluid during the brake bleeding operation. Fill brake system with Delco Supreme 11 Brake Fluid (P/N 19299818 USA, P/N 19299819 Canada).

- 41. Bleed the brake system. Refer to Hydraulic Brake System Bleeding in SI.
- 42. Place a copy of the Owner Manual Supplement (found on the next page) in the customer's owner manual.

Owner Manual Supplement

Please place this in the "Recommended Fluids and Lubricants" section of your Owner Manual

Below are the GM recommended brake fluids. Using brake fluid other than GM recommended brake fluid may cause corrosion to components of the brake system. Corrosion may make the brake system not work well and could cause a crash.

Usage	Fluid/Lubricant
Hydraulic Brake	Delco Supreme 11 Brake Fluid
System	(GM Part No. U.S. 19299818, in Canada 19299819)

CUSTOMER REIMBURSEMENT - For US

Customer requests for reimbursement of previously paid repairs for the recall condition are to be submitted to the dealer by August 30, 2015, unless otherwise specified by state law. If this is not convenient for the customer, they may mail the completed Customer Reimbursement Request Form and all required documents to the GM Customer Assistance Center.

All reasonable and customary costs to correct the condition described in this bulletin should be considered for reimbursement. Any questions or concerns should be reviewed with your GM representative prior to processing the request.

When a customer requests reimbursement, they must provide the following:

- A completed Customer Reimbursement Request Form. This form is mailed to the customer or can be obtained through GM GlobalConnect.
- The name and address of the person who paid for the repair.
- Paid receipt confirming the amount of the repair expense, a description of the repair, and the person or entity performing the repair.

IMPORTANT: GM requires dealers to approve or deny a reimbursement request within 30 days of receipt. If a reimbursement request is approved, the dealer should immediately issue a check to the customer and submit an appropriate warranty transaction for the incurred expense. If a reimbursement request is denied, the dealer <u>MUST</u> provide the customer with a clear and concise explanation, in writing, as to why the request was denied. The bottom portion of the Customer Reimbursement Request Form may be used for this purpose. If the denial was due to missing documents, the customer can resubmit the request when the missing documents are obtained, as long as it is still within the allowed reimbursement period.

Warranty transactions for customer reimbursement of previously paid repairs are to be submitted as required by GM Global Warranty Management. Additional information can also be found in Warranty Administration Bulletin 11-00-89-004.

CUSTOMER REIMBURSEMENT - For Canada and Export

Customer requests for reimbursement of previously paid repairs to correct the condition described in this bulletin are to be submitted to the dealer prior to or by August 30, 2015.

When a customer requests reimbursement, they must provide the following:

- Proof of ownership at time of repair.
- Original paid receipt confirming the amount of unreimbursed repair expense(s) (including Service Contract deductibles), a description of the repair, and the person or entity performing the repair.

All reasonable and customary costs to correct the condition described in this bulletin should be considered for reimbursement. Any questions or concerns should be reviewed with your GM representative prior to processing the request.

WARRANTY TRANSACTION INFORMATION

Submit a transaction using the table below. All transactions should be submitted as a ZFAT transaction type, unless noted otherwise.

Labor Code	Description	Labor Time
9100798	Inspect ABS Module (no replacement necessary) (inc brake fluid change)	2.3
9100799	Inspect & Replace ABS Module (inc brake fluid change)	
	- Optra	1.5
	- Aveo, G3, Wave	2.0
9100800	Customer Reimbursement Approved	0.2
9100801	Customer Reimbursement Denied - For US dealers only	0.1

CUSTOMER NOTIFICATION – For US and Canada

General Motors will notify customers of this recall on their vehicle <u>CUSTOMER NOTIFICATION</u> – For Export

Letters will be sent to known owners of record located within areas covered by the US National Traffic and Motor Vehicle Safety Act. For owners outside these areas, dealers should notify customers using the attached sample letter.

DEALER RECALL RESPONSIBILITY – All

All unsold new vehicles in dealers' possession and subject to this recall <u>must</u> be held and inspected/repaired per the service procedure of this recall bulletin <u>before</u> customers take possession of these vehicles.

Dealers are to service all vehicles subject to this recall at no charge to customers, regardless of mileage, age of vehicle, or ownership, from this time forward.

Customers who have recently purchased vehicles sold from your vehicle inventory, and for which there is no customer information indicated on the dealer listing, are to be contacted by the dealer. Arrangements are to be made to make the required correction according to the instructions contained in this bulletin. A copy of the customer letter is provided in this bulletin for your use in contacting customers. Recall follow-up cards should not be used for this purpose, since the customer may not as yet have received the notification letter.

In summary, whenever a vehicle subject to this recall enters your vehicle inventory, or is in your dealership for service in the future, you must take the steps necessary to be sure the recall correction has been made before selling or releasing the vehicle.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the tools, equipment, safety instructions, and know-how to do a job properly and safely. If a condition is described, <u>DO NOT</u> assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your dealer for information on whether your vehicle may benefit from the information.

