

IMPORTANT SAFETY RECALL

December 2014

This notice applies to your vehicle, VIN: ______.

Dear General Motors Customer:

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

General Motors has decided that a defect which relates to motor vehicle safety exists in 2013 and some 2014 model year Cadillac XTS vehicles. As a result, GM is conducting a safety recall. We apologize for this inconvenience. However, we are concerned about your safety and continued satisfaction with our products.

IMPORTANT

- Your vehicle is involved in safety recall 14062.
- Schedule an appointment with your Cadillac dealer.
- This service will be performed for you at **no charge**.

General Motors recently discovered a data system issue which may have caused some current owners of vehicles -- that were originally purchased by fleet buyers in the U.S. and Canada -to not receive certain recall communications from GM. This issue may have prevented prior letters concerning this recall from reaching you, which is why you are receiving this letter. We have corrected our data system and apologize for any delay in providing this letter to you.

In cooperation with the National Highway Traffic Safety Administration (NHTSA) we recommend that you check your vehicle identification number periodically at the GM recall website (https://recalls.gm.com) or at NHTSA's website (https://vinrcl.safercar.gov/vin/), where you can find the most up-to-date recall information for your vehicle.

Why is your vehicle being recalled?	Pressure within the brake booster pump harness may cause a brake booster pump cavity plug to dislodge from the connector. This could allow contamination which may cause corrosion of the brake booster pump relay connector. If there is sufficient corrosion of the relay connector, it may cause a resistive short and melt the connector, which could cause a fire.

What will we Your Cadillac dealer will ensure that the vacuum pump vent hose is re-routed so it cannot be restricted. Silicone sealer will be applied to increase the retention of the connector cavity plugs, and if necessary, your dealer will replace the front body wiring harness. This service will be performed for you at no charge. Because of service scheduling requirements, it is likely that your dealer will need your vehicle longer than the actual time to reroute the vacuum pump vent hose and apply the sealer, which is approximately 45 minutes.

If the front body wiring harness requires replacement, it will take approximately 5 hours and 30 minutes.

If your vehicle is within the New Vehicle Limited Warranty, your dealer may provide you with shuttle service or some other form of courtesy transportation while your vehicle is at the dealership for this repair. Please refer to your Owner Manual and your dealer for details on courtesy transportation.

What should
you do?You should contact your Cadillac dealer to arrange a service
appointment as soon as possible.

Do you have questions? If you have questions or concerns that your dealer is unable to resolve, please contact the appropriate Customer Assistance Center at the number listed below.

Division	Number	Text Telephones (TTY)
Cadillac	1-800-458-8006	1-800-833-2622
Guam	65-6267-1752	
Puerto Rico – English	1-800-496-9992	
Puerto Rico – Español	1-800-496-9993	
Virgin Islands	1-800-496-9994	

If after contacting your dealer and the Customer Assistance Center, you are still not satisfied we have done our best to remedy this condition without charge and within a reasonable time, you may wish to write the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE., Washington, DC 20590, or call the toll-free Vehicle Safety Hotline at 1.888.327.4236 (TTY 1.800.424.9153), or go to http://www.safercar.gov. The National Highway Traffic Safety Administration Campaign ID Number for this recall is 14V116.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

Jeffrey M. Boyer Vice President Global Vehicle Safety

GM Recall #14062