

U.S. Department of Transportation

National Highway Traffic Safety Administration

May 28, 2015

Mr. Todd Fronckowiak Assistant Director, Global Automotive Safety Compliance Ford Motor Company Fairlane Plaza South, Suite #500 330 Town Center Drive Dearborn, MI 48126-2738

Subject: Driver Side Frontal Air Bag May Rupture

Dear Mr. Fronckowiak:

This letter serves to acknowledge Ford Motor Company's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

1200 New Jersey Avenue SE Washington, DC 20590

NVS-215SM

15V-319

Makes/Models/Model Years:

FORD/GT/2005-2006 FORD/MUSTANG/2005-2014

Mfr's Report Date: May 27, 2015

NHTSA Campaign Number: 15V-319

Components:

AIR BAGS:FRONTAL:DRIVER SIDE INFLATOR MODULE

Potential Number of Units Affected: 1,019,081

Problem Description:

Ford Motor Company (Ford) is recalling certain model year 2005-2014 Mustang vehicles manufactured April 6, 2004, to June 21, 2014, and 2005-2006 GT vehicles manufactured February 20, 2004, to September 22, 2006. The affected vehicles are equipped with a dual-stage driver frontal air bag that may be susceptible to moisture intrusion which, over time, could cause the inflator to rupture.

Consequence:

In the event of a crash necessitating deployment of the driver's frontal air bag, the inflator could rupture with metal fragments striking and potentially seriously injuring the driver or other occupants.

Remedy:

Ford will notify owners, and dealers will replace the front driver side air bag inflator, free of charge. The recall is expected to begin July 13, 2015. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 15S21. Note: This recall supersedes recall 14V802 in its entirety. Additionally, vehicles that have had their driver side frontal air bag replaced previously as part of a recall remedy need to have their air bag replaced under this recall as well.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.



This recall was the subject of an engineering analysis, EA15-001, conducted by the Office of Defects Investigation.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Sarah Mcshane who may be reached by phone at 202-366-7401, or by email at sarah.mcshane@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

Jennifer Timian

Chief, Recall Management Division Office of Defects Investigations

Enforcement

