

Part 573 Safety Recall Report**15V-046****Manufacturer Name :** Chrysler (FCA US LLC)**Submission Date :** FEB 02, 2016**NHTSA Recall No. :** 15V-046**Manufacturer Recall No. :** R06**Manufacturer Information :**

Manufacturer Name : Chrysler (FCA US LLC)

Address : 800 Chrysler Drive

CIMS 482-00-91 Auburn Hills MI 48326-2757

Company phone : 1-800-853-1403

Population :

Number of potentially involved : 753,176

Estimated percentage with defect : 0

Vehicle Information :

Vehicle : 2002-2003 Jeep Liberty

Vehicle Type : LIGHT VEHICLES

Body Style : SUV

Power Train : GAS

Descriptive Information : 2002-2003 Jeep Liberty

Production Dates : JAN 09, 2001 - MAR 28, 2003

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2003-2004 Dodge Viper

Vehicle Type : LIGHT VEHICLES

Body Style : 2-DOOR

Power Train : GAS

Descriptive Information : 2003-2004 Dodge Viper

Production Dates : NOV 01, 2001 - JUN 30, 2004

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2002-2004 Jeep Grand Cherokee

Vehicle Type : LIGHT VEHICLES

Body Style : SUV

Power Train : GAS

Descriptive Information : 2002-2004 Jeep Grand Cherokee

Production Dates : FEB 13, 2001 - MAY 23, 2003

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : Some vehicles may experience front airbag, side curtain airbag, and seatbelt pretensioner inadvertent deployments.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Airbags that unexpectedly deploy increase the possibility of a crash and risk of injury.

Description of the Cause : The inadvertent airbag deployments are the result of an electrical over-stress to one of two Application Specific Integrated Circuits that control the airbag squibs. The cause of the electrical over-stress has yet to be determined and is actively under investigation.

Identification of Any Warning that can Occur : Customer complaints have indicated, in many instances, that the airbag warning lamp and/or chime are activated shortly before an inadvertent airbag deployment.

Supplier Identification :**Component Manufacturer**

Name : TRW Automotive

Address : 24175 Research Drive

Farmington Hills 48335-2642

Country : NR

Chronology :

Please see attached supplemental information titled "Chrysler Group LLC Chronology R06".

Description of Remedy :

Description of Remedy Program : FCA US will conduct a voluntary safety recall on all affected vehicles to replace the ORC module and side impact sensors as required. Chrysler has a longstanding policy and practice of reimbursing owners who have incurred the cost of repairing a problem that subsequently becomes the subject of a field action. To ensure consistency, Chrysler, as part of the owner letter, will request that customers send the original receipt and/or other adequate proof of payment to the company for confirmation of the expense.

How Remedy Component Differs from Recalled Component : Replacement ORC modules are being developed that utilize the next generation of electrical architecture for ORC modules, including a revision to the positioning of the Safing Sensor.

These next generation ORC modules do not have a history of IAD.

Identify How/When Recall Condition was Corrected in Production : N/A

Recall Schedule :

Description of Recall Schedule : ** 2/2/16:

Phase 2 update: Remaining rest of country week of 2/5/16**

Owner Launch

Phase 1: Southern States by 12/29/2015

Phase 2: Remaining rest of country by 3/31/2016

Planned Dealer Notification Date : DEC 18, 2015 - DEC 18, 2015

Planned Owner Notification Date : DEC 29, 2015 - FEB 12, 2016

* NR - Not Reported