

Part 573 Safety Recall Report**15V-267****Manufacturer Name :** General Motors LLC**Submission Date :** MAY 06,2015**NHTSA Recall No. :** 15V-267**Manufacturer Recall No. :** 15150**Manufacturer Information :**

Manufacturer Name : General Motors LLC

Address : 30001 VAN DYKE

MAIL CODE 480-210-2V WARREN MI 48090

Company phone : 999

Population :

Number of potentially involved : 49,980

Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2015-2015 Chevrolet Colorado

Vehicle Type : LIGHT VEHICLES

Body Style : PICKUP TRUCK

Power Train : NR

Descriptive Information : 2015 Chevrolet Colorado

Production Dates : JAN 06, 2014 - APR 01, 2015

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2015-2015 GMC Canyon

Vehicle Type : LIGHT VEHICLES

Body Style : PICKUP TRUCK

Power Train : NR

Descriptive Information : Certain 2015 GMC Canyon vehicles

Production Dates : JAN 06, 2014 - APR 01, 2015

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : General Motors has decided that certain 2015 model year Chevrolet Colorado and GMC Canyon vehicles fail to conform to Federal Motor Vehicle Safety Standard No. 207, "Seating Systems". In these vehicles, certain seat-frame attachment hooks that secure the front of the driver's and/or front passenger's seat may not have been properly attached to the vehicle body during the assembly process. Where this

condition is present, the seats may not remain in the position required by FMVSS 207 during certain crashes.

Description of the Safety Risk : Where this condition is present, the front of the seat may not remain secured to the body of the vehicle in a crash, increasing the risk of injury.

Description of the Cause : Certain seat-frame attachment hooks that secure the front of the affected seats were not properly attached to the vehicle body during the assembly process at GM's Wentzville assembly plant.

Identification of Any Warning that can Occur : Affected seats may tilt back slightly when the vehicle rapidly accelerates or when significant pressure is applied to the upper seat back.

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR

FOREIGN STATES

Country : NR

Chronology :

On January 23, 2015, a GM employee reported to GM's Wentzville assembly plant that, in his company vehicle, the seat-frame attachment hooks that secure the front of the driver's seat were not attached to the vehicle body. On February 11, 2015, the issue was reported through GM's Speak Up For Safety program. GM opened an investigation into the issue on February 17, 2015. On April 29, 2015, GM's Safety and Field Investigation Decision Authority (SFADA) decided to conduct a noncompliance recall.

Description of Remedy :

Description of Remedy Program : Dealers will inspect potentially affected seats for proper installation, and if required, disassemble and properly reassemble the seats.

Pursuant to 577.11, General Motors does not plan to provide notice about reimbursement to owners because all involved vehicles are covered under the new vehicle warranty.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : A yard sort at the Wentzville assembly plant was completed on March 31, 2015. The assembly plant retrained seat installers and secondary operators to inspection criteria on April 1, 2015.

Recall Schedule :

Description of Recall Schedule : General Motors will provide the owner letter mail date when available.

Planned Dealer Notification Date : MAY 06, 2015 - MAY 06, 2015

Planned Owner Notification Date : NR - NR

* NR - Not Reported