

Part 573 Safety Recall Report**15V-287****Manufacturer Name :** Nissan North America, Inc.**Submission Date :** MAY 14,2015**NHTSA Recall No. :** 15V-287**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Nissan North America, Inc.

Address : P. O. BOX 685001

Franklin TN 37068-5009

Company phone : (999) 999-9999

Population :

Number of potentially involved : 263,692

Estimated percentage with defect : 0

Vehicle Information :

Vehicle : 2004-2004 Nissan Pathfinder

Vehicle Type : LIGHT VEHICLES

Body Style : SUV

Power Train : GAS

Descriptive Information : The vehicles subject to this report are equipped with SPI inflators, and are currently registered outside of the High Absolute Humidity (HAH) Regions and are not part of prior recalls.

Vehicles equipped with SPI inflators currently or previously registered within the HAH Regions are already subject to recalls 14V-701 and 15V-226.

Earlier production (MY01-04) Pathfinder vehicles equipped with SPI inflators are already subject to national recalls 13V-136 and 14V-361.

Production Dates : JAN 06, 2004 - JUL 19, 2004

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2004-2006 Nissan Sentra

Vehicle Type : LIGHT VEHICLES

Body Style : 4-DOOR

Power Train : GAS

Descriptive Information : The vehicles subject to this report are equipped with SPI inflators, and are currently registered outside of the High Absolute Humidity (HAH) Regions and are not part of prior recalls.

Vehicles equipped with SPI inflators currently or previously registered within the HAH Regions are already subject to recalls 14V-701 and 15V-226.

Earlier production (MY02-04) Sentra vehicles equipped with SPI inflators are already subject to national recalls 13V-136 and 14V-361.

Production Dates : JAN 07, 2004 - AUG 26, 2006

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

Not sequential VINs

Description of Defect :

Description of the Defect : The root cause of the issue remains under investigation. However, based on information available to date, it appears that the subject front passenger air bag inflator (SPI) could, over time, lose seal integrity in the inflator body which could potentially lead to ambient air penetration into the inflator.

The effects of ambient air penetration into the inflator in areas outside of the HAH Region are still under investigation. Nevertheless, Nissan is conducting this campaign out of abundance of caution and to enable additional parts collection and analysis.

Description of the Safety Risk : This inflator could be susceptible to moisture intrusion, possibly resulting in abnormal passenger air bag deployment in the event of a crash, increasing the risk of injury to the occupant.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : TK HOLDINGS INC.

Address : 2500 Takata Drive

Auburn Hills MICHIGAN 48326

Country : United States

Chronology :

See attached Part 573 Report for detailed chronology.

Description of Remedy :

Description of Remedy Program : Nissan will notify vehicle owners by first class mail. Owner notification will be completed within 60 days. The front passenger air bag inflator will be replaced with a new one at no cost to owners for parts or labor. Nissan anticipates having enough replacement parts on hand and will address any potential short-term service issues with individual customers on case-by-

case basis.

We will include a statement in the Part 577 owner notification concerning reimbursement for the cost of obtaining a pre-notification remedy.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Nissan will notify vehicle owners by first class mail. Owner notification will be completed within 60 days.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported