

Part 573 Safety Recall Report**15V-459****Manufacturer Name :** Chrysler (FCA US LLC)**Submission Date :** JUL 21,2015**NHTSA Recall No. :** 15V-459**Manufacturer Recall No. :** R36**Manufacturer Information :**

Manufacturer Name : Chrysler (FCA US LLC)

Address : 800 Chrysler Drive

CIMS 482-00-91 Auburn Hills MI 48326-2757

Company phone : 1-800-853-1403

Population :

Number of potentially involved : 1,060,531

Estimated percentage with defect : 1

Vehicle Information :

Vehicle : 2012-2014 Ram 1500

Vehicle Type :

Body Style : PICKUP TRUCK

Power Train : NR

Descriptive Information : Certain 2012-2014 MY Ram Truck vehicles with Electronic Vehicle Information Center option.

Production Dates : JAN 18, 2011 - OCT 07, 2014

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2012-2014 Ram 2500

Vehicle Type :

Body Style : PICKUP TRUCK

Power Train : NR

Descriptive Information : Certain 2012-2014 MY Ram Truck vehicles with Electronic Vehicle Information Center option.

Production Dates : JAN 18, 2011 - OCT 07, 2014

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2012-2014 Ram 3500

Vehicle Type :

Body Style : PICKUP TRUCK

Power Train : NR

Descriptive Information : Certain 2012-2014 MY Ram Truck vehicles with Electronic Vehicle Information Center option.

Production Dates : JAN 18, 2011 - OCT 07, 2014

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

Not sequential VINs

Vehicle : 2012-2014 Ram 4500/5500

Vehicle Type :

Body Style : PICKUP TRUCK

Power Train : NR

Descriptive Information : Certain 2012-2014 MY Ram Truck vehicles with Electronic Vehicle Information Center option.

Production Dates : JAN 18, 2011 - OCT 07, 2014

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

Not sequential VINs

Description of Defect :

Description of the Defect : Certain 2012-2014 MY Ram Truck vehicles may have a steering wheel wiring harness that contacts the driver airbag module retainer spring end causing wear on the harness wires which may lead to an electrical short.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : This condition increases the potential of inadvertent driver airbag deployment.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : Autoliv

Address : NR

MICHIGAN

Country : United States

Chronology :

Please see the attached supplemental information titled "FCA US LLC Chronology - Steering Wheel Wiring Harness - 07212015.pdf".

Description of Remedy :

Description of Remedy Program : FCA US will conduct a Voluntary Safety Recall on all affected vehicles to inspect, repair as required and tie back the steering wheel wiring harness,

and add protective caps to the airbag retainer spring ends.

FCA US has a longstanding policy and practice of reimbursing owners who have incurred the cost of repairing a problem that subsequently becomes the subject of a field action. To ensure consistency, FCA US, as part of the owner letter, will request that customers send the original receipt and/or other adequate proof of payment to the company for confirmation of the expense.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Planned Dealer Notification: 09/19/2015

Planned Owner Notification Start / End Date: 09/19/2015 -09/19/2015

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported