OMB Control No.: 2127-0004

Part 573 Safety Recall Report

15V-483

Manufacturer Name: Volkswagen Group of America, Inc.

Submission Date: SEP 02,2015 NHTSA Recall No.: 15V-483 Manufacturer Recall No.: 69L2



Manufacturer Information:

Manufacturer Name: Volkswagen Group of America, Inc.

Address: 3800 Hamlin Road

Auburn Hills MI 48326 Company phone : 1-800-822-8987

Population:

Number of potentially involved : 415,825 Estimated percentage with defect : 100

Vehicle Information:

Vehicle: 2011-2011 Volkswagen Tiguan

Vehicle Type : Body Style :

Power Train: NR

Descriptive Information: Steering Wheel Clock Spring

24,608

Production Dates: MAY 03, 2010 - JUN 15, 2011

VIN (Vehicle Identification Number) Range

Begin: WVGAV7AX4BW000010 End: WVGBV7AX1BW570423 Not sequential VINs

Vehicle: 2010-2012 Volkswagen CC (B6)

Vehicle Type : Body Style : Power Train : NR

Descriptive Information : Steering Wheel Clock Spring

58,998

 $Production\ Dates: JUL\ 03,\ 2009-DEC\ 24,\ 2011$

VIN (Vehicle Identification Number) Range

Begin: WVWML7AN6AE509655 End: WVWHP7AN0CE553420 Not sequential VINs

Vehicle: 2010-2010 Volkswagen Passat Wagon (B6)

Vehicle Type : Body Style : Power Train : NR

Descriptive Information : Steering Wheel Clock Spring

2,033

Production Dates : OCT 30, 2009 - JUN 01	, 2010	
VIN (Vehicle Identification Number) R	ange	
Begin: WVWXK7AN9AE053893	End: WVWXM7AN6AE170101	☐ Not sequential VINs
Vehicle: 2010-2010 Volkswagen Passat Vehicle Type: Body Style: Power Train: NR Descriptive Information: Steering Wheel 8,422		
Production Dates: NOV 02, 2009 - JUN 01	, 2010	
VIN (Vehicle Identification Number) R	ange	
Begin: WVWJK7AN3AE053863	End: WVWJM7ANXAE170141	☐ Not sequential VINs
Vehicle: 2010-2010 Volkswagen Passat Vehicle Type: Body Style: Power Train: NR Descriptive Information: Steering Wheel 742	Clock Spring	
Production Dates : NOV 10, 2009 - MAY 2	8, 2010	
VIN (Vehicle Identification Number) R	ange	
Begin: WVWJK7AN4AP024666	End: WVWJK7ANXAP055890	☐ Not sequential VINs
Vehicle: 2010-2011 Volkswagen Eos Vehicle Type: Body Style: Power Train: NR Descriptive Information: Steering Wheel 6.766	Clock Spring	
o,766 Production Dates : OCT 02, 2009 - AUG 14	1, 2010	
VIN (Vehicle Identification Number) R	ange	
Begin: WVWFA7AH9AV008347	End: WVWFW7AH3BV005544	☐ Not sequential VINs
Vehicle: 2011-2014 Volkswagen Golf/G Vehicle Type: Body Style: Power Train: NR Descriptive Information: Steering Wheel 15,528		

Descriptive Information : Steering Wheel Clock Spring 12,665

Power Train: NR

Production Dates : DEC 02, 2010 - FEB 18	, 2013	
VIN (Vehicle Identification Number) Ra	ange	
Begin: WVWBW7AH7CV000010	End: WVWFW8AH2DV006113	☐ Not sequential VINs
Vehicle: 2012-2014 Volkswagen Tiguan	(New)	
Vehicle Type :		
Body Style :		
Power Train : NR		
$\begin{array}{c} \textbf{Descriptive Information: Steering Wheel} \\ \textbf{50,219} \end{array}$. 0	
Production Dates: FEB 28, 2011 - FEB 26,	2014	
VIN (Vehicle Identification Number) Ra	ange	
Begin: WVGBV7AX5CW000006	End: WVGBV3AX8EW593355	☐ Not sequential VINs
Vehicle: 2013-2014 Volkswagen CC (B7)		
Vehicle Type :		
Body Style :		
Power Train : NR		
Descriptive Information : Steering Wheel 24,073	Clock Spring	
Production Dates: JAN 19, 2012 - APR 01,	2014	
VIN (Vehicle Identification Number) Ra	ange	
Begin: WVWAP7AN9DE500024	End: WVWBN7AN8EE534564	☐ Not sequential VINs

Description of the Defect: The steering wheel clock spring could become contaminated with long hair or long

fibers which may cause a displacement of the internal guide loops. When the guide loops are dragged out of position, they may apply tension to the internal flat cable and cause it to tear. Should the cable tear, the electrical connection to the driver's front airbag may be lost, causing the airbag monitoring indicator light to illuminate. In a crash that warrants a driver front airbag deployment, the airbag will not

deploy, leading to a risk of driver injury.

FMVSS 1:NR FMVSS 2:NR

Description of the Safety Risk: Should the cable tear, the electrical connection to the driver's front airbag may

be lost, causing the airbag monitoring indicator light to illuminate. In a crash that warrants a driver front airbag deployment, the airbag will not deploy,

leading to a risk of driver injury.

Description of the Cause: Contamination of the clock spring assembly with long hair or long fabrics may cause

a displacement of internal guide loops. When guide loops are dragged out of

position, they may apply tension to the internal flat cable and cause rupture of the

Identification of Any Warning that can Occur: The airbag monitoring indicator light will immediately illuminate if clock spring cable ruptures

Supplier Identification:

Component Manufacturer

Name: Valeo Interior Controls (CIC)

Address: Valeo Straße 1

Wemding FOREIGN STATES 86650

Country: Germany

Chronology:

December 2011 - Reception of first field reports.

February 2012 - Field Data and Return Part Analysis.

March 2012 - Part Design Optimization Initiated (Implementation by running change as of January 2013) accompanied by manufacturing process improvements through December 2013.

May 2012 - First evaluation in Volkswagen's product safety committee, low failure rate detected and no impact on vehicle safety was found at that time.

March 2015 - Opening Resume from NHTSA received, data analysis and evaluation initiated.

April 2015 - Risk assessment/evaluation initiated (European standard-RAPEX).

May 2015 – Submitted PE response to NHTSA with a request for a technical meeting.

June 2015 - Additional risk assessment calculation (fault tree analysis) prepared in advance of technical meeting.

July 15, 2015 – Technical meeting with NHTSA to explain risk assessment.

July 22, 2015 - NHTSA response with non-acceptance of risk evaluation and demand for notification of defect.

July 23, 2015 - Review at Volkswagen's product safety committee and formal determination of defect due to NHTSA's demand.

Description of Remedy:

Description of Remedy Program: To be determined

How Remedy Component Differs from Recalled Component: To be determined

Identify How/When Recall Condition was Corrected in Production: Clock spring parts have been improved and implemented by running change as of December 2012.

Recall Schedule:

Description of Recall Schedule: To be determined

Planned Dealer Notification Date: NR - NR

Planned Owner Notification Date: NR - NR

Part 573 Safety Re	ecall Report	15V-483	Page 6
* NR - Not Reported			
	The information contained in this	report was submitted pursuant to 49 CFR §573	