

Part 573 Safety Recall Report**15V-500****Manufacturer Name :** General Motors LLC**Submission Date :** AUG 05,2015**NHTSA Recall No. :** 15V-500**Manufacturer Recall No. :** 15075**Manufacturer Information :**

Manufacturer Name : General Motors LLC

Address : 30001 VAN DYKE

MAIL CODE 480-210-2V WARREN MI 48090

Company phone : 999

Population :

Number of potentially involved : 59,474

Estimated percentage with defect : 8

Vehicle Information :

Vehicle : 2010-2010 Chevrolet Cobalt

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Certain 2010 Chevrolet Cobalt sedan vehicles

Production Dates : JAN 04, 2010 - JUN 23, 2010

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : General Motors has decided that a defect which relates to motor vehicle safety exists in certain 2010 Chevrolet Cobalt sedan vehicles. In some of these vehicles, the side-impact sensor wire harness in the driver-side front door may have been improperly routed. If the wire harness was improperly routed, the window regulator could contact the harness when the window is fully lowered and, over time, chafe the harness insulation. If the regulator penetrates the insulation, a short could occur in the side-impact sensor circuit. When a short occurs, the vehicle's sensing and diagnostic module (SDM) may no longer receive sensing data from that sensor, preventing the driver-side roof-rail airbag from deploying during a crash.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Disabling the driver-side roof-rail airbag increases the risk of occupant injury in certain kinds of crashes.

Description of the Cause : The side-impact sensor wire harness was misrouted during the vehicle-assembly process.

Identification of Any Warning that can Occur : The vehicle's airbag warning light will illuminate for the

duration of the ignition cycle. This condition can be intermittent between ignition cycles.

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

see attached

Description of Remedy :

Description of Remedy Program : Dealers will inspect the SIS wiring in the front left doors. If the condition is present, they will repair damaged wires, correct the clip orientation, and correct the wire routing.

How Remedy Component Differs from Recalled Component : Pursuant to 577.11, GM will provide reimbursement to owners for repairs completed on or before ten days after the owner mailing is completed, according to the plan submitted on May 20, 2015.

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : General Motors will provide the dealer bulletin notification dates when available.

Planned Dealer Notification Date : AUG 05, 2015 - AUG 05, 2015

Planned Owner Notification Date : AUG 26, 2015 - AUG 26, 2015

* NR - Not Reported