

Part 573 Safety Recall Report**15V-520****Manufacturer Name :** BMW of North America, LLC**Submission Date :** AUG 13,2015**NHTSA Recall No. :** 15V-520**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : BMW of North America, LLC

Address : P.O. Box 1227

200 Chestnut Ridge Road Westwood NJ 07675-122

Company phone : 999-999-9999

Population :

Number of potentially involved : 7,544

Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2012-2015 BMW 3 Series Sedan (320i, 320xi, 328i, 328xi, 335i, 335xi, ActiveHybrid 3)

Vehicle Type : LIGHT VEHICLES

Body Style : 4-DOOR

Power Train : GAS

Descriptive Information : Affected vehicles were programmed with a software version not compliant with FMVSS 108.

7, 146 vehicles are affected.

Production Dates : OCT 20, 2011 - JUN 22, 2015

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2014-2015 BMW 328xi Sports Wagon

Vehicle Type : LIGHT VEHICLES

Body Style : STATIONWAGON

Power Train : GAS

Descriptive Information : Affected vehicles were programmed with a software version not compliant with FMVSS 108. 68 vehicles are affected.

Production Dates : MAR 21, 2013 - MAR 17, 2015

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2014-2015 BMW 3 Series Sedan (328d, 328xd)

Vehicle Type : LIGHT VEHICLES

Body Style : 4-DOOR

Power Train : DIESEL

Descriptive Information : Affected vehicles were programmed with a software version not compliant with FMVSS 108.
258 vehicles are affected.

Production Dates : JUN 28, 2013 - APR 21, 2015

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

Not sequential VINs

Vehicle : 2014-2015 BMW 328xd Sports Wagon

Vehicle Type : LIGHT VEHICLES

Body Style : STATIONWAGON

Power Train : DIESEL

Descriptive Information : Affected vehicles were programmed with a software version not compliant with FMVSS 108.
72 vehicles are affected.

Production Dates : JUL 05, 2013 - APR 21, 2015

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

Not sequential VINs

Description of Noncompliance :

Description of the Noncompliance : This recall involves the front side marker lamps. Affected vehicles were updated by dealers with a new software version which inadvertently made the front side marker lamps inoperative. As a result, the front side marker lamps do not illuminate in conjunction with the parking lamps or headlamps and no warning message is displayed in the instrument cluster. Therefore, affected vehicles do not conform to FMVSS 108 "Lamps, reflective devices, and associated equipment". The turn signal function of the front side marker lamps remains operational.

FMVSS 1 : 108 - Lamps, reflective devices, and assoc. Equipment

FMVSS 2 : NR

Description of the Safety Risk : The affected vehicles may be less conspicuous in darkness or other low light conditions, which may increase the risk of a crash.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

Chronology :

On July 24, 2015, BMW became initially aware of this concern through routine checks of its Technical Service measures. It was found that both front amber parking lamps were no longer illuminated in conjunction with the headlamps after programming a customer's vehicle with an updated software version, which had been released to the dealer network on June 15, 2015. Initial analyses pointed to a possible bug in this new software version.

On July 29, 2015, a service information bulletin was released to BMW dealers, instructing them not to perform any programming or coding on potentially affected customer vehicles until a revised software version becomes available, which was subsequently released on August 3, 2015.

Further analyses were performed to determine the quantity and production date range of the potentially affected vehicles.

On August 6, 2015, it was determined that vehicles programmed with this software version do not fully conform to FMVSS 108. As a result, BMW decided to conduct a voluntary recall.

BMW has not received any reports, nor is BMW otherwise aware, of any accidents or injuries related to this issue.

Description of Remedy :

Description of Remedy Program : The affected field vehicles will be programmed with a revised software version to correct the non-compliance.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : AUG 13, 2015 - OCT 09, 2015

Planned Owner Notification Date : OCT 09, 2015 - OCT 09, 2015

* NR - Not Reported