

**Part 573 Safety Recall Report****15V-563****Manufacturer Name :** Honda (American Honda Motor Co.)**Submission Date :** SEP 04,2015**NHTSA Recall No. :** 15V-563**Manufacturer Recall No. :** JU0**Manufacturer Information :**

Manufacturer Name : Honda (American Honda Motor Co.)

Address : 1919 Torrance Blvd.

Torrance CA 90501

Company phone : 310-783-2000

**Population :**

Number of potentially involved : 37

Estimated percentage with defect : 100

**Vehicle Information :**

Vehicle : 2003-2003 HONDA ODYSSEY

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined based on manufacturing records. The VIN range reflects all possible vehicles that could potentially experience the problem.

Production Dates : AUG 28, 2002 - AUG 30, 2002

**VIN (Vehicle Identification Number) Range**

Begin : 2HKRL18693H500470

End : 2HKRL18683H500640

 Not sequential VINs**Description of Defect :**

Description of the Defect : During manufacturing of the passenger frontal airbag module, the supplier may have incorrectly installed 2002 model year parts into 2003 model year modules. The 2002 model year Odyssey used a PSPI inflator, while the 2003 model year Odyssey used PSPI-L inflator as well as a new airbag cushion design.

FMVSS 1 : 208 - Occupant crash protection

FMVSS 2 : NR

Description of the Safety Risk : The incorrect parts do not comply with the FMVSS 208 advanced airbag requirements that came into effect for the 2003 model year.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

**Supplier Identification :****Component Manufacturer**

Name : T.K. Holdings, Inc.

Address : 888 16th Street NW

Washington DISTRICT OF COLUMBIA 20006

Country : United States

**Chronology :**

June 2014

The Honda Odyssey was involved in recalls related to Takata passenger inflator over pressurization concerns.

November 2014 – June 2015

17 field reports were received from dealer technicians in the USA and Canada; regarding Takata inflator remedies that could not be completed due to incorrect OEM inflator installation (New modules were installed to satisfy the recall remedy).

August 27, 2015

Honda completed the investigation and determined that non-compliance exists and decided to conduct a non-compliance recall.

As of August 27, 2015 Honda has received 17 field reports and no warranty claims or injuries related to this issue.

**Description of Remedy :**

Description of Remedy Program : The owners of all affected vehicles will be contacted by mail and asked to take their vehicle to a Honda automobile dealer. The dealer will replace passenger frontal airbag module free of charge (this repair will also satisfy the remedy to an open Takata passenger inflator recall, if applicable).

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

**Recall Schedule :**

Description of Recall Schedule : NR

Planned Dealer Notification Date : SEP 04, 2015 - NR

Planned Owner Notification Date : OCT 06, 2015 - OCT 06, 2015

\* NR - Not Reported