The information contained in this report was submitted pursuant to 49 CFR §573

OMB Control No.: 2127-000

Number of potentially involved :

Estimated percentage with defect : 100 %

Part 573 Safety Recall Report

Manufacturer Name: Mitsubishi Motors North America, Inc. Submission Date : MAY 04, 2016 NHTSA Recall No.: 15V-579 Manufacturer Recall No.: SR-15-010

Manufacturer Information :

Manufacturer Name : Mitsubishi Motors North America, Inc. Address: 6400 Katella Avenue Cypress CA 90630 Company phone: 1-888-648-7820

Vehicle Information :

Vehicle 1: 2011-2011 Mitsubishi Outlander Sport Vehicle Type : LIGHT VEHICLES Body Style: 4-DOOR Power Train : GAS Descriptive Information : Only two consecutively built vehicles are involved in this non-compliance recall. Production Dates : DEC 03, 2010 - DEC 03, 2010 VIN Range 1: Begin: JA4AR4AU3BZ006824 End: JA4AP4AU8BZ006825 Not sequential

Description of Noncompliance :

-	Two certification labels were inadvertently swapped and installed incorrectly by a line worker during vehicle production. As a result, the VIN printed on the certification label located on the driver's side B pillar does not match the actual VIN for these two vehicles. Due to this mismatch, Mitsubishi Motors Corporation (MMC) determined that the certification label in the two affected 2011 MY Outlander Sport vehicles are in non-compliance with 49 CFR Part 567 - Certification. In all other respects, the description of the GVWR, GAWR, etc. fully comply with the subject regulation.
FMVSS 1 :	NR
FMVSS 2 :	NR
Description of the Safety Risk :	This non-compliance does not affect the safety or performance of the vehicle.
Description of the Cause :	NR
Identification of Any Warning that can Occur :	NR



15V-579

2

Population:

pplier Identification :		
omponent Manufacturer		
Name: NR		
Address : NR		
NR		
Country: NR		
ronology :		
See the attached document for the chronology of events leading up to the defect decision.		
scription of Remedy :		
Description of Remedy Program : Mitsubishi Motors North America, Inc. and MMSC will contact the two		
customers by phone and have them bring their vehicle to a local dealer for		
certification label replacement. Alternatively, the two customers may elect		
to have a Mitsubishi service representative visit them for certification label replacement.		
How Remedy Component Differs NR		
from Recalled Component :		
entify How/When Recall Condition NR was Corrected in Production :		
was corrected in Production :		
call Schedule :		
Description of Recall Schedule : MMNA is working internally to determine the dealer and customer		
notification date and will update accordingly.		
Planned Dealer Notification Date : NR - NR		
Planned Owner Notification Date : NR - NR		

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR \$573