OMB Control No.: 2127-0004

Part 573 Safety Recall Report

15V-674

Manufacturer Name: Mazda North American Operations

Submission Date: OCT 25,2015 **NHTSA Recall No.**: 15V-674 **Manufacturer Recall No.**: 8715J



•	-		^	-				
N	/	anu	20	turer	Inte	arma	tion	•
и	78.	41111	4.			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		_

Manufacturer Name: Mazda North American Operations

Address: 1025 Connecticut Avenue, NW

Suite 910 Washington DC 20036

Company phone: 800-222-5500

Population:

Number of potentially involved: 1,368,500

Estimated percentage with defect : 0

Vehicle	Informa	ation	:
---------	---------	-------	---

Vehicle: 1993-1995 Mazda Mazda 929

Vehicle Type: LIGHT VEHICLES

Body Style : 4-DOOR Power Train : GAS

Descriptive Information: The vehicles manufactured at Hiroshima plant of Mazda Motor Corporation in

Japan.

 $Production\ Dates: SEP\ 01,\ 1992\ - APR\ 26,\ 1995$

VIN (Vehicle Identification Number) Range

Vehicle: 1989-1998 Mazda MPV Vehicle Type: LIGHT VEHICLES

Body Style : 4-DOOR Power Train : GAS

Descriptive Information: The vehicles manufactured at Hiroshima plant of Mazda Motor Corporation.

Production Dates: APR 05, 1988 - NOV 25, 1998

VIN (Vehicle Identification Number) Range

Begin : JM2LV6212K0100025	End: JM2LV6214K0120289	☐ Not sequential VINs
Begin : JM3LV5224K0100008	End: JM3LV5224K0139584	☐ Not sequential VINs
Begin : JM2LV6211L0240391	End: JM2LV6216L0248728	☐ Not sequential VINs
Begin : JM3LV5238L0200008	End: JM3LV5239L0259049	☐ Not sequential VINs
Begin : JM2LV6211M0300011	End: JM2LV6211M0349936	☐ Not sequential VINs

VIN (Vehicle Identification Number) Range Begin: JM1BG2245L0100065 End: JM1BG2261L0191224 Not sequential VINs Begin: JM1BG2246M0200001 End: JM1BG226XM0311314 Not sequential VINs Begin: JM1BG2249N0400016 End: JM1BG2240N0514485 Not sequential VINs Begin: JM1BG2247P0550001 End: JM1BG2249P0655946 Not sequential VINs Begin: JM1BG2240R0700002 End: JM1BG2249R0820395 Not sequential VINs Begin: JM1BG2249S0830401 End: JM1BG2246S0839749 Not sequential VINs Begin: JM1BA1418S0138919 End: JM1BA1416S0140359 Not sequential VINs Begin: JM1BB1422T0313284 End: JM1BB1427T0365977 Not sequential VINs

Descriptive Information: The manufactured vehicles at Auto Alliance International in USA.

Production Dates: SEP 01, 1992 - MAY 30, 1997

VIN (Vehicle Identification Number) Range

Address: Shiba-daimon 1-1-30, Minato, Tokyo Japan

FOREIGN STATES

Country: Japan

Chronology:

May, 2001 Mazda received a field report from the Japan market. The report said that short circuit occurred at the ignition switch and smoke was emitted, and starter continued running. However, we couldn't collect and investigate the switch and then we determined to continue monitoring the field.

April, 2002 Mazda received a field report with a fire from Japan market. However, Mazda determined to continue monitoring the field because this failure occurred because the vehicle continued running with ignition switch overrun.

March, 2008 As a result of the investigation of the failure switch, Mazda determined that insulation failure occurred due to grease accumulation if an excessive amount of grease was applied to the ignition switch, leading to a smoke and a short circuit resulting in engine stop.

October, 2010 Mazda believed that the excessive amount grease was due to grease injection in the field maintenance and decided to continue monitoring the field.

April 17, 2015: Mazda was requested to assess the switch assembly by the Japan authority regarding the affected ignition switch, as another manufacturer conducted a safety recall on the same type of ignition switch in Japan

October 12, 2015: Mazda has not been able to determine the source of the excessive grease (production or field maintenance) but understands there is a potential that this situation can result in the switch overheating and possibly resulting in a fire. Therefore, Mazda decided to conduct a safety recall campaign on the affected vehicles.

Description of Remedy:

Description of Remedy Program : For all the vehicle owners involved with the recall campaign, MNAO will notify them of the recall campaign. We will replace the ignition switch for free.

How Remedy Component Differs from Recalled Component : We have changed the grease used at the terminal of the ignition switch to the fluorine-based grease which is less susceptible to the formation of carbon.

Identify How/When Recall Condition was Corrected in Production : No countermeasure has been taken because mass production has already finished.

Recall Schedule:

Description of Recall Schedule: NR

Planned Dealer Notification Date: DEC 05, 2015 - DEC 05, 2015

Planned Owner Notification Date: DEC 15, 2015 - DEC 15, 2015

* NR - Not Reported