The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report

Manufacturer Name : Honda (American Honda Motor Co.) Submission Date : OCT 28,2015 NHTSA Recall No. : 15V-714 Manufacturer Recall No. : JV9

Manufacturer Information :

Manufacturer Name : Honda (American Honda Motor Co.) Address : 1919 Torrance Blvd. Torrance CA 90501 Company phone : 1-800-999-1009

Vehicle Information :

 Vehicle : 2016-2016 Honda CR-V Vehicle Type : Body Style : Power Train : NR Descriptive Information : Based on the current working hypothesis for this defect, the recall population was determined based on manufacturing records of vehicles manufactured with driver frontal airbag modules that contain airbag inflators that were built within the same lot as the unit that ruptured. The VIN range will be revised if necessary after additional work is done to try to confirm the root cause. Production Dates : OCT 12, 2015 - OCT 19, 2015 				
			e	
			End : NR	☐ Not sequential VINs
			Description of Defect : Description of the Defect : The current defect hypothesis is that the airbag inflator contained in the driver frontal airbag module may have been improperly stamped and/or contains a defect	
				ag inflator's metal housing which, in the for components to separate.
material possibly causing	al fragments could pass through the g injury or fatality to vehicle occupants. Honda are currently conducting an			
	on manufacturing record ules that contain airbag in ruptured. The VIN range done to try to confirm the off e End : NR hypothesis is that the airb le may have been improp to manufacture the airb oyment, may cause inflat			

scription of the Cause : The root cause is not yet known. Takata and Honda are currently conducting an investigation into the cause of the condition. As noted above, the current hypothesis is that the airbag inflator's metal housing may have been manufactured using steel improperly stamped and/or with a defect in materials. Honda will revise this



Number of potentially involved : 515

Estimated percentage with defect : NR

Population:

15V-714

description if necessary after additional work is done to try to confirm the root

cause. Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer Name : T.K. Holdings, Inc. Address : 888 16th Street NW Suite 800 Washington DISTRICT OF COLUMBIA 20006 Country : United States

Chronology :

October 12, 2015 Takata notified NHTSA and Honda Motor Co., Ltd. (HMC) that one driver frontal airbag module (PSDI-X) failed Lot Acceptance Testing (LAT) cold test (-35 degrees C) at the Monclova factory.

October 12-16, 2015 Honda and Takata identified and traced modules from the same inflator lot as the failed module to potentially impacted manufacturing plants and vehicles.

October 16, 2015 Lab analysis of the failed module showed a centerline crack in the airbag inflator, potentially caused by a material or stamping issue, but no root cause identified.

October 26, 2015 HMC made the determination that a defect related to motor vehicle safety exists and decided to conduct a safety recall.

As of October 26, 2015 Honda has not received any warranty claims, field reports, crash or injury allegations related to this issue.

Description of Remedy :

Description of Remedy Program : The owners of all affected vehicles will be contacted by mail and asked to take their vehicle to a Honda automobile dealer. The dealer will replace the driver frontal airbag module free of charge. Because the new vehicle warranty on all affected vehicles would have provided a free repair for the problem addressed by this recall, without any payment by the owner, reimbursement for pre-notification repairs will not be offered.

How Remedy Component Differs from Recalled Component : NR Identify How/When Recall Condition was Corrected in Production : NR

Part 573 Safety Recall Report

15V-714

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : OCT 29, 2015 - OCT 29, 2015

Planned Owner Notification Date : DEC 04, 2015 - DEC 04, 2015

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR \$573