

Part 573 Safety Recall Report**15V-734****Manufacturer Name :** Dodgen Industries, Inc.**Submission Date :** NOV 04,2015**NHTSA Recall No. :** 15V-734**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Dodgen Industries, Inc.

Address : Highway 169 North

Humboldt IA 50548

Company phone : 515-332-3755

Population :

Number of potentially involved : 7

Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2006-2014 Dodgen Mobile Tech. Mobility RV's

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : ALL

Power Train : GAS

Descriptive Information : Under certain conditions present in some applications, the platforms included on the subject S-Series model wheelchair lifts can exhibit cracking of the platform pivot plate while in the stowed position which, if left unchecked, can propagate to the point where separation of the rear portion of the pivot plate occurs rendering the lift potentially inoperable and possibly unsafe for the operator. In the event the aforementioned crack occurs on both sides of the platform and is allowed to propagate to the point of material separation on both sides it is possible for the lift platform to lean against the vehicle lift door(s) and fall out of the vehicle when the door(s) is (are) opened putting the lift operator at risk.

Production Dates : JAN 01, 2006 -NOV 24, 2014

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

☐ Not sequential VINs**Description of Defect :**

Description of the Defect : Under certain conditions present in some applications, the platforms included on the subject S-Series model wheelchair lifts can exhibit cracking of the platform pivot plate while in the stowed position which, if left unchecked, can propagate to the point where separation of the rear portion of the pivot plate occurs rendering the lift potentially inoperable and possibly unsafe for the operator. In the event the aforementioned crack occurs on both sides of the platform and is allowed to propagate to the point of material separation on both sides it is possible for the lift platform to lean against the vehicle lift door(s) and fall out of the vehicle when the door(s) is (are) opened putting the lift operator at risk.

FMVSS 1 :NR

FMVSS 2 :NR

Description of the Safety Risk : Under certain conditions present in some applications, the platforms included on the subject S-Series model wheelchair lifts can exhibit cracking of the platform pivot plate while in the stowed position which, if left unchecked, can propagate to the point where separation of the rear portion of the pivot plate occurs rendering the lift potentially inoperable and possibly unsafe for the operator. In the event the aforementioned crack occurs on both sides of the platform and is allowed to propagate to the point of material separation on both sides it is possible for the lift platform to lean against the vehicle lift door (s) and fall out of the vehicle when the door(s) is (are) opened putting the lift operator at risk.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : Ricon, A Wabtec Subsidiary

Address : 1135 Aviation Place

San Fernando CALIFORNIA 91340

Country : United States

Chronology :

NR

Description of Remedy :

Description of Remedy Program : NR

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported