

Part 573 Safety Recall Report**15V-804****Manufacturer Name :** Mack Trucks, Inc.**Submission Date :** NOV 25,2015**NHTSA Recall No. :** 15V-804**Manufacturer Recall No. :** SC0398**Manufacturer Information :**

Manufacturer Name : Mack Trucks, Inc.

Address : 2100 Mack Boulevard

PO Box M Allentown PA 18105-5000

Company phone : 610-709-2131

Population :

Number of potentially involved : 679

Estimated percentage with defect : 0

Vehicle Information :

Vehicle : 2010-2016 Mack Granite

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : DIESEL

Descriptive Information : Certain Mack 2010 - 2016 Granite model trucks manufactured from September 17, 2009 through July 31, 2015

Production Dates : SEP 17, 2009 - JUL 31, 2015

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : On certain 4x2 configured trucks, there may be a brake imbalance between the steer axle and drive axle brakes.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : As a result, the rear brakes may overheat which increases the risk of a tire blowout or wheel-end fire on the drive axle.

Description of the Cause : Size of brake chambers used

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

Chronology :

10/9/2015 Potential Issue reported to Regulatory Affairs, Investigation opened

11/20/2015 Mack Trucks determines that a safety-related defect exists

11/25/2015 Mack Trucks notifies NHTSA that a voluntary safety recall will be released to address the potential issue

Description of Remedy :

Description of Remedy Program : The trucks will be repaired by replacing brake chambers on either the steer axle or drive axle. Pre notification repairs will be addressed according to the reimbursement plan on file with NHTSA.

How Remedy Component Differs from Recalled Component : Different size brake chambers to address the potential imbalance

Identify How/When Recall Condition was Corrected in Production : October 12, 2015

Recall Schedule :

Description of Recall Schedule : Dealers will be notified by December 2, 2015 and owner notification letters will be mailed by January 25, 2016

Planned Dealer Notification Date : DEC 02, 2015 - DEC 02, 2015

Planned Owner Notification Date : JAN 25, 2016 - JAN 25, 2016

* NR - Not Reported